
TRANSPORTATION TECHNICAL REPORT

APPENDIX C

Crash Data (1993-2003) and Crash Analysis Results

SUMMARY STATEWIDE AVERAGE CRASH RATES
1998-2002

SECTIONS	Rate (Crashes/MVM *)
<u>Functional Classification</u>	
<u>Rural:</u>	
1 Interstate	0.1395
2 Principal Arterial	0.3438
6 Minor Arterial	0.6072
7 Major Collector	0.5766
8 Minor Collector	0.6296
9 Local	0.6296
<u>Urban:</u>	
11 Interstate	0.1071
12 Other Freeways and Expressways	0.3453
14 Principal Arterial	1.7787
16 Minor Arterial	1.4338
17 Urban Collector	1.4265
19 Local	0.3817

INTERSECTIONS

	Rate (Crashes/MV **)
Principal Arterial (r) / Minor Arterial (r)	0.181
Principal Arterial (r)/Major Collector (r)	0.143
Freeway/Expressway (u)/Principal Arterial (u)	0.205
Principal Arterial (u)/Urban Collector (u)	0.232
Freeway/Expressway (u)/Minor Arterial (u)	0.285
Principal Arterial (u)/Minor Arterial (u)	0.418
Principal Arterial (u)/ Principal Arterial (u)	0.258
Major Collector (r)/Major Collector (r)	0.144
Minor Arterial (u)/Minor Arterial (u)	0.310
Minor Arterial (u)/Urban Collector (u)	0.240
Minor Arterial (r)/Major Collector (r)	0.314
Principal Arterial (r)/Principal Arterial (r)	0.115
Urban Collector (u)/Urban Collector (u)	0.266
Minor Arterial (r) / Minor Arterial (r)	0.193
Interstate, Rural (r)/Principal Arterial (r)	0.115
Major Collector (r)/Non-Federal Aid Collectors (r)	0.144
Interstate, Urban (u)/Principal Arterial (u)	0.205
Minor Arterial (r)/Non-Federal Aid Collectors (r)	0.314
Freeway/Expressway (u)/ Urban Collector (u)	0.285
Non-Federal Aid Collectors (r)	0.144

* Crashes per Million Vehicle Miles.
 ** Crashes per Million Vehicles.

NOTES:

(r) = Rural
 (u) = Urban

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-2A											
0417/12412-03	Williston	0.36	10/18/2003	22:55	Fog, Smog, Smoke	Failure to keep in proper lane or running off road, No improper driving	Same Direction Sideswipe	0	0	N	SH
0417/02WT0241	Williston	0.82	8/1/2002	21:30	Clear	No improper driving	Opp Direction Sideswipe	0	0		SH
0417/9026-03	Williston	0.92	7/25/2003	22:13	Cloudy	No improper driving	Head On	1	0	S	SH
0417/9172-03	Williston	0.92	7/25/2003	22:13	Cloudy	No improper driving	Single Vehicle Crash	0	0	N	SH
0417/4807	Williston	1.05	4/7/1999	14:16	Clear	Fatigued, asleep		0	1	S	SH
0417/13213-03	Williston	1.31	10/29/2003	9:48	Rain	Unknown	Single Vehicle Crash	0	0	S	SH
0417/10275	Williston	1.68	5/10/2000	16:10	Rain	Other improper action		1	0	N	SH
0417/141-02	Williston	1.87	2/17/2002	10:40	Snow	Other improper action		1	0	S	SH
0417/11392-01	Williston	1.92	11/27/2001	21:41	Unknown	No improper driving	Single Vehicle Crash	1	0	S	SH
0417/6609-02	Williston	2.14	6/28/2002	12:01	Clear	Unknown	Opp Direction Sideswipe	1	0	N	SH
0417/10380	Williston	2.32	10/21/2000	10:43	Clear	Failed to yield right of way		0	0	S	SH
0417/13930	Williston	2.32	12/14/2001	14:50	Clear	Failure to keep in proper lane or running off road	Head On	1	0	S	SH
0417/6707-03	Williston	2.32	5/30/2003	6:56	Cloudy	Failed to yield right of way, No improper driving	Right Turn and Thru, Same Direction Sideswipe/Angle	0	0		SH
0417/12673-2	Williston	2.47	11/4/2002	13:30	Cloudy	Inattention, No improper driving	Rear End	0	0	S	SH
0417/14358	Williston	2.53	5/26/2001	2:53	Clear	Other improper action		1	0	S	SH
0417/5154-03	Williston	2.55	4/1/2003	15:46	Snow	Driving too fast for conditions, No improper driving	Rear End	0	0	N	SH
0417/714-03	Williston	2.65	1/21/2003	13:47	Clear	Followed too closely, No improper driving	Rear End	0	0	N	SH
0417/5964	Williston	2.71	3/22/1999	8:00	Cloudy	Followed too closely	Rear End	1	0	N	SH
0417/18363-03	Williston	2.84	6/29/2003	17:16	Clear	Unknown	Rear End	0	0	N	SH
0417/12408	Williston	2.89	4/3/2001	7:45	Cloudy	Other improper action	Rear End	1	0	N	SH
0417/14733	Williston	2.93	1/7/2002	17:05	Cloudy	Driving too fast for conditions		0	0	N	SH
0417/13558-02	Williston	2.93	11/15/2002	16:40	Rain	Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner, Under the influence of medication/drugs/alcohol. No improper driving	Left Turn and Thru, Angle Broadside -->v--	1	0		SH
0417/4283-03	Williston	2.93	2/26/2003	13:08	Clear	Unknown	Left Turn and Thru, Head On ^v--	0	0	N	SH
0417/4994-03	Williston	2.93	4/10/2003	9:30	Clear	No improper driving, Distracted	Rear End	0	0		SH
0417/7076-03	Williston	2.93	6/5/2003	16:26	Rain	Swerving or avoiding due to wind, slippery surface, vehicle, object, non-motorist in roadway etc. No improper driving	Left Turn and Thru, Head On ^v--	0	0	N	SH
0417/9106-03	Williston	2.93	7/26/2003	19:15	Clear	Inattention, No improper driving	Rear End	0	0	S	SH
0417/13205-03	Williston	2.93	10/19/2003	15:01	Clear	Under the influence of medication/drugs/alcohol, Fatigued, asleep. No improper driving	Right Turn and Thru, Same Direction Sideswipe/Angle	0	0	S	SH
0417/8856-02	Williston	2.98	8/30/2002	15:42	Clear	Unknown	Same Direction Sideswipe	0	0	N	SH
0417/10047	Williston	3.01	9/23/2000	16:21	Clear	Failed to yield right of way		2	0	W	SH
0417/3804-03	Williston	3.03	2/12/2003	16:55	Clear	Failed to yield right of way, Inattention, No improper driving	Left Turn and Thru, Angle Broadside -->v--	0	0	N	SH
0417/14089-02	Williston	3.06	12/6/2002	12:22	Clear	Technology Related Distraction, No improper driving	Rear End	0	0	S	SH
0417/17852-03	Williston	3.06	2/20/2003	20:59	Unknown	Unknown, No improper driving	Same Direction Sideswipe	0	0		SH
0417/6424-03	Williston	3.06	5/21/2003	19:48	Cloudy	No improper driving, Operating vehicle in erratic, reckless, careless, negligent or aggressive manner. Inattention	Rear End	0	0	N	SH
0417/14533-03	Williston	3.06	11/18/2003	18:06	Cloudy	Failed to yield right of way, Inattention, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	E	SH
0417/5111-03	Williston	3.07	4/11/2003	17:01	Cloudy	No improper driving, Failed to yield right of way	No Turns, Thru moves only, Broadside ^<	0	0	N	SH
0417/7174	Williston	3.12	11/11/1999	12:42	Clear	Followed too closely	Rear End	0	0	N	SH
0417/16657-03	Williston	3.15	12/13/2003	17:28	Clear	No improper driving, Inattention, Driving too fast for conditions	Rear End	1	0	N	SH
0417/8704	Williston	3.16	4/9/2000	7:10	Snow	Wrong side or wrong way	Head On	1	0	S	SH
0417/12960	Williston	3.16	7/11/2001	16:28	Clear	Inattention	Rear End	1	0		SH
0417/13933	Williston	3.16	12/22/2001	13:15	Clear	Inattention	Rear End	1	0	N	SH
0417/3221-02	Williston	3.16	3/20/2002	21:11	Snow	Made an improper turn, No improper driving	Rear End	1	0	N	SH
0417/6785-03	Williston	3.18	5/29/2003	16:07	Rain	Made an improper turn, No improper driving	Left Turn and Thru, Angle Broadside -->v--	2	0	E	SH
0417/5641	Williston	3.19	7/1/1999	17:00	Clear	Other improper action		0	0	E	SH

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Road Direction	Road Group
Route: VT-2A											
0417/6566-03	Williston	3.19	4/11/2003	16:08	Cloudy	Failed to yield right of way, No improper driving	Left Turn and Thru, Broadside v<--	0	0	E	SH
0417/9466-03	Williston	3.19	8/6/2003	17:27	Cloudy	Unknown, Failed to yield right of way	Left Turn and Thru, Angle Broadside -->v--	0	0	N	SH
0417/6880	Williston	3.2	10/19/1999	20:00	Clear	Followed too closely	Rear End	4	0	S	SH
0417/10789-02	Williston	3.2	10/5/2002	16:00	Cloudy	Inattention, Followed too closely, No improper driving	Rear End	1	0	N	SH
0417/02WT0329	Williston	3.2	10/11/2002	18:38	Cloudy	Failed to yield right of way, No improper driving	Right Turn and Thru, Angle Broadside -->^--	0	0	N	SH
0417/7653-03	Williston	3.2	6/22/2003	14:28	Clear	Made an improper turn, No improper driving	Opp Direction Sideswipe	1	0	E	SH
0417/13857-02	Williston	3.28	11/29/2002	13:50	Snow	Unknown	No Turns, Thru moves only, Broadside ^<	0	0	N	SH
0417/11284-02	Williston	3.29	11/26/2002	19:50	Clear	Inattention, No improper driving	Rear End	1	0	S	SH
0417/10792-03	Williston	3.3	9/11/2003	7:23	Clear	Fatigued, asleep, No improper driving	Rear End	0	0	N	SH
0417/7069	Williston	3.33	11/8/1999	13:40	Cloudy	Operating defective equipment	Rear End	0	0	S	SH
0417/6642-02	Williston	3.33	7/2/2002	15:40	Clear	No improper driving		1	0	E	SH
0417/02WT0274	Williston	3.33	8/25/2002	17:06	Clear	Inattention, Unknown	Left and Right Turns, Simultaneous Turn Crash --vv--	0	0	N	SH
0417/10215-02	Williston	3.33	9/26/2002	10:46	Clear	No improper driving, Inattention	Rear End	1	0	N	SH
0417/02WT0333	Williston	3.33	10/15/2002	14:41	Cloudy	Inattention, No improper driving	Same Direction Sideswipe	0	0	E	SH
0417/9946-02	Williston	3.33	10/25/2002	18:32	Clear	Unknown	Head On	0	0	N	SH
0417/11524-02	Williston	3.33	11/21/2002	7:30	Cloudy	Inattention, Followed too closely, No improper driving	Rear End	0	0	E	SH
0417/11286-02	Williston	3.33	11/25/2002	17:20	Clear	No improper driving, Failed to yield right of way	Opp Direction Sideswipe	0	0	N	SH
0417/14008-02	Williston	3.33	12/3/2002	11:50	Clear	Inattention, Followed too closely, No improper driving	Rear End	0	0	N	SH
0417/04016	Williston	3.33	12/8/2002	11:35	Snow		Rear End	0	0	N	SH
0417/3410-03	Williston	3.33	2/5/2003	19:30	Clear	Followed too closely, Inattention, No improper driving	Rear End	0	0	S	SH
0417/3604-03	Williston	3.33	2/8/2003	18:29	Cloudy	Failed to yield right of way, No improper driving	Left and Right Turns, Simultaneous Turn Crash --vv--	0	0	S	SH
0417/4237-03	Williston	3.33	2/23/2003	16:32	Sleet, Hail (Freezing Rain or	No improper driving	Rear End	0	0	N	SH
0417/4836-03	Williston	3.33	4/6/2003	14:24	Clear	Inattention, Distracted, No improper driving	Rear End	0	0	S	SH
0417/5166-03	Williston	3.33	4/10/2003	7:58	Clear	No improper driving, Distracted	Rear End	0	0	W	SH
0417/7071-03	Williston	3.33	5/7/2003	22:07	Not Reported	Inattention, No improper driving	Rear End	0	0	S	SH
0417/7343-03	Williston	3.33	6/14/2003	12:42	Clear	No improper driving, Failed to yield right of way, Disregarded traffic signs, signals, road markings	Left Turn and Thru, Angle Broadside -->v--	0	0	N	SH
0417/07669-03	Williston	3.33	6/24/2003	15:15	Clear	No improper driving, Failed to yield right of way	Left Turn and Thru, Angle Broadside -->v--	0	0	N	SH
0417/18451-03	Williston	3.33	7/3/2003	12:11	Clear	No improper driving	Rear End	0	0	W	SH
0417/8532-03	Williston	3.33	7/9/2003	15:36	Clear	Inattention, Unknown	Rear End	1	0	S	SH
0417/8324-03	Williston	3.33	7/9/2003	19:40	Clear	Inattention, No improper driving	Left Turn and Thru, Angle Broadside -->v--	2	0	E	SH
0417/9819-03	Williston	3.33	8/6/2003	17:27	Cloudy	No improper driving, Other improper action	Rear End	0	0	S	SH
0417/11698-03	Williston	3.33	10/3/2003	12:56	Clear	Made an improper turn, No improper driving		1	0	N	SH
0417/12037-03	Williston	3.33	10/4/2003	10:45	Rain	Unknown	Rear End	0	0	N	SH
0417/12355-03	Williston	3.33	10/15/2003	15:40	Cloudy	Inattention	Left Turn and Thru, Angle Broadside -->v--	0	0	E	SH
0417/13107-03	Williston	3.33	11/1/2003	19:23	Cloudy	Failure to keep in proper lane or running off road, No improper driving	Same Direction Sideswipe	0	0	S	SH
0417/15340-03	Williston	3.33	11/11/2003	9:47	Cloudy	Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner. No improper driving	Same Direction Sideswipe	0	0	S	SH
0417/14569-03	Williston	3.33	12/1/2003	11:55	Cloudy	No improper driving, Failed to yield right of way	Head On	0	0	N	SH
0417/15472-03	Williston	3.33	12/5/2003	14:02	Clear	Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner	Rear End	0	0	S	SH
0417/15411-03	Williston	3.33	12/11/2003	14:44	Rain	Unknown	Opp Direction Sideswipe	0	0	N	SH
0417/16697-03	Williston	3.33	12/28/2003	11:07	Clear	Unknown	Head On	0	0	N	SH
0417/02648-02	Williston	3.35	7/2/2002	7:25	Cloudy	Failure to keep in proper lane or running off road, No improper driving	Same Direction Sideswipe	0	0	S	SH
0417/03838	Williston	3.37	11/25/2002	19:45	Clear	Inattention, Distracted	Single Vehicle Crash	0	0	S	SH
0417/5824-03	Williston	3.39	5/2/2003	20:45	Clear	Inattention, No improper driving	Rear End	1	0		SH
0417/5109-03	Williston	3.42	4/10/2003	17:32	Clear	Unknown	Same Direction Sideswipe	0	0	S	SH

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Road Direction	Road Group
0417/7085-03	Williston	3.43	6/6/2003	16:35	Clear	Inattention, No improper driving	Rear End	0	0	S	SH
0417/12341-03	Williston	3.52	10/9/2003	17:38	Clear	Inattention, No improper driving	Rear End	0	0	N	SH
0417/14806-03	Williston	3.52	12/2/2003	12:08	Cloudy	Failed to yield right of way, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	E	SH
0417/4471-03	Williston	3.53	3/22/2003	14:10	Cloudy	Failed to yield right of way, No improper driving	Left Turn and Thru, Angle Broadside -->v--	0	0	N	SH
0417/14497	Williston	3.65	12/21/2001	11:40	Clear	Wrong side or wrong way		0	0	N	SH
0417/4694	Williston	3.72	3/20/1999	23:38	Clear	Failed to yield right of way		0	0	N	SH
0417/10048	Williston	3.72	9/11/2000	13:47	Cloudy	Inattention	Rear End	1	0	N	SH
0417/10379	Williston	3.72	10/8/2000	18:00	Cloudy	Made an improper turn		0	0	S	SH
0417/11017	Williston	3.72	12/21/2000	14:00	Clear	Followed too closely	Rear End	0	0	N	SH
0417/02363-02	Williston	3.72	7/29/2002	12:09	Not Reported	Inattention, No improper driving	Rear End	0	0	N	SH
0417/8506-02	Williston	3.72	8/21/2002	12:16	Clear	Visibility obstructed, No improper driving	Same Direction Sideswipe	0	0	S	SH
0417/9002-02	Williston	3.72	8/29/2002	12:00	Clear	Distracted, No improper driving	Rear End	0	0	N	SH
0417/03355-02	Williston	3.72	10/16/2002	14:30	Rain	Inattention, No improper driving	Rear End	0	0	N	SH
0417/11623-02	Williston	3.72	12/4/2002	8:16	Clear	No improper driving, Failed to yield right of way, Made an improper turn	Opp Direction Sideswipe	0	0	S	SH
0417/03WT0033	Williston	3.72	1/24/2003	14:25	Clear	Inattention, Followed too closely, No improper driving	Rear End	0	0	S	SH
0417/12627-03	Williston	3.72	10/17/2003	7:46	Clear	Inattention, No improper driving	Same Direction Sideswipe	0	0	S	SH
0417/15377-03	Williston	3.72	12/4/2003	8:40	Snow	No improper driving	Rear End	0	0	N	SH
0417/14955-03	Williston	3.72	12/4/2003	13:07	Clear	Inattention, No improper driving	Rear End	0	0	N	SH
0417/16678-03	Williston	3.72	12/22/2003	6:05	Cloudy	Unknown	Right Turn and Thru, Angle Broadside -->^--	0	0	E	SH
0417/14564-03	Williston	3.73	11/24/2003	16:04	Cloudy	Disregarded traffic signs, signals, road markings	Single Vehicle Crash	0	0	N	SH
0417/14261-03	Williston	3.73	11/26/2003	15:35	Clear	Failed to yield right of way, Visibility obstructed, No improper driving	Opp Direction Sideswipe	0	0	E	SH
0417/7621	Williston	3.74	12/17/1999	15:45	Clear	Failed to yield right of way		0	0	S	SH
0417/10685-02	Williston	3.74	10/25/2002	12:34	Cloudy	Inattention, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	E	SH
0417/18123-03	Williston	3.74	5/24/2003	16:34	Clear	Failed to yield right of way, No improper driving	Left Turns, Opposite Directions, Head On/Angle Crash --^v--	0	0	E	SH
0417/7251-03	Williston	3.75	6/10/2003	9:57	Clear	Inattention, No improper driving	Rear End	0	0	N	SH
0417/9590-03	Williston	3.76	8/11/2003	14:37	Cloudy	No improper driving	Same Direction Sideswipe	0	0	S	SH
0417/9168-03	Williston	3.78	7/18/2003	15:45	Cloudy	Failure to keep in proper lane or running off road, Under the influence of medication/drugs/alcohol	Single Vehicle Crash	1	0	S	SH
0417/13274	Williston	3.8	7/20/2001	14:56	Clear	Technology Related Distraction		1	0	S	SH
0417/8658-02	Williston	3.8	9/30/2002	13:45	Cloudy	Other improper action, Visibility obstructed		0	0	N	SH
0417/14127-02	Williston	3.8	12/27/2002	15:03	Cloudy	No improper driving, Failed to yield right of way	Left Turn and Thru, Broadside v<--	1	0	N	SH
0417/14280-03	Williston	3.8	11/21/2003	12:26	Clear	Followed too closely, No improper driving	Rear End	0	0	N	SH
0417/4773-03	Williston	3.83	4/3/2003	14:40	Snow	Unknown	Single Vehicle Crash	0	0	S	SH
0417/14822-03	Williston	3.83	12/3/2003	11:50	Clear	No improper driving, Failed to yield right of way	No Turns, Thru moves only, Broadside ^<	0	0	N	SH
0417/8701	Williston	3.85	4/12/2000	17:29	Cloudy	Followed too closely	Rear End	0	0	S	SH
0417/9734	Williston	3.85	7/18/2000	13:10	Clear	Failed to yield right of way		1	0	E	SH
0417/9980-02	Williston	3.86	9/27/2002	16:10	Unknown	No improper driving, Failed to yield right of way		0	0		SH
0417/11604-02	Williston	3.99	12/4/2002	14:26	Clear	Unknown	No Turns, Thru moves only, Broadside ^<	0	0	W	SH
0417/4293-03	Williston	4.07	2/27/2003	10:20	Clear	Unknown	Same Direction Sideswipe	0	0	E	SH
0417/13536-03	Williston	4.13	11/10/2003	16:57	Clear	Inattention, No improper driving	Rear End	0	0	N	SH
0417/7071	Williston	4.22	11/14/1999	14:05	Cloudy	Inattention	Rear End	0	0	N	SH
0417/13865	Williston	4.22	10/23/2001	21:05	Clear	Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner		2	0	N	SH
0417/17635-03	Williston	4.37	1/20/2003	10:05	Clear	Inattention	Single Vehicle Crash	0	0	S	SH
0417/02215-02	Williston	4.39	7/14/2002	17:49	Clear	Distracted, No improper driving	Rear End	0	0	N	SH
0417/14357	Williston	4.4	10/26/2001	17:00	Clear	Inattention, Followed too closely	Rear End	1	0	N	SH
0417/7452-03	Williston	4.4	6/13/2003	17:37	Rain	Followed too closely, No improper driving	Rear End	0	0	N	SH

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-2A											
0417/7627-02	Williston	4.48	8/13/2002	18:01	Clear	Unknown	Rear End	0	0	N	SH
0417/8402	Williston	4.5	3/1/2000	14:19	Cloudy	Inattention	Rear End	1	0	N	SH
0417/10218-02	Williston	4.5	9/27/2002	12:20	Rain	Driving too fast for conditions, Swerving or avoiding due to wind, slippery surface, vehicle, object, non-motorist in roadway etc.	Right Turn, Same Direction, Rear End ^-^--	1	0	N	SH
0417/02WT0341	Williston	4.5	10/20/2002	19:00	Clear	No improper driving	Single Vehicle Crash	0	0		SH
0417/4855-03	Williston	4.5	1/23/2003	13:01	Clear	Unknown, No improper driving	Rear End	0	0	N	SH
0417/13743-03	Williston	4.5	11/13/2003	16:08	Rain	Inattention, Distracted, No improper driving	Rear End	1	0	N	SH
0417/14572-03	Williston	4.5	11/25/2003	16:20	Clear	Under the influence of medication/drugs/alcohol, Inattention, No improper driving	Rear End	1	0	N	SH
0417/7521-02	Williston	4.67	7/26/2002	17:32	Cloudy	Unknown, No improper driving	Rear End	0	0	N	SH
0417/9538-02	Williston	4.67	10/9/2002	21:39	Cloudy	Inattention, No improper driving	Rear End	0	0	S	SH
0417/13748-03	Williston	4.67	10/30/2003	17:24	Clear	Distracted, No improper driving	Rear End	0	0	N	SH
0417/12369-02	Williston	4.73	12/11/2002	8:05	Clear	Inattention, No improper driving	Rear End	0	0	S	SH
0417/14992-03	Williston	4.73	12/3/2003	15:45	Fog, Smog, Smoke	Inattention, Distracted, No improper driving	Rear End	0	0	N	SH
0417/13744-03	Williston	4.78	11/4/2003	17:42	Cloudy	Inattention, No improper driving	Rear End	0	0	N	SH
0417/12693	Williston	4.79	6/1/2001	8:11	Cloudy	Failed to yield right of way		1	0	E	SH
0417/12692	Williston	4.79	6/5/2001		Snow	Fatigued, asleep	Rear End	2	0	N	SH
0417/13331	Williston	4.79	8/30/2001	17:40	Unknown	Other improper action	Rear End	1	0	S	SH
0417/161-02	Williston	4.79	2/20/2002	20:56	Cloudy	Failed to yield right of way		0	0	E	SH
0417/977-02	Williston	4.79	9/28/2002	14:20	Clear	Inattention, No improper driving	Rear End	0	0	S	SH
0417/03WT00349	Williston	4.79	1/25/2003	12:21	Clear	Under the influence of medication/drugs/alcohol, No improper driving	Rear End	0	0	S	SH
0417/11068-03	Williston	4.79	9/11/2003	21:43	Clear	Failed to yield right of way, No improper driving	Left Turn and Thru, Angle Broadside -->v--	0	0	N	SH
0417/11427-03	Williston	4.79	9/28/2003	12:55	Rain	Driving too fast for conditions, No improper driving	Rear End	0	0	S	SH
0417/13303-03	Williston	4.79	11/5/2003	18:40	Cloudy	Failed to yield right of way, No improper driving	Left Turn and Thru, Angle Broadside -->v--	0	0	S	SH
0417/16180-03	Williston	4.82	12/24/2003	11:28	Rain	Swerving or avoiding due to wind, slippery surface, vehicle, object, non-motorist in roadway etc, Inattention, No improper driving	Same Direction Sideswipe	0	0	N	SH
0417/8516-02	Williston	4.93	8/23/2002	17:19	Clear	Swerving or avoiding due to wind, slippery surface, vehicle, object, non-motorist in roadway etc	Rear End	1	0	S	SH
0417/18271-03	Williston	4.94	4/26/2003	12:13	Rain	Inattention, No improper driving	Rear End	0	0	S	SH
0417/8059-03	Williston	4.94	6/16/2003	10:32	Clear	Driving too fast for conditions, Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner	Single Vehicle Crash	1	0	N	SH
0417/8451-03	Williston	4.94	7/11/2003	16:08	Cloudy	No improper driving, Inattention	Rear End	0	0	S	SH
0417/1092-03	Williston	4.95	1/5/2003	11:29	Cloudy	Followed too closely, No improper driving	Rear End	0	0	N	SH
0417/10558-03	Williston	4.99	9/3/2003	12:44	Cloudy	Followed too closely, No improper driving	Rear End	0	0	S	SH
0417/13871	Williston	5.02	11/9/2001	19:48	Clear	Inattention	Rear End	1	0	N	SH
0417/8533-03	Williston	5.02	7/9/2003	10:55	Clear	Inattention, Followed too closely, No improper driving	Rear End	0	0	S	SH
0417/9105-03	Williston	5.02	7/26/2003	14:27	Cloudy	Inattention, No improper driving	Rear End	0	0	N	SH
0417/11304-02	Williston	5.15	11/25/2002	13:55	Cloudy	No improper driving, Failed to yield right of way, Inattention	Opp Direction Sideswipe	1	0	N	SH
0417/13216-03	Williston	5.17	10/31/2003	18:46	Cloudy	Inattention, No improper driving	Rear End	0	0	S	SH
0417/6289-02	Williston	5.28	7/10/2002	8:23	Clear	No improper driving		1	0	N	SH
0417/8845-03	Williston	5.3	7/22/2003	12:25	Cloudy	Inattention, No improper driving	Rear End	0	0	N	SH
0417/12638-02	Williston	5.32	10/31/2002	14:08	Clear	Followed too closely	Rear End	0	0	N	SH
0417/10160-03	Williston	5.32	8/14/2003	18:43	Clear	Inattention, No improper driving	Rear End	0	0	N	SH
0417/18538-03	Williston	5.42	7/21/2003	15:51	Rain	Failed to yield right of way, No improper driving	Other	0	0	N	SH
0417/5937	Williston	5.46	7/30/1999	21:20	Cloudy	Inattention	Rear End	1	0	N	SH
0417/10565-03	Williston	5.46	9/4/2003	15:00	Clear	Followed too closely, Distracted, No improper driving	Rear End	0	0	N	SH
0417/14993-03	Williston	5.46	12/3/2003	19:18	Clear	Driving too fast for conditions, Inattention, No improper driving	Rear End	6	0	S	SH

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-2A											
0417/13212-03	Williston	5.5	10/27/2003	22:42	Rain	Driving too fast for conditions, Inattention	Single Vehicle Crash	0	0	N	SH
0417/8841	Williston	5.52	4/28/2000	16:24	Clear	Inattention		1	0	S	SH
0417/8401	Williston	5.53	3/20/2000	21:15	Clear	Followed too closely	Rear End	1	0	N	SH
0417/15046	Williston	5.53	1/22/2002	7:13	Cloudy	Inattention	Rear End	1	0	E	SH
0417/8050-02	Williston	5.53	8/28/2002	15:53	Clear	Failed to yield right of way		0	0	N	SH
0417/12333-02	Williston	5.53	12/17/2002	20:15	Cloudy	No improper driving	Single Vehicle Crash	0	0		SH
0417/630-03	Williston	5.53	1/17/2003	12:27	Clear	Inattention, Followed too closely, No improper driving	Rear End	1	0	N	SH
0417/722-03	Williston	5.53	1/22/2003	8:00	Clear	Distracted, Followed too closely, No improper driving	Rear End	1	0	S	SH
0417/8531-03	Williston	5.53	7/9/2003	15:09	Clear	Inattention, Driving too fast for conditions, No improper driving	Rear End	0	0		SH
0417/9303-03	Williston	5.53	7/28/2003	11:11	Cloudy	No improper driving	Left Turn and Thru, Angle Broadside -->v--	2	0	N	SH
0417/13393-03	Williston	5.53	11/7/2003	6:50	Cloudy	Followed too closely, Inattention, Unknown	Rear End	0	0	N	SH
0417/5900-02	Williston	5.56	6/28/2002	22:06	Cloudy	Followed too closely	Rear End	0	0	S	SH
0417/11016	Williston	5.6	12/19/2000	16:35	Snow	Made an improper turn		0	0	S	SH
0417/7492-02	Williston	5.6	8/21/2002	11:03	Clear	Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner. Inattention. No improper driving	Rear End	1	0	N	SH
0417/509-03	Williston	5.6	1/11/2003	13:00	Cloudy	Driving too fast for conditions, Followed too closely	Single Vehicle Crash	2	0	N	SH
0417/11463-02	Williston	5.64	11/30/2002	13:32	Cloudy	Inattention, No improper driving	Rear End	0	0	S	SH
0417/14562-03	Williston	5.93	11/23/2003	0:39	Clear	Driving too fast for conditions, Swerving or avoiding due to wind, slippery surface, vehicle, object, non-motorist in roadway etc	Single Vehicle Crash	2	0	S	SH
0417/7428	Williston	5.94	12/3/1999	14:31	Clear	Followed too closely	Rear End	1	0	N	SH
0417/6131	Williston	UNK	8/6/1999	12:08	Cloudy	Failed to yield right of way		1	0	E	SH
0417/11774	Williston	UNK	2/5/2001	15:17	Snow	Other improper action	Head On	2	0	S	SH
0417/10833-01	Williston	UNK	12/11/2001	17:10	Cloudy	No improper driving	Rear End	0	0	S	SH
0417/02WT0360	Williston	UNK	11/5/2002	12:31	Clear	Inattention, No improper driving	Rear End	0	0	N	SH
0417/2269-03	Williston	UNK	1/9/2003	13:56	Clear	Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner. Inattention. No improper driving	Rear End	0	0	N	SH
0417/13745-03	Williston	UNK	10/24/2003	14:43	Clear	No improper driving, Followed too closely	Right Turn and Thru, Same Direction Sideswipe/Angle Crash ^^--	4	0	S	SH
0417/14561-03	Williston	UNK	11/22/2003	14:29	Clear	Inattention, No improper driving	Rear End	0	0	S	SH
0417/14765-03	Williston	UNK	12/4/2003	7:44	Snow	No improper driving	Opp Direction Sideswipe	0	0	N	SH

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
<u>Route: VT-2A</u>											
0406/13927-	Essex	0.12	11/15/2003	11:01	Clear	Failed to yield right of way, No improper driving	Left Turn and Thru, Angle Broadside -->v--	1	0	N	SH
0406/12213-	Essex	0.14	9/12/2003	18:22	Clear	Failed to yield right of way	Single Vehicle Crash	1	0		SH
0406/10302-	Essex	0.21	8/27/2003	7:35	Clear	Followed too closely, No improper driving	Rear End	0	0		SH
0406/8404	Essex	0.31	2/23/2000	19:34	Cloudy	Other improper action	Rear End	0	0	N	SH
0406/9255	Essex	0.31	6/26/2000	14:00	Clear	Followed too closely	Rear End	0	0	S	SH
0406/12252	Essex	0.31	4/21/2001	9:15	Clear	Other improper action		0	0	N	SH
0406/388-03	Essex	0.36	1/6/2003	18:46	Cloudy	No improper driving, Failed to yield right of way, Made an improper turn	Left Turn and Thru, Angle Broadside -->v--	0	0	S	SH
0406/10616	Essex	0.42	2/18/2000	7:57	Clear	Inattention	Rear End	0	0	S	SH
0406/9112-03	Essex	0.43	7/27/2003	13:23	Cloudy	Followed too closely, No improper driving	Rear End	0	0		SH
0406/4139	Essex	0.44	1/18/1999	16:30	Rain	Followed too closely	Rear End	0	0	S	SH
0406/9131	Essex	0.44	5/30/2000	16:02	Unknown	Technology Related Distraction	Rear End	0	0	S	SH
0406/11776	Essex	0.49	2/26/2001	18:42	Clear	Other improper action, Exceeded authorized speed limit		1	0	N	SH
0406/10217-	Essex	0.5	9/27/2002	17:03	Rain	Followed too closely, No improper driving	Rear End	1	0	S	SH
0406/6767	Essex	0.56	9/30/1999	7:35	Rain	Followed too closely	Rear End	0	0	N	SH
0406/4422	Essex	0.57	2/16/1999	18:50	Clear	Other improper action		0	0	S	SH
0406/10637-	Essex	0.58	8/19/2003	10:50	Clear	Other improper action, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	E	SH
0406/3669-02	Essex	0.59	4/1/2002	7:35	Cloudy	Unknown	Rear End	0	0	N	SH
0406/5935-02	Essex	0.62	7/1/2002	16:08	Clear	Unknown, Failed to yield right of way		2	0	N	SH
0406/12576-	Essex	0.62	10/22/2003	15:41	Cloudy	No improper driving, Failed to yield right of way	No Turns, Thru moves only, Broadside ^<	0	0	N	SH
0406/6766	Essex	0.63	10/4/1999	19:15	Cloudy	Failed to yield right of way		0	0	E	SH
0406/12965	Essex	0.64	8/2/2001	16:41	Clear	Failed to yield right of way		2	0	S	SH
0406/6445	Essex	0.65	9/1/1999	16:00	Unknown	Made an improper turn		0	0	S	SH
0406/12015-	Essex	0.65	12/6/2002	18:06	Clear	No improper driving, Made an improper turn	No Turns, Thru moves only, Broadside ^<	0	0	N	SH
0406/4138	Essex	0.66	1/24/1999	19:19	Clear	Failed to yield right of way		0	0	W	SH
0406/4511	Essex	0.67	2/20/1999	18:50	Snow	Other improper action		1	0	E	SH
0406/4856	Essex	0.67	4/10/1999	19:22	Unknown	Followed too closely	Rear End	0	0	N	SH
0406/9495	Essex	0.67	7/3/2000	15:53	Rain	Failed to yield right of way	Head On	0	0	E	SH
0406/14774	Essex	0.67	1/16/2002	11:15	Cloudy	Disregarded traffic signs, signals, road markings		1	0	E	SH
0406/7013-03	Essex	0.67	6/7/2003	14:50	Cloudy	Followed too closely, No improper driving	Rear End	0	0	S	SH
0406/1704-03	Essex	0.73	2/11/2003	8:00	Not Reported	Unknown	No Turns, Thru moves only, Broadside ^<	0	0	E	SH
0406/10773	Essex	0.82	11/17/2000	16:32	Snow	Failed to yield right of way		0	0	W	SH
0406/6969-03	Essex	0.82	6/6/2003	12:20	Clear	Followed too closely, No improper driving	Rear End	1	0	S	SH
0406/3586-02	Essex	0.92	4/12/2002	11:22	Unknown	No improper driving, Other improper action	Rear End	0	0	N	SH
0406/6709-02	Essex	1.04	6/24/2000	17:59	Clear	Failed to yield right of way, Made an improper turn		1	0	N	SH
0406/9000	Essex	1.19	5/27/2000	8:45	Clear	Inattention	Rear End	0	0	S	SH
0406/10987-	Essex	1.19	8/25/2003	17:43	Clear	No improper driving, Made an improper turn	Head On	0	0	N	SH
0406/4260	Essex	1.87	1/29/1999	13:38	Clear	Failed to yield right of way		1	0	S	SH
0406/11995	Essex	1.87	3/19/2001	15:07	Clear	Failed to yield right of way		2	0	E	SH

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
<u>Route: VT-2A</u>											
0406/12253	Essex	1.87	4/16/2001	19:50	Not Reported	Other improper action		3	0	S	SH
0406/14765	Essex	1.87	1/2/2002	9:28	Clear	Disregarded traffic signs, signals, road markings		2	0	W	SH
0406/24-02	Essex	1.87	2/8/2002	18:58	Cloudy	Failed to yield right of way		3	0	E	SH
0406/11679-	Essex	1.87	11/19/2002	17:15	Cloudy	No improper driving, Other improper action	Rear End	0	0	N	SH
0406/4315-03	Essex	1.87	3/28/2003	16:30	Clear	Unknown	Rear End	1	0	N	SH
0406/11775	Essex	1.89	1/11/2001	15:14	Clear	Failed to yield right of way		1	0	E	SH
0406/6133	Essex	2.47	8/21/1999	19:45	Cloudy	Failed to yield right of way		0	0	E	SH
0406/5642	Essex	2.49	5/4/1999	5:45	Clear	Disregarded traffic signs, signals, road markings		2	0	E	SH
0406/10382	Essex	2.49	10/13/2000	10:25	Clear	Disregarded traffic signs, signals, road markings		0	0	W	SH
0406/10381	Essex	2.49	10/21/2000	5:51	Cloudy	Failed to yield right of way		1	0	S	SH
0406/10903	Essex	2.49	11/30/2000	18:21	Snow	Disregarded traffic signs, signals, road markings		0	0	S	SH
0406/11554	Essex	2.49	1/22/2001	15:54	Clear	Inattention, Followed too closely	Rear End	0	0	S	SH
0406/12694	Essex	2.49	6/22/2001	17:21	Clear	Other improper action		0	0	E	SH
0406/14359	Essex	2.59	1/10/2001	5:20	Cloudy	Failed to yield right of way		0	0	E	SH
0406/14494	Essex	2.6	10/18/2001	0:00	Clear	Distracted		2	0	S	SH
0406/9478-03	Essex	2.6	7/29/2003	12:28	Clear	No improper driving, Followed too closely	Rear End	0	0	N	SH
0406/9455-03	Essex	2.6	8/4/2003	14:40	Cloudy	Disregarded traffic signs, signals, road markings, Other improper action	Right Turn and Thru, Broadside ^<--	0	0	S	SH
0406/9730-03	Essex	2.6	8/17/2003	3:18	Clear	Failed to yield right of way, No improper driving	No Turns, Thru moves only, Broadside ^<	3	0	E	SH
0406/8972	Essex	2.7	5/6/2000	10:00	Cloudy	Inattention	Rear End	0	0	S	SH
0406/3867-02	Essex	2.7	4/6/2002	12:00	Cloudy	Disregarded traffic signs, signals, road markings, No improper driving	No Turns, Thru moves only, Broadside ^<	1	0	S	SH
0406/13152	Essex	2.75	9/2/2001	16:33	Clear	Failed to yield right of way		0	0	N	SH
0406/3808-02	Essex	2.75	4/7/2002	18:15	Clear	Failed to yield right of way, No improper driving	Left Turn and Thru, Broadside v<--	0	0	W	SH
0406/5529-02	Essex	2.75	5/30/2002	19:12	Clear	Failed to yield right of way, Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner, Failure to keep in proper lane or running off road	Head On	2	0	N	SH
0406/6796-03	Essex	2.78	6/2/2003	7:55	Cloudy	No improper driving, Failed to yield right of way	Left Turn and Thru, Same Direction Sideswipe/Angle Crash v<--	0	0	S	SH
0406/10237	Essex	2.94	10/10/2000	17:05	Rain	Made an improper turn		2	0	N	SH
0406/8403	Essex	2.99	2/25/2000	8:29	Rain	Inattention		2	0	S	SH
0406/14255	Essex	3.02	10/7/2001	17:41	Clear	Made an improper turn	Head On	3	0	N	SH
0406/5967	Essex	3.03	6/28/1999	20:40	Clear	Other improper action		1	0	N	SH
0406/6659-02	Essex	3.45	7/3/2002	6:39	Clear	Fatigued, asleep, Failure to keep in proper lane or running off road	Opp Direction Sideswipe	0	0	N	SH
0406/3684-03	Essex	3.45	2/11/2003	13:58	Clear	Followed too closely, No improper driving	Rear End	3	0	N	SH
0406/14625	Essex	UNK	9/3/2001	17:18	Clear	Inattention	Rear End	0	0	S	SH
0406/16285-	Essex	UNK	12/23/2003	17:56	Clear	No improper driving, Visibility obstructed	No Turns, Thru moves only, Broadside ^<	0	0		SH

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
0417/02WT04017	Williston	0	12/8/2002	11:35	Snow	Swerving or avoiding due to wind, slippery surface, vehicle, object, non-motorist in roadway etc	Single Vehicle Crash	0	0	E	SH
0417/4598-02	Williston	0.09	5/21/2002	10:50	Clear	Followed too closely, No improper driving	Rear End	0	0	E	SH
0417/14558-03	Williston	0.09	12/2/2003	12:25	Cloudy	Inattention, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	W	SH
0417/16207-03	Williston	0.14	12/23/2003	14:17	Cloudy	Failed to yield right of way, Visibility obstructed, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0		SH
0417/4388-03	Williston	0.22	3/3/2003	14:15	Clear	Inattention, No improper driving	Rear End	0	0	E	SH
0417/11379-03	Williston	0.25	9/25/2003	9:35	Clear	Operating defective equipment, Inattention, No improper driving	Rear End	1	0	W	SH
0417/7329	Williston	0.26	12/9/1999	16:30	Clear	Other improper action	Rear End	1	0	E	SH
0417/2006-02	Williston	0.26	6/27/2002	17:15	Rain	No improper driving, Followed too closely	Rear End	0	0	W	SH
0417/7781-02	Williston	0.26	8/30/2002	17:50	Clear	Operating defective equipment, Unknown	Rear End	0	0	W	SH
0417/739-03	Williston	0.26	1/25/2003	13:27	Cloudy	No improper driving, Unknown	Opp Direction Sideswipe	0	0	E	SH
0417/2346-03	Williston	0.26	3/4/2003	17:16	Cloudy	Other improper action	Same Direction Sideswipe	0	0	E	SH
0417/4603-03	Williston	0.26	4/3/2003	14:11	Snow	Driving too fast for conditions, Followed too closely, No improper driving	Rear End	3	0	W	SH
0417/15383-03	Williston	0.26	12/9/2003	10:52	Clear	No improper driving, Unknown	Rear End	0	0	W	SH
0417/16702-03	Williston	0.27	12/31/2003	13:19	Cloudy	Other improper action, Distracted, No improper driving	Rear End	0	0	W	SH
0417/8514-03	Williston	0.31	7/14/2003	18:13	Clear	Inattention, Technology Related Distraction, No improper driving	Rear End	0	0	W	SH
0417/12339-03	Williston	0.5	10/10/2003	14:25	Clear	No improper driving, Inattention, Other improper action	Rear End	0	0	W	SH
0417/4451-03	Williston	0.64	3/29/2003	15:11	Rain	Unknown	Rear End	0	0	E	SH
0417/14849	Williston	0.7	1/18/2002	16:45	Cloudy	Failed to yield right of way	Head On	3	0	E	SH
0417/6035-02	Williston	0.7	6/14/2002	9:42	Cloudy	Disregarded traffic signs, signals, road markings, No improper driving		2	0	N	SH
0417/6590-02	Williston	0.7	6/30/2002	12:26	Clear	No improper driving, Disregarded traffic signs, signals, road markings. Driving too fast for conditions		2	0	N	SH
0417/3756-03	Williston	0.7	2/14/2003	13:27	Clear	Inattention, No improper driving	Rear End	0	0	E	SH
0417/9971-03	Williston	0.7	8/5/2003	7:45	Cloudy	No improper driving, Inattention	Rear End	0	0	E	SH
0417/13207-03	Williston	0.7	10/23/2003	17:28	Cloudy	Inattention, No improper driving	Rear End	0	0	S	SH
0417/9484-03	Williston	0.74	8/5/2003	13:02	Clear	Unknown	Rear End	0	0	S	SH
0417/7405	Williston	0.88	12/9/1999	16:10	Clear	Followed too closely	Rear End	2	0	W	SH
0417/9918-02	Williston	0.88	10/24/2002	14:00	Clear	No improper driving		0	0	S	SH
0417/13363-03	Williston	0.99	11/6/2003	18:40	Clear	Under the influence of medication/drugs/alcohol, Inattention, No improper driving	Rear End	1	0	W	SH
0417/5656	Williston	1.02	6/22/1999	14:30	Clear	Other improper action		0	0	S	SH
0417/5781	Williston	1.02	6/29/1999	15:15	Clear	Exceeded authorized speed limit	Rear End	0	0	W	SH
0417/13598	Williston	1.02	10/5/2001	11:13	Cloudy	Other improper action	Rear End	2	0	W	SH
0417/5157-03	Williston	1.05	4/4/2003	10:30	Unknown	Unknown	Rear End	0	0	E	SH
0417/7057-03	Williston	1.05	6/8/2003	10:48	Clear	No improper driving, Disregarded traffic signs, signals, road markings. Inattention	No Turns, Thru moves only, Broadside ^<	0	0	S	SH
0417/16308-03	Williston	1.27	12/24/2003	11:56	Rain	Followed too closely, Inattention, No improper driving	Rear End	0	0	W	SH
0417/2058-03	Williston	1.29	2/26/2003	13:12	Clear	Failed to yield right of way, No improper driving	Right Turn and Thru, Same Direction Sideswipe/Angle Crash ^^--	0	0	S	SH
0417/18183-03	Williston	1.32	6/6/2003	13:29	Clear	Inattention, Unknown	Rear End	0	0	W	SH
0417/10497-03	Williston	1.32	9/3/2003	17:10	Cloudy	Failed to yield right of way, Made an improper turn, No improper driving	Same Direction Sideswipe	0	0	E	SH
0417/13883-02	Williston	1.33	11/30/2002	15:04	Cloudy	No improper driving, Failed to yield right of way	Left Turn and Thru, Broadside v<--	0	0	E	SH

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Date Marker MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: US-2										
0417/5656-03	Williston	1.33	4/23/2003	15:59	Cloudy	Unknown	Rear End	0	0	E SH
* 0417/4407	Williston	1.38	2/18/1999	17:50	Clear	Inattention	Rear End	1	0	E SH
0417/5966-03	Williston	1.38	5/7/2003	8:40	Clear	Unknown	No Turns, Thru moves only, Broadside ^<	0	0	E SH
0417/13219-03	Williston	1.38	11/1/2003	18:15	Cloudy	No improper driving	Opp Direction Sideswipe	0	0	W SH
0417/550-03	Williston	1.39	1/11/2003	18:02	Clear	Failed to yield right of way, No improper driving	Head On	0	0	S SH
* 0417/9128	Williston	1.41	5/11/2000	12:00	Cloudy	Failed to yield right of way		1	0	E SH
* 0417/02364-02	Williston	1.41	7/29/2002	13:36	Cloudy	Inattention, No improper driving	Rear End	0	0	S SH
0417/14355-03	Williston	1.41	11/18/2003	15:03	Cloudy	Failed to yield right of way, Inattention, No improper driving	Same Direction Sideswipe	0	0	E SH
* 0417/4800	Williston	1.42	4/1/1999	8:55	Clear	Other improper action		2	0	E SH
* 0417/7407	Williston	1.42	11/29/1999	22:30	Snow	Failed to yield right of way		0	0	E SH
* 0417/7406	Williston	1.42	12/27/1999	6:00	Clear	Disregarded traffic signs, signals, road markings		1	0	W SH
* 0417/13678	Williston	1.42	3/26/2001	3:23	Clear	Disregarded traffic signs, signals, road markings		0	0	N SH
* 0417/12674	Williston	1.42	6/8/2001	13:15	Clear	Failed to yield right of way		2	0	S SH
* 0417/12931	Williston	1.42	7/3/2001	22:32	Clear	Failed to yield right of way		1	0	E SH
* 0417/13732	Williston	1.42	12/6/2001	18:45	Clear	Failed to yield right of way		1	0	S SH
* 0417/178-02	Williston	1.42	2/26/2002	18:10	Cloudy	Other improper action, Wrong side or wrong way		0	0	E SH
* 0417/7330-02	Williston	1.42	6/22/2002	17:45	Cloudy	No improper driving, Failed to yield right of way, Disregarded traffic signs, signals, road markings	Opp Direction Sideswipe	0	0	S SH
* 0417/8189-02	Williston	1.42	8/13/2002	17:46	Clear	Failed to yield right of way		2	0	E SH
* 0417/02654-02	Williston	1.42	8/20/2002	13:35	Clear	Unknown	No Turns, Thru moves only, Broadside ^<	0	0	E SH
* 0417/8708-02	Williston	1.42	8/30/2002	20:45	Clear	No improper driving, Inattention	Same Direction Sideswipe	0	0	W SH
0417/02WY0310	Williston	1.42	9/25/2002	14:17	Clear	Inattention, No improper driving	Left Turn and Thru, Broadside v<--	0	0	N SH
0417/9754-02	Williston	1.42	10/19/2002	11:08	Cloudy	Failed to yield right of way, Inattention, No improper driving	Opp Direction Sideswipe	2	0	E SH
0417/9944-02	Williston	1.42	10/24/2002	22:14	Clear	Failed to yield right of way		2	0	S SH
0417/17539-03	Williston	1.42	1/15/2003	17:19	Clear	Unknown	No Turns, Thru moves only, Broadside ^<	0	0	SH
0417/17800-03	Williston	1.42	2/23/2003	15:15	Sleet, Hail (Freezing Rain or	No improper driving	Rear End	0	0	W SH
0417/2608-03	Williston	1.42	3/8/2003	18:50	Clear	Failed to yield right of way, No improper driving	Left Turn and Thru, Broadside v<--	2	0	E SH
0417/4775-03	Williston	1.42	4/4/2003	11:05	Cloudy	Followed too closely, No improper driving	Rear End	0	0	E SH
0417/5659-03	Williston	1.42	4/18/2003	17:47	Not Reported	No improper driving	Rear End	0	0	E SH
0417/5657-03	Williston	1.42	4/21/2003	19:54	Clear	Inattention, No improper driving	Rear End	0	0	N SH
0417/7985-03	Williston	1.42	7/1/2003	7:45	Clear	No improper driving	Same Direction Sideswipe	0	0	E SH
* 0417/9028-02	Williston	1.43	8/31/2002	14:40	Clear	Failed to yield right of way, No improper driving	Rear End	3	0	N SH
0417/12868-02	Williston	1.43	12/23/2002	16:45	Cloudy	Inattention, Followed too closely, No improper driving	Rear End	1	0	E SH
* 0417/6166	Williston	1.44	8/19/1999	17:05	Clear	Failed to yield right of way		0	0	W SH
* 0417/7060-02	Williston	1.44	7/26/2002	18:28	Clear	Driving too fast for conditions, Exceeded authorized speed limit, No improper driving	Same Direction Sideswipe	0	0	W SH
0417/3663-03	Williston	1.44	3/22/2003	14:00	Cloudy	Failed to yield right of way, Distracted, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	N SH
0417/14331-03	Williston	1.44	11/25/2003	17:08	Cloudy	Failed to yield right of way, Inattention, No improper driving	Same Direction Sideswipe	0	0	N SH
0417/1486-03	Williston	1.46	1/13/2003	15:44	Clear	Failed to yield right of way, No improper driving	Left Turns, Opposite Directions, Head On/Angle Crash --^v--	0	0	E SH
0417/4646-03	Williston	1.46	3/8/2003	7:49	Unknown	Followed too closely, No improper driving	Rear End	0	0	SH
* 0417/5784	Williston	1.48	6/27/1999	9:56	Clear	Other improper action		1	0	E SH
* 0417/6168	Williston	1.48	8/4/1999	17:06	Rain	Failed to yield right of way		1	0	S SH
* 0417/8902	Williston	1.48	4/27/2000	17:14	Clear	Failed to yield right of way		1	0	N SH

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: US-2											
* 0417/8900	Williston	1.48	5/24/2000	19:20	Clear	Failed to yield right of way		1	0	E	SH
* 0417/12673	Williston	1.48	6/15/2001	9:14	Other	Failed to yield right of way		2	0	E	SH
* 0417/12805	Williston	1.48	7/11/2001	11:10	Clear	Failed to yield right of way		1	0	E	SH
* 0417/13675	Williston	1.48	10/29/2001	18:26	Clear	Other improper action		0	0	N	
* 0417/13679	Williston	1.48	10/29/2001		Clear	Failed to yield right of way		2	0	E	SH
* 0417/7372-02	Williston	1.48	7/22/2002	14:12	Clear	Failed to yield right of way, No improper driving	Left Turn and Thru, Angle Broadside -->v--	0	0	N	SH
0417/8576-02	Williston	1.55	8/19/2002	7:42	Clear	Failed to yield right of way, Disregarded traffic signs, signals, road markings, No improper driving		2	0	E	SH
0417/7151-02	Williston	1.56	8/3/2002	10:30	Not Reported	Inattention	Rear End	0	0	E	SH
0417/02974-02	Williston	1.56	9/13/2002	12:26	Clear	Driving too fast for conditions, No improper driving	Rear End	0	0	W	SH
0417/10801-03	Williston	1.59	9/10/2003	18:56	Clear	Distracted, No improper driving	Other	1	0	W	SH
0417/8204-02	Williston	1.66	8/14/2002	16:23	Clear	Unknown	Rear End	0	0	W	SH
0417/9039-03	Williston	1.67	7/20/2003	12:46	Clear	Inattention, No improper driving	Rear End	0	0	N	SH
0417/9766-03	Williston	1.68	8/16/2003	23:16	Cloudy	Unknown	Right Turn and Thru, Angle Broadside -->^--	0	0	E	SH
0417/4798	Williston	1.69	4/4/1999	0:17	Rain	Fatigued, asleep		0	0	E	SH
0417/8904	Williston	1.78	5/9/2000	14:30	Rain	Failed to yield right of way		0	0	E	SH
0417/13261	Williston	1.78	9/13/2001	12:15	Clear	Failed to yield right of way		0	0	S	SH
0417/14353	Williston	2	5/31/2001	21:30	Clear	Driving too fast for conditions, Other improper action	Head On	2	0	E	SH
0417/1690-03	Williston	2.04	2/12/2003	14:25	Clear	Driving too fast for conditions	Single Vehicle Crash	0	0		SH
0417/15023	Williston	2.35	1/24/2002	14:45	Rain	Inattention, Other improper action	Rear End	0	0	E	SH
0417/02W10302	Williston	2.5	9/18/2002	8:29	Clear	No improper driving	Rear End	0	0	W	SH
0417/12049-03	Williston	2.6	10/4/2003	12:25	Rain	Unknown	Rear End	0	0	E	SH
0417/5652	Williston	2.62	7/11/1999	8:27	Cloudy	Failed to yield right of way		0	0	W	SH
0417/42-02	Williston	2.75	2/18/2002	16:44	Clear			0	0	E	SH
0417/479-03	Williston	2.78	1/9/2003	8:41	Snow	No improper driving	Rear End	0	0	W	SH
0417/2193-02	Williston	2.9	7/12/2002	21:04	Clear		Single Vehicle Crash	0	0	W	SH
0417/6723-03	Williston	3.06	5/25/2003	19:04	Clear	Exceeded authorized speed limit	Single Vehicle Crash	0	0	E	SH
0417/10207	Williston	3.1	10/12/2000	15:27	Clear	Disregarded traffic signs, signals, road markings		4	0	E	SH
0417/1763-03	Williston	3.1	2/15/2003	12:26	Clear	Inattention, No improper driving	Rear End	0	0	E	SH
0417/16294-03	Williston	3.1	12/26/2003	8:09	Snow	Failed to yield right of way, Disregarded traffic signs, signals, road markings, No improper driving	Same Direction Sideswipe	0	0	W	SH
0417/10252	Williston	3.35	5/5/2000	14:30	Cloudy	Followed too closely	Rear End	0	0	E	SH
0417/266-02	Williston	3.35	3/16/2002	13:23	Cloudy	Inattention	Rear End	1	0	E	SH
0417/18350-03	Williston	3.35	6/26/2003	7:05	Unknown	Other improper action, Inattention	Single Vehicle Crash	0	0		SH
0417/10649-03	Williston	3.48	8/20/2003	13:39	Clear	Inattention, No improper driving	Rear End	0	0	W	SH
0418/14679	Williston	3.5	9/28/2001	19:00	Cloudy	Other improper action		1	1	E	SH
0417/9657-02	Williston	3.51	9/18/2002	8:17	Clear	Inattention	Rear End	2	0	W	SH
0417/14354	Williston	3.57	4/30/2001	15:56	Clear	Technology Related Distraction		1	0	E	SH
0417/8129	Williston	3.74	1/23/2000	10:06	Cloudy	Failed to yield right of way		1	0	E	SH
0417/8508	Williston	3.74	3/13/2000	7:50	Clear	Failed to yield right of way		0	0	E	SH
0417/10356	Williston	3.74	10/10/2000	7:50	Snow	Failed to yield right of way		2	0	W	SH
0417/8687-01	Williston	3.74	10/19/2001	15:33	Cloudy	No improper driving, Disregarded traffic signs, signals, road markings	Rear End	0	0	E	SH

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: US-2											
0417/13600	Williston	3.74	11/1/2001	17:27	Clear	Disregarded traffic signs, signals, road markings		1	0	E	SH
0417/14783	Williston	3.74	1/4/2002	20:08	Clear	Other improper action		0	0	E	SH
0417/3445-02	Williston	3.74	3/23/2002	15:10	Clear	No improper driving, Disregarded traffic signs, signals, road markings	No Turns, Thru moves only, Broadside ^<	0	0	S	SH
0417/7240-02	Williston	3.74	8/13/2002	8:57	Clear	Disregarded traffic signs, signals, road markings, No improper driving		0	0	E	SH
0417/13009-02	Williston	3.74	11/6/2002	11:09	Rain	No improper driving, Disregarded traffic signs, signals, road markings, Inattention	Left Turn and Thru, Same Direction Sideswipe/Angle Crash vV--	0	0	N	SH
0417/14198-02	Williston	3.74	12/7/2002	15:36	Cloudy	Followed too closely, No improper driving	Rear End	1	0		SH
0417/12412-02	Williston	3.74	12/17/2002	12:59	Clear	No improper driving, Disregarded traffic signs, signals, road markings, Exceeded authorized speed limit	No Turns, Thru moves only, Broadside ^<	1	0	N	SH
0417/4304-03	Williston	3.74	2/27/2003	11:06	Clear	Unknown	No Turns, Thru moves only, Broadside ^<	0	0	E	SH
0417/13211-03	Williston	3.74	10/27/2003	8:13	Rain	Driving too fast for conditions, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	E	SH
0417/10548-03	Williston	3.79	9/5/2003	19:05	Cloudy	Driving too fast for conditions, No improper driving	Same Direction Sideswipe	0	0	N	SH
0417/4498	Williston	3.85	3/1/1999	21:00	Clear	Fatigued, asleep		1	0	E	SH
0417/9290-02	Williston	4.24	9/7/2002	15:53	Clear	No improper driving, Inattention	Rear End	0	0	W	SH
0417/4232	Williston	5.17	2/6/1999	8:00	Cloudy	Other improper action		0	0	E	SH
0417/15263-03	Williston	5.21	12/6/2003	9:55	Snow	Unknown	Single Vehicle Crash	0	0	E	SH
0417/4112	Williston	5.26	1/28/1999	8:18	Snow	Driving too fast for conditions	Head On	0	0	E	SH
0417/11095-03	Williston	5.36	9/19/2003	10:04	Severe Crosswinds	No improper driving	Same Direction Sideswipe	0	0	E	SH
0417/5957	Williston	5.51	11/19/1999	16:00	Clear	Other improper action		2	0	E	SH
0417/13220-03	Williston	5.61	11/3/2003	10:54	Rain	No improper driving	Rear End	0	0	W	SH
0417/227-02	Williston	5.89	2/12/2002	12:02	Other	Other improper action		1	0	W	SH
0417/5961	Williston	UNK	1/29/1999	16:15	Clear	Failed to yield right of way		0	0	E	SH
0417/5962	Williston	UNK	7/12/1999	9:50	Clear	Other improper action		1	0		SH
0417/14452	Williston	UNK	12/12/2001	14:44	Cloudy	Failed to yield right of way		2	0	E	SH
0417/9303-02	Williston	UNK	9/6/2002	14:45	Clear	No improper driving	Single Vehicle Crash	1	0	E	SH
0417/10943-02	Williston	UNK	10/8/2002	15:18	Cloudy	Inattention	Rear End	0	0	W	SH
0417/11121-02	Williston	UNK	10/9/2002	16:45	Cloudy	No improper driving, Failed to yield right of way	Left Turn and Thru, Broadside v<--	0	0	E	SH
0417/12265-02	Williston	UNK	10/22/2002	7:41	Clear	Unknown, No improper driving	Rear End	0	0	N	SH
0417/10089-02	Williston	UNK	10/31/2002	12:23	Clear	No improper driving, Failed to yield right of way		0	0	E	SH
0417/10487-02	Williston	UNK	11/1/2002	12:50	Cloudy	Distracted, Followed too closely, No improper driving	Rear End	0	0	W	SH
0417/12674-02	Williston	UNK	11/4/2002	18:04	Cloudy	No improper driving, Inattention	Rear End	0	0	N	SH
0417/12477-02	Williston	UNK	11/7/2002	6:35	Other	Driving too fast for conditions	Single Vehicle Crash	0	0	E	SH

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-117											
0406/7947-02	Essex	0	8/6/2002	20:23	Cloudy	Under the influence of medication/drugs/alcohol, Failed to yield right of way, Disregarded traffic signs, signals, road markings		0	0	S	SH
0406/3624-03	Essex	0.02	2/10/2003	18:53	Cloudy	No improper driving, Inattention	Rear End	1	0	W	SH
0406/6355-02	Essex	0.07	6/24/2002	8:53	Clear	Inattention, No improper driving	Rear End	0	0	W	SH
0406/4173	Essex	0.08	1/13/1999	13:00	Snow	Failure to keep in proper lane or running off road		0	0	S	SH
0406/11183-03	Essex	0.34	9/20/2003	16:10	Cloudy	Inattention	Right Turn and Thru, Broadside ^<--	0	0	E	SH
0406/6408-03	Essex	0.42	5/22/2003	7:25	Clear	Followed too closely, No improper driving	Rear End	0	0	W	SH
0406/11242-03	Essex	0.42	9/20/2003	12:46	Clear	Followed too closely, No improper driving	Rear End	2	0	W	SH
0406/3341-02	Essex	0.55	3/26/2002		Snow	Unknown	Rear End	0	0	W	SH
0406/2151-02	Essex	0.9	2/15/2002	12:15	Cloudy	Exceeded authorized speed limit	Single Vehicle Crash	0	0	E	SH
0406/7224	Essex	0.91	11/17/1999	6:56	Unknown	Made an improper turn	Head On	0	0	E	SH
0406/11713	Essex	0.91	1/23/2001	6:15	Cloudy	Made an improper turn		0	0	E	SH
0406/5707	Essex	1.52	6/28/1999	9:07	Rain	Failed to yield right of way		2	0	S	SH
0406/8874	Essex	1.52	5/22/2000	15:57	Clear	Followed too closely	Rear End	2	0	E	SH
0406/13313	Essex	1.71	8/15/2001	13:23	Clear	Followed too closely	Rear End	0	0	W	SH
0406/8978-03	Essex	1.71	7/25/2003	18:06	Clear	Followed too closely, Distracted, No improper driving, Unknown	Rear End	1	0	E	SH
0406/6846	Essex	2.11	9/28/1999	6:56	Fog, Smog, Smoke	Driving too fast for conditions, Other improper action	Rear End	1	0	E	SH
0406/9324	Essex	2.75	7/11/2000	19:00	Clear	Other improper action		1	0	E	SH
0406/13375	Essex	2.75	9/13/2001	17:03	Clear	Inattention	Rear End	2	0	E	SH
0406/8630	Essex	2.95	3/8/2000	16:46	Clear	Other improper action, Followed too closely	Rear End	0	0	E	SH
0406/4174	Essex	2.96	1/26/1999	17:23	Snow	Followed too closely	Rear End	2	0	E	SH
0406/8728	Essex	2.96	4/6/2000	6:00	Clear	Fatigued, asleep		1	0	W	SH
0406/6005-03	Essex	3.17	5/10/2003	16:18	Clear	Made an improper turn, No improper driving	Same Direction Sideswipe	0	0		SH
0406/5845-02	Essex	3.19	6/12/2002	19:32	Clear	No improper driving, Followed too closely	Rear End	2	0	N	SH
0406/10447-01	Essex	3.23	10/13/2001	13:59	Clear	Other improper action, Operating defective equipment		1	0	E	SH
0406/7227	Essex	3.28	11/16/1999	23:52	Snow	Technology Related Distraction		0	0	S	SH
0406/8629	Essex	3.28	4/13/2000	19:26	Clear	Failed to yield right of way		0	0	E	SH
0406/13822	Essex	3.28	11/14/2001	15:50	Clear	Technology Related Distraction		0	0	W	SH
0406/9345-03	Essex	3.28	8/4/2003	16:45	Clear	Failed to yield right of way	No Turns, Thru moves only, Broadside ^<	1	0	S	SH
0406/9440-03	Essex	3.28	8/4/2003	17:10	Clear	Unknown	Rear End	0	0	S	SH
0406/6934	Essex	3.53	8/19/1999	22:03	Cloudy	Exceeded authorized speed limit		1	0	N	SH
0406/8875	Essex	3.81	5/12/2000	16:05	Clear	Failed to yield right of way	Rear End	1	0	E	SH
0406/13175	Essex	3.81	6/26/2001	7:50	Clear	Made an improper turn		1	0	E	SH

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-117											
0406/12867	Essex	3.81	7/6/2001	11:48	Clear	Inattention, Followed too closely	Rear End	1	0	N	SH
0406/13823	Essex	3.81	11/25/2001	11:05	Clear	Failed to yield right of way, Other improper action		2	0	E	SH
0406/6705-02	Essex	3.81	7/30/2002	15:03	Clear	No improper driving, Failed to yield right of way		2	0	E	SH
0406/13906-03	Essex	3.81	11/15/2003	12:02	Clear	Other improper action	Same Direction Sideswipe	1	0	E	SH
0406/10187	Essex	4.11	9/18/2000	18:28	Clear	Wrong side or wrong way	Head On	0	0	E	SH
0417/5948-02	Essex	4.23	6/23/2002	20:31	Rain	No improper driving, Followed too closely	Rear End	0	0	E	SH
0406/6935	Essex	UNK	10/5/1999		Unknown	Made an improper turn	Rear End	0	0	W	SH

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-15											
0406/12840	Essex	0.037	6/27/2001	7:14	Cloudy	Followed too closely	Rear End	1	0	W	SH
0406/230-03	Essex	0.19	1/17/2003	20:34	Clear	Exceeded authorized speed limit, Driving too fast for conditions, Under the influence of medication/drugs/alcohol	Head On	1	1	E	SH
0405/3036-02	Essex	0.3	6/15/2002	18:50	Rain	Inattention, No improper driving	Rear End	0	0	E	SH
0406/959-03	Essex	0.39	1/18/2003	14:45	Snow	Followed too closely, No improper driving	Rear End	0	0	E	SH
0406/3348-03	Essex	0.39	2/12/2003	15:15	Clear	No improper driving, Driving too fast for conditions, Failure to keep in proper lane or running off road	Head On	0	0	E	SH
0406/351-03	Essex	0.51	1/4/2003	15:02	Cloudy	Other improper action, No improper driving		0	0		SH
0406/9789	Essex	0.52	8/6/2000	11:05	Clear	Other improper action	Rear End	1	0	E	SH
0406/4041	Essex	0.56	1/2/1999	8:03	Clear	Followed too closely	Rear End	0	0	W	SH
0406/8276	Essex	0.56	2/26/2000	12:20	Clear	Inattention	Rear End	0	0	W	SH
0406/8732	Essex	0.56	4/29/2000	13:26	Clear	Followed too closely	Rear End	0	0	E	SH
0406/3878-02	Essex	0.56	4/10/2002	17:37	Clear	Followed too closely, No improper driving	Rear End	0	0	E	SH
0406/6481	Essex	0.57	8/24/1999	10:07	Clear	Followed too closely	Rear End	0	0	E	SH
0406/9271	Essex	0.57	6/26/2000	10:38	Unknown	Other improper action	Rear End	2	0	W	SH
0406/10697	Essex	0.57	10/15/2000	9:29	Clear	Other improper action		1	0	N	SH
0406/12721	Essex	0.57	6/20/2001	17:35	Clear	Disregarded traffic signs, signals, road markings		0	0	E	SH
0406/13153	Essex	0.57	9/3/2001	21:05	Clear	Followed too closely, Inattention		0	0	E	SH
0406/2894-02	Essex	0.57	3/19/2002	16:26	Cloudy	Made an improper turn, No improper driving	Rear End	0	0	E	SH
0406/13396-02	Essex	0.57	11/15/2002	10:18	Cloudy	Unknown, Exceeded authorized speed limit, Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner, No improper driving	Rear End	2	0	E	SH
0406/844-03	Essex	0.57	1/18/2003	9:46	Cloudy	Other improper action	Single Vehicle Crash	1	0	W	SH
0406/11077-	Essex	0.57	9/17/2003	17:08	Clear	No improper driving, Followed too closely, Unknown	Rear End	0	0		SH
0406/11098-03	Essex	0.57	9/20/2003	21:00	Cloudy	Unknown	Left Turn and Thru, Same Direction Sideswipe/Angle Crash	0	0	E	SH
0406/13055-	Essex	0.57	10/31/2003	15:05	Clear	Failed to yield right of way, No improper driving	Rear End	0	0		SH
0406/16934-	Essex	0.57	12/30/2003	18:48	Unknown	Inattention, No improper driving	Same Direction Sideswipe	0	0		SH
0406/10429-03	Essex	0.6	9/1/2003	10:50	Unknown	Unknown	Left Turn and Thru, Same Direction Sideswipe/Angle Crash	0	0	N	SH
0406/12839	Essex	0.67	6/21/2001	13:08	Clear	Followed too closely	Rear End	0	0	W	SH
0406/9573-03	Essex	0.67	8/1/2003	0:37	Clear	Under the influence of medication/drugs/alcohol, Other improper action	Rear End	0	0		SH
0406/14516	Essex	0.8	9/19/2001	14:26	Clear		Rear End	2	0	E	SH
0406/10475-	Essex	0.83	11/8/2002	11:35	Cloudy	No improper driving, Followed too closely	Rear End	0	0	W	SH
0406/6675-03	Essex	0.85	5/30/2003	8:16	Clear	Unknown	Single Vehicle Crash	0	0	W	SH
0406/6573	Essex	0.87	9/10/1999	16:45	Clear	Followed too closely	Rear End	0	0	W	SH
0406/10544-	Essex	0.88	9/2/2003	6:55	Cloudy	Inattention, No improper driving	Same Direction Sideswipe	0	0	W	SH
0406/13764	Essex	0.98	11/3/2001	11:33	Clear	Followed too closely, Operating defective equipment		1	0	E	SH
0406/7678	Essex	1	1/11/1999	15:17	Clear	Followed too closely	Rear End	2	0	E	SH
0406/13151	Essex	1.02	9/2/2001	18:07	Clear	Made an improper turn, Failed to yield right of way		1	0	W	SH
0406/12065-02	Essex	1.02	12/9/2002	8:14	Clear	Followed too closely, Visibility obstructed, No improper driving	Rear End	0	0		SH
0405/1848-03	Essex	1.02	2/14/2003	7:25	Clear	Inattention, Failed to yield right of way, Driving too fast for conditions	No Turns, Thru moves only, Broadside ^<	0	0	S	SH

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-15											
0406/8432-03	Essex	1.02	7/9/2003	16:09	Clear	Disregarded traffic signs, signals, road markings, Technology Related Distraction, No improper driving	Right Turn and Thru, Same Direction Sideswipe/Angle Crash ^^--	0	0	E	SH
0406/17276-03	Essex	1.02	11/29/2003	0:45	Clear	Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner, Under the influence of medication/drugs/alcohol No improper driving	Left Turn and Thru, Angle Broadside -->v--	1	0		SH
0406/13307-03	Essex	1.15	11/6/2003	18:00	Cloudy	Failed to yield right of way, No improper driving	Left Turn and Thru, Angle Broadside -->v--	2	0	E	SH
0406/13768	Essex	1.22	11/28/2001	13:05	Clear	Failed to yield right of way		0	0	W	SH
0406/9037	Essex	1.25	5/18/2000	11:20	Rain	Failed to yield right of way		1	0	W	SH
0406/8874-02	Essex	1.25	8/31/2002	23:06	Unknown	No improper driving, Failed to yield right of way	No Turns, Thru moves only, Broadside ^<	1	0	E	SH
0406/16171-	Essex	1.25	12/23/2003	16:50	Clear	No improper driving, Failed to yield right of way	Head On	0	0	W	SH
0406/8272-02	Essex	1.26	8/30/2002	11:35	Clear	Failed to yield right of way, No improper driving		1	0	S	SH
0406/8320-03	Essex	1.26	7/9/2003	12:05	Clear	Other improper action, No improper driving	Rear End	0	0	E	SH
0406/4440	Essex	1.3	2/2/1999	12:05	Unknown	Made an improper turn, Inattention		2	0	E	SH
0406/9270	Essex	1.36	6/29/2000	21:05	Rain	Inattention	Rear End	1	0	E	SH
0406/13771	Essex	1.36	11/30/2001	21:16	Rain	Driving too fast for conditions	Rear End	3	0	E	SH
0406/6122-02	Essex	1.36	7/10/2002	14:29	Cloudy	Inattention	No Turns, Thru moves only, Broadside ^<	1	0	S	SH
0406/6231-02	Essex	1.36	7/17/2002	20:37	Clear	Driving too fast for conditions, No improper driving		0	0	S	SH
0406/5866	Essex	1.4	7/21/1999	17:25	Clear	Failed to yield right of way		1	0	S	SH
0406/5174	Essex	1.42	5/20/1999	17:40	Clear	Failed to yield right of way		0	0	S	SH
0406/7666	Essex	1.42	12/31/1999	12:28	Clear	Failed to yield right of way		1	0	S	SH
0406/6509-03	Essex	1.42	5/24/2003	14:01	Rain	No improper driving, Failure to keep in proper lane or running off road, Driving too fast for conditions	Head On	0	0	E	SH
0406/12000-	Essex	1.42	10/9/2003	12:03	Clear	Wrong side or wrong way, No improper driving	Rear End	0	0	E	SH
0406/12291-	Essex	1.42	10/18/2003	21:30	Cloudy	No improper driving, Failed to yield right of way	Left Turn and Thru, Broadside v<--	2	0	E	SH
0406/6929-02	Essex	1.43	7/9/2002	14:20	Clear	Unknown		0	0		SH
0406/8309-03	Essex	1.43	7/8/2003	9:45	Clear	Unknown	Same Direction Sideswipe	0	0	W	SH
0406/9444-03	Essex	1.43	8/5/2003	14:39	Clear	Exceeded authorized speed limit, No improper driving	Rear End	0	0	E	SH
0406/9790	Essex	1.44	9/1/2000	23:14	Cloudy	Other improper action		1	0	W	SH
0406/14347	Essex	1.46	12/28/2001	21:23	Clear	Followed too closely, Other improper action		2	0	W	SH
0120/7204-02	Essex	1.48	8/9/2002	20:15		Unknown	Rear End	2	0		SH
0406/14-02	Essex	1.49	1/26/2002	0:35	Clear	Exceeded authorized speed limit, Other improper action		1	0	W	SH
0406/8328-03	Essex	1.49	7/10/2003	14:25	Clear	Followed too closely, No improper driving	Rear End	0	0	W	SH
0406/13357	Essex	1.51	9/9/2001	11:20	Clear	Failed to yield right of way		0	0	E	SH
0406/8321	Essex	1.55	3/3/2000	13:58	Unknown	Technology Related Distraction	Rear End	0	0	W	SH
0406/14225	Essex	1.55	10/19/2001	9:25	Clear	Failed to yield right of way		0	0	E	SH
0406/3157-02	Essex	1.55	3/26/2002	16:00	Snow	No improper driving, Failed to yield right of way, Inattention		0	0	E	SH
0406/13437-	Essex	1.55	12/13/2002	13:00	Cloudy	Followed too closely, No improper driving	Rear End	1	0	W	SH
0406/8958	Essex	1.56	4/21/2000	8:09	Clear	Failed to yield right of way		1	0	E	SH
0406/13150	Essex	1.56	8/13/2001	12:53	Clear	Followed too closely	Rear End	1	0	E	SH
0406/5791-03	Essex	1.56	5/2/2003	15:25	Cloudy	No improper driving, Failed to yield right of way	No Turns, Thru moves only, Broadside ^<	2	0	E	SH
0406/12812-	Essex	1.56	10/23/2003	12:02	Snow	No improper driving, Failed to yield right of way	Left Turn and Thru, Angle Broadside -->v--	0	0	W	SH
0406/5952	Essex	1.57	9/3/1999	21:23	Clear	Other improper action		0	0	W	SH
0406/6570	Essex	1.57	9/5/1999		Clear	Inattention	Rear End	2	0	E	SH

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-15											
0406/12005	Essex	1.57	2/17/2001	15:38	Clear	Failed to yield right of way	Head On	2	0	E	SH
0406/12838	Essex	1.57	6/15/2001	17:30	Clear	Inattention		1	0	E	SH
0406/14448	Essex	1.57	11/13/2001	16:43	Clear	Followed too closely	Rear End	1	0	W	SH
0406/15484-03	Essex	1.58	12/13/2003	18:05	Cloudy	No improper driving, Inattention	Left Turn and Thru, Same Direction Sideswipe/Angle Crash	0	0	W	SH
0406/12408-	Essex	1.66	10/20/2003	14:51	Cloudy	No improper driving, Followed too closely	vw-- Rear End	0	0	E	SH
0406/11426-03	Essex	1.67	9/28/2003	16:05	Rain	No improper driving, Disregarded traffic signs, signals, road markings	Left Turn and Thru, Head On ^v--	1	0	S	SH
0406/11035	Essex	1.68	12/8/2000	14:09	Cloudy	Followed too closely	Rear End	1	0	E	SH
0406/13722-	Essex	1.69	11/13/2003	15:22	Cloudy	Followed too closely, No improper driving	Rear End	0	0		SH
0406/12170	Essex	1.71	3/15/2001	15:56	Unknown	Followed too closely	Rear End	0	0	E	SH
0406/5950	Essex	1.72	8/5/1999	11:35	Cloudy	Inattention	Rear End	0	0	W	SH
0406/14204	Essex	1.72	12/7/2001	7:48	Clear	Wrong side or wrong way	Head On	0	0	E	SH
0406/10627	Essex	1.78	4/3/2000	14:39	Rain	Followed too closely	Rear End	3	0	W	SH
0406/15905-	Essex	1.78	12/16/2003	8:12	Clear	No improper driving, Other improper action	Rear End	0	0	W	SH
0406/10601-	Essex	1.8	7/7/2003	7:45	Clear	Failed to yield right of way, No improper driving	No Turns, Thru moves only, Broadside ^<	1	0	E	SH
0406/15234-03	Essex	1.82	12/6/2003	11:10	Snow	Driving too fast for conditions, Followed too closely, No improper driving	Rear End	0	0	E	SH
0406/13958-	Essex	1.83	11/18/2003	13:11	Cloudy	No improper driving, Followed too closely	Rear End	0	0		SH
0406/15463-	Essex	1.85	12/16/2003	9:19	Clear	Visibility obstructed	No Turns, Thru moves only, Broadside ^<	0	0	E	SH
0406/9146-03	Essex	1.86	7/30/2003	18:14	Unknown	Unknown	Rear End	0	0	E	SH
0406/10068	Essex	1.9	9/20/2000	13:28	Clear	Followed too closely	Rear End	1	0	E	SH
0406/10070	Essex	1.93	9/4/2000	21:13	Clear	Inattention	Rear End	1	0	E	SH
0406/10695	Essex	1.93	11/24/2000	8:01	Clear	Failed to yield right of way		1	0	E	SH
0406/14224	Essex	1.93	10/31/2001	7:35	Clear	Inattention	Rear End	1	0	W	SH
0406/10633-	Essex	1.96	7/16/2003	15:35	Clear	Inattention, No improper driving	Left Turn and Thru, Broadside v<--	0	0	W	SH
0406/4439	Essex	2.03	2/3/1999	17:35	Clear	Other improper action, Exceeded authorized speed limit		0	0	E	SH
0406/12562	Essex	2.1	6/6/2001	14:20	Clear	Failed to yield right of way		0	0	E	SH
0406/15006-	Essex	2.1	12/5/2003	13:14	Clear	Other improper action, Failed to yield right of way	Left Turn and Thru, Head On ^v--	0	0	E	SH
0406/15602-03	Essex	2.1	12/20/2003	0:17	Snow	Visibility obstructed, No improper driving	Right Turn and Thru, Same Direction Sideswipe/Angle Crash ^^--	0	0	S	SH
0406/8277	Essex	2.15	2/11/2000	18:39	Snow	Made an improper turn		1	0	E	SH
0406/10069	Essex	2.16	9/5/2000	16:03	Clear	Inattention, Followed too closely	Rear End	1	0	W	SH
0406/14205	Essex	2.16	12/6/2001	18:37	Clear	Visibility obstructed, Other improper action		1	0	W	SH
0406/6605-03	Essex	2.16	5/25/2003	11:38	Clear	Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner. No improper driving	Rear End	3	0		SH
0406/15906-	Essex	2.16	12/16/2003	10:34	Clear	No improper driving, Followed too closely	Rear End	0	0	E	SH
0406/13770	Essex	2.19	10/27/2001	19:39	Cloudy	Other improper action		0	0	S	SH
0406/14348	Essex	2.19	12/1/2001	2:35	Fog, Smog, Smoke	No improper driving		1	0	E	SH
0406/6771-03	Essex	2.2	5/30/2003	17:15	Not Reported	Inattention, No improper driving	Rear End	0	0	E	SH
0406/8740	Essex	2.28	4/15/2000	15:00	Unknown	Followed too closely	Rear End	0	0	W	SH
0406/608-02	Essex	2.28	1/16/2002	14:25	Clear	Followed too closely, No improper driving	Rear End	0	0	E	SH
0406/5101	Essex	2.3	5/4/1999	16:22	Clear	Followed too closely	Rear End	0	0	W	SH
0406/605-03	Essex	2.3	1/17/2003	16:12	Unknown	Unknown	Rear End	0	0	W	SH

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-15											
0406/6574	Essex	2.34	9/21/1999	16:10	Cloudy	Inattention, Followed too closely	Rear End	1	0	W	SH
0406/5951	Essex	2.38	8/7/1999	10:30		Followed too closely	Rear End	0	0	W	SH
0406/8322	Essex	2.39	2/25/2000	17:01	Clear	Failed to yield right of way		2	0	E	SH
0406/11085-	Essex	2.42	9/18/2003		Clear	No improper driving	Rear End	0	0		SH
0406/8961	Essex	2.44	5/24/2000	13:20	Rain	Followed too closely	Rear End	1	0	E	SH
0406/13262-	Essex	2.44	11/5/2003	15:17	Cloudy	Unknown	Right Turn and Thru, Broadside ^<--	0	0	S	SH
0406/15049-03	Essex	2.45	12/6/2003	12:53	Snow	No improper driving, Unknown, Driving too fast for conditions	Rear End	0	0	W	SH
0406/3514-02	Essex	2.51	4/14/2002	14:37	Cloudy	Inattention, Distracted, No improper driving	Rear End	1	0	E	SH
0406/7084-03	Essex	2.51	6/5/2003	14:40	Rain	Unknown, No improper driving	Rear End	0	0	E	SH
0406/14267-	Essex	2.53	12/9/2002	15:09	Cloudy	No improper driving, Inattention	Rear End	0	0	E	SH
0406/8415	Essex	2.58	3/17/2000	16:27	Clear	Followed too closely	Rear End	1	0	E	SH
0406/14428-	Essex	2.61	11/25/2003	14:50	Clear	Followed too closely, No improper driving, Unknown	Rear End	0	0	E	SH
0406/14784-	Essex	2.64	12/5/2003	12:20	Clear	Followed too closely, No improper driving	Rear End	0	0	W	SH
0406/12234-	Essex	2.66	11/1/2002	15:53	Sleet, Hail (Freezing Rain or	No improper driving, Failed to yield right of way, Inattention	Left Turn and Thru, Broadside v<--	1	0	E	SH
0406/6760-03	Essex	2.66	5/28/2003	12:57	Clear	Distracted, No improper driving	Rear End	0	0	W	SH
0406/5175	Essex	2.67	5/8/1999	23:54	Cloudy	Failed to yield right of way		2	0	S	SH
0406/13367-03	Essex	2.68	9/28/2003	18:10	Rain	No improper driving, Under the influence of medication/drugs/alcohol, Followed too closely	Rear End	3	0	S	SH
0406/13284-	Essex	2.71	11/3/2003	9:48	Clear	Followed too closely, Inattention, No improper driving	Rear End	0	0	W	SH
0406/8278	Essex	2.76	2/3/2000	8:01	Clear	Inattention	Rear End	2	0	E	SH
0406/13502	Essex	2.76	10/12/2001	7:40	Rain	Other improper action		0	0	S	SH
0406/5241-02	Essex	2.76	6/15/2002	9:00	Cloudy	Unknown	Rear End	4	0		SH
0406/976-03	Essex	2.76	1/31/2003	7:45	Clear	Failed to yield right of way, No improper driving		0	0	E	SH
0406/12705-	Essex	2.76	10/24/2003	15:56	Cloudy	Inattention, Followed too closely, No improper driving	Rear End	2	0	W	SH
0406/15439-	Essex	2.82	7/16/2003	15:10	Unknown	Inattention	Rear End	0	0	N	SH
0406/12115-	Essex	3.17	10/10/2003	8:21	Clear	No improper driving, Followed too closely	Rear End	0	0	W	SH
0406/6516-03	Essex	3.61	5/25/2003	14:50	Cloudy	No improper driving, Followed too closely	Rear End	0	0	W	SH
0406/12720	Essex	3.63	7/9/2001	18:00	Clear	Inattention, Failed to yield right of way		0	0	W	SH
0406/13241-03	Essex	3.63	11/4/2003	20:32	Cloudy	No improper driving, Disregarded traffic signs, signals, road markings, Technology Related Distraction	No Turns, Thru moves only, Broadside ^<	1	0	N	SH
0406/8275	Essex	3.79	2/17/2000	13:26	Clear	Inattention	Rear End	0	0	E	SH
0406/11579	Essex	3.79	1/26/2001	13:44	Clear	Disregarded traffic signs, signals, road markings		1	0	E	SH
0406/12428	Essex	3.79	5/14/2001	11:19	Clear	Disregarded traffic signs, signals, road markings		1	0	S	SH
0406/11533-	Essex	3.82	12/2/2002	10:11	Clear	Followed too closely, Inattention, No improper driving	Rear End	1	0	W	SH
0406/8960	Essex	3.83	5/25/2000	17:49	Cloudy	Operating defective equipment, Followed too closely	Rear End	2	0	W	SH
0406/6897-03	Essex	3.83	6/4/2003	17:15	Clear	Unknown	Rear End	0	0	E	SH
0406/9273-03	Essex	3.83	8/1/2003	10:11	Cloudy	Distracted, No improper driving	Rear End	1	0		SH
0406/5681	Essex	3.85	7/1/1999	14:26	Clear	Disregarded traffic signs, signals, road markings	Head On	0	0	E	SH
0406/12431	Essex	3.85	5/8/2001	17:49	Clear	Disregarded traffic signs, signals, road markings		1	0	E	SH
0406/9605-03	Essex	3.9	8/11/2003	13:11	Clear	Inattention, Followed too closely, No improper driving	Rear End	0	0		SH
0406/4441	Essex	3.93	1/28/1999	17:45	Snow	Other improper action		0	0	E	SH
0406/4275	Essex	3.93	1/30/1999	19:10	Clear	Wrong side or wrong way		0	0	E	SH

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-15											
0406/4529	Essex	3.93	2/12/1999	13:40	Unknown	Followed too closely	Rear End	0	0	W	SH
0406/11461	Essex	3.93	1/11/2001	16:06	Unknown	Disregarded traffic signs, signals, road markings		2	0	E	SH
0406/11682	Essex	3.93	2/9/2001	8:26	Unknown	Disregarded traffic signs, signals, road markings		0	0	E	SH
0406/14612-	Essex	3.93	12/24/2002	18:02	Clear	Made an improper turn, No improper driving	Left Turn and Thru, Angle Broadside -->v--	0	0	E	SH
0406/433-03	Essex	3.93	1/11/2003	18:15	Cloudy	Followed too closely, No improper driving	Rear End	0	0	W	SH
0406/5448	Essex	3.95	5/20/1999	9:15	Clear	Followed too closely	Rear End	2	0	W	SH
0406/17932-	Essex	3.99	3/13/2003	12:14	Clear	Followed too closely, No improper driving	Rear End	0	0		SH
0406/8027-03	Essex	3.99	7/3/2003	10:03	Clear	Followed too closely, No improper driving	Rear End	0	0		SH
0406/5117-02	Essex	4.06	6/5/2002	14:11	Cloudy	No improper driving	Rear End	1	0	W	SH
0406/4039	Essex	4.12	1/14/1999	15:45	Snow	Other improper action	Rear End	0	0	E	SH
0406/8741	Essex	4.12	4/17/2000	14:50	Cloudy	Inattention	Rear End	0	0	E	SH
0406/12323-	Essex	4.12	10/17/2003	14:59	Cloudy	Followed too closely, Inattention, No improper driving	Rear End	1	0	E	SH
0406/12990	Essex	4.17	7/22/2001	17:30	Clear	Followed too closely	Rear End	0	0	E	SH
0406/13506	Essex	4.19	9/28/2001	7:25	Rain	Followed too closely	Rear End	0	0	W	SH
0406/6201	Essex	4.3	8/6/1999	15:29	Rain	Followed too closely	Rear End	0	0	W	SH
0406/9788	Essex	4.3	9/1/2000	7:27	Unknown	Followed too closely	Rear End	4	0	W	SH
0406/12561	Essex	4.3	6/8/2001	13:25	Cloudy	Inattention	Rear End	0	0	E	SH
0406/5969	Essex	4.32	9/24/1999	7:30	Clear	Other improper action	Rear End	1	0	W	SH
0406/8114-02	Essex	4.4	8/8/2002	17:40	Unknown	No improper driving	Rear End	0	0	W	SH
0406/10558-	Essex	4.4	9/8/2002	16:10	Clear	Failed to yield right of way	Single Vehicle Crash	1	0	N	SH
0406/10696	Essex	4.42	11/19/2000	16:59	Clear	Failed to yield right of way, Other improper action		1	0	E	SH
0406/6812-02	Essex	4.42	7/29/2002	16:55	Clear	No improper driving, Disregarded traffic signs, signals, road markings. Failed to yield right of way		0	0	E	SH
0406/7944-03	Essex	4.42	6/30/2003	12:02	Clear	Followed too closely, Unknown, No improper driving	Rear End	1	0	W	SH
0406/7438	Essex	4.57	12/16/1999	16:40	Cloudy	Failed to yield right of way		0	0	W	SH
0406/8282-02	Essex	4.63	8/15/2002	15:24	Cloudy	Followed too closely, Inattention, No improper driving	Rear End	3	0	W	SH
0406/10757-	Essex	4.63	9/9/2003	15:19	Clear	Inattention, No improper driving	Rear End	2	0	W	SH
0406/8092-02	Essex	4.7	8/8/2002	17:17	Clear	Followed too closely, No improper driving	Rear End	2	0	E	SH
0406/10307-	Essex	4.74	8/29/2003	7:05	Clear	Followed too closely, No improper driving	Rear End	0	0	W	SH
0406/10862-	Essex	4.75	9/13/2003	12:55	Clear	No improper driving, Other improper action	Rear End	0	0	W	SH
0406/11681	Essex	4.83	2/15/2001	15:37	Unknown	Followed too closely	Rear End	3	0	E	SH
0406/8959	Essex	4.84	5/9/2000	14:33	Unknown	Visibility obstructed		0	0	E	SH
0406/7463-03	Essex	4.85	6/17/2003	14:47	Clear	Distracted, Unknown, No improper driving	Rear End	2	0	W	SH
0406/6788	Essex	4.87	9/26/1999	17:00	Clear	Followed too closely	Rear End	2	0	E	SH
0406/10790	Essex	4.87	12/5/2000	18:15	Snow	Other improper action		1	0	S	SH
0406/7200-02	Essex	4.87	7/31/2002	17:42	Clear	Failed to yield right of way, Followed too closely, No improper driving	Rear End	1	0	E	SH
0406/11474-	Essex	4.87	10/13/2002	16:56	Rain	Followed too closely, Distracted, No improper driving	Rear End	2	0	E	SH
0406/8957	Essex	4.96	5/8/2000	16:41	Rain	Followed too closely	Rear End	3	0	E	SH
0406/13765	Essex	4.96	5/20/2001	15:55	Clear	Other improper action		1	0	E	SH
0406/7974-03	Essex	4.99	7/1/2003	8:37	Clear	Followed too closely, No improper driving	Rear End	0	0	W	SH

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-15											
0406/9967-03	Essex	4.99	8/22/2003	16:57	Clear	No improper driving, Disregarded traffic signs, signals, road markings, Operating vehicle in erratic, reckless, careless, negligent or aggressive manner	Left Turn and Thru, Angle Broadside -->v--	0	0	E	SH
0406/10988-	Essex	4.99	9/4/2003	15:16	Cloudy	Followed too closely, Inattention, No improper driving	Rear End	0	0	W	SH
0406/15211-	Essex	5.14	12/8/2003	15:29	Clear	No improper driving, Followed too closely	Rear End	0	0	W	SH
0406/5105	Essex	5.17	5/6/1999	19:05	Clear	Followed too closely	Rear End	0	0	E	SH
0406/4151	Essex	5.21	1/14/1999	8:43	Clear	Followed too closely	Rear End	0	0	W	SH
0406/12989	Essex	5.21	8/2/2001	7:02	Cloudy	Followed too closely	Rear End	0	0	W	SH
0406/15025-	Essex	5.22	12/6/2003	11:46	Snow	No improper driving, Driving too fast for conditions	Rear End	0	0	W	SH
0406/13154	Essex	5.25	9/3/2001	13:54	Clear	Followed too closely	Rear End	0	0	W	SH
0406/5169	Essex	5.34	5/25/1999	11:23	Rain	Followed too closely	Rear End	1	0	W	SH
0406/7913-02	Essex	5.34	8/7/2002	18:12	Unknown	Under the influence of medication/drugs/alcohol, Driving too fast for conditions. No improper driving	Rear End	2	0	E	SH
0406/4160-02	Essex	5.44	4/13/2002	11:40	Cloudy	Distracted, Under the influence of medication/drugs/alcohol, No improper driving	Rear End	0	0	W	SH
0406/9158	Essex	5.48	6/5/2000	6:55	Clear	Followed too closely	Rear End	1	0	W	SH
0406/4040	Essex	5.52	1/14/1999	7:43	Unknown	Followed too closely	Rear End	0	0	W	SH
0406/13000-	Essex	5.53	11/1/2003	9:53	Cloudy	Followed too closely, No improper driving	Rear End	0	0		SH
0406/3692-02	Essex	5.59	4/19/2002	9:02	Clear	Inattention, No improper driving	Rear End	3	0	E	SH
0406/4274	Essex	5.6	1/22/1999	17:39	Sleet, Hail (Freezing Rain or	Failed to yield right of way		1	0	E	SH
0406/8416	Essex	5.6	3/14/2000	7:15	Unknown	Failed to yield right of way		1	0	E	SH
0406/10397	Essex	5.6	10/30/2000	12:23	Cloudy	Inattention	Rear End	1	0	W	SH
0406/11162	Essex	5.6	12/26/2000	10:36	Clear	Failed to yield right of way		0	0	E	SH
0406/12563	Essex	5.6	6/1/2001	16:35	Clear	Failed to yield right of way	Head On	0	0	E	SH
0406/13356	Essex	5.6	9/21/2001	17:17	Clear	Followed too closely	Rear End	0	0	W	SH
0406/10463-	Essex	5.6	6/24/2003	12:22	Clear	Unknown	No Turns, Thru moves only, Broadside ^<	1	0	E	SH
0406/13036-	Essex	5.6	10/28/2003	7:23	Clear	Exceeded authorized speed limit, Failed to yield right of way	Right Turn and Thru, Angle Broadside -->^--	0	0	E	SH
0406/5684	Essex	5.72	6/24/1999	8:45	Clear	Inattention	Rear End	0	0	W	SH
0406/14916-	Essex	6.34	12/8/2003	10:55	Clear	Inattention, Followed too closely, No improper driving	Head On	1	0	E	SH
0406/13698-	Essex	6.52	11/10/2003	14:57	Clear	Inattention, No improper driving	Rear End	2	0	E	SH
0406/13505	Essex	6.59	10/13/2001	14:41	Clear	Other improper action		1	0	W	SH
0406/12265	Essex	6.64	5/1/2001	6:38	Clear	Inattention	Rear End	0	0	W	SH
0406/10254	Essex	6.68	2/19/2000	11:45	Clear	Wrong side or wrong way		0	0	E	SH
0406/13769	Essex	6.75	10/16/2001	6:34	Clear	Other improper action		1	0	E	SH
0406/10626	Essex	6.87	11/2/2000	6:35	Clear	Followed too closely	Rear End	1	0	W	SH
0406/6422-03	Essex	6.87	5/21/2003	12:11	Cloudy	Other improper action, No improper driving	Same Direction Sideswipe	0	0	N	SH
0406/12988	Essex	6.9	7/27/2001	17:05	Clear	Failed to yield right of way		0	0	E	SH
0406/8666-02	Essex	6.96	9/23/2002	19:00	Clear	Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner	Single Vehicle Crash	1	0	E	SH
0406/14037-	Essex	7.1	11/16/2003	20:17	Clear	Unknown	No Turns, Thru moves only, Broadside ^<	0	0	W	SH
0406/13157-	Essex	7.27	9/3/2003	10:52	Clear	No improper driving, Operating defective equipment	Rear End	1	0	W	SH
0406/16368-	Essex	7.39	12/1/2003	13:20	Cloudy	Driving too fast for conditions	Single Vehicle Crash	0	0	W	SH
* 0406/5103	Essex	7.4	4/21/1999	13:24	Clear	Inattention		0	0	E	SH
* 0406/6480	Essex	7.4	8/13/1999	17:13	Clear	Other improper action	Head On	5	0	E	SH

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-15											
0406/9038	Essex	7.4	5/26/2000	16:49	Clear	Followed too closely, Inattention	Rear End	1	0	E	SH
0406/11265-	Essex	7.46	9/24/2003	17:58	Cloudy	Followed too closely, Unknown	Rear End	0	0		SH
0406/9742-02	Essex	7.48	10/20/2002	12:10	Rain	Followed too closely, No improper driving	Rear End	1	0	W	SH
* 0406/4152	Essex	7.92	1/25/1999	16:30	Unknown	Technology Related Distraction	Rear End	1	0	E	SH
0406/12874-	Essex	7.92	10/29/2003	15:13	Rain	No improper driving	Head On	1	0		SH
0406/16276-	Essex	8.02	12/22/2003	15:03	Cloudy	No improper driving, Followed too closely	Rear End	0	0	E	SH
0406/13767	Essex	8.03	11/18/2001	2:18	Clear	Technology Related Distraction		1	0	W	SH
0406/5970	Essex	UNK	1/14/1999	8:20	Clear	Followed too closely	Rear End	0	0	W	SH
0406/10625	Essex	UNK	5/20/2000	12:35	Cloudy	Inattention		1	0	E	SH
0406/12430	Essex	UNK	4/25/2001	16:26	Clear	Followed too closely	Rear End	2	0	W	SH
0406/13673-	Essex	UNK	11/27/2002	13:51	Clear	Followed too closely, No improper driving	Rear End	0	0	W	SH
0406/12328-	Essex	UNK	10/17/2003	16:16	Cloudy	Followed too closely, Inattention, Unknown	Rear End	0	0	E	SH

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Date Marker MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group	
Route: INDUSTRIAL AVE., WILLISTON											
0417/8390-02	Williston	0	9/11/2002	13:45	Rain	Inattention, No improper driving		2	0	N	FAU
0417/11465-	Williston	0	12/2/2002	8:37	Cloudy	Inattention, Followed too closely, No improper driving	Rear End	0	0	E	FAU
0414/13680-	Williston	0	11/12/2003	17:36	Cloudy	Followed too closely, No improper driving	Rear End	0	0	W	FAU
0417/11497-	Williston	0.1	10/23/2002	6:57	Clear	Inattention, No improper driving	Rear End	0	0	W	FAU
0414/4558-03	Williston	0.1	3/31/2003	17:27	Clear	Followed too closely, No improper driving	Rear End	0	0	E	FAU
0417/13544	Williston	0.13	10/13/2001	10:15	Clear	Failed to yield right of way, Operating defective equipment		0	0	E	FAU
0417/12030-	Williston	0.13	12/11/2002	13:18	Clear	Followed too closely, No improper driving	Rear End	0	0	E	FAU
0417/7072-03	Williston	0.13	6/1/2003	17:21	Clear	No improper driving, Inattention	Rear End	0	0	W	FAU
0417/7526-03	Williston	0.13	6/20/2003	8:52	Unknown	Followed too closely, Unknown	Rear End	1	0	E	FAU
0417/9890-02	Williston	0.28	10/21/2002	12:49	Cloudy	No improper driving, Visibility obstructed		0	0	E	FAU
0417/7105-03	Williston	0.52	6/11/2003	12:58	Cloudy	Followed too closely, No improper driving	Rear End	0	0	W	FAU
0417/6062	Williston	0.54	7/26/1999	17:15	Clear	Followed too closely	Rear End	0	0	E	FAU
0417/10283	Williston	0.54	7/1/2000	10:08	Clear	Failed to yield right of way		1	0	S	FAU
0417/13200	Williston	0.54	8/27/2001	17:18	Clear	Driving too fast for conditions	Rear End	0	0	E	FAU
0417/1288-03	Williston	0.6	1/7/2003	16:08	Clear	Failed to yield right of way, No improper driving	Left Turn and Thru, Angle Broadside -->v--	0	0	W	FAU
0417/15613-03	Williston	0.6	12/22/2003	10:16	Cloudy	Inattention, Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner, Unknown, No improper driving	Rear End	0	0	E	FAU
0417/14171	Williston	0.73	10/30/2001	16:10	Clear	Failed to yield right of way		1	0	E	FAU
0417/345-02	Williston	0.73	4/1/2002	9:19	Rain	Disregarded traffic signs, signals, road markings		1	0	N	FAU
0417/5951-02	Williston	0.73	7/1/2002	11:06	Clear	Other improper action, No improper driving	Rear End	3	0	W	FAU
0417/13385-	Williston	0.73	12/11/2002	11:20	Rain	Unknown	Single Vehicle Crash	0	0	E	FAU
0417/9159-03	Williston	0.73	7/30/2003	19:42	Clear	Other improper action	Single Vehicle Crash	0	0	N	FAU
0417/10655	Williston	0.76	11/15/2000	17:38	Cloudy	Driving too fast for conditions		1	0	E	FAU
0417/9925-02	Williston	0.77	10/27/2002	19:38	Cloudy	Exceeded authorized speed limit	Single Vehicle Crash	0	0	W	FAU
0417/2764-03	Williston	0.79	3/5/2003	17:58	Snow	No improper driving, Driving too fast for conditions	Opp Direction Sideswipe	1	0	E	FAU
0417/5979	Williston	0.83	8/25/1999	17:28	Clear	Other improper action		1	0	E	FAU
0417/5980	Williston	0.83	8/31/1999	20:18	Clear	Failure to keep in proper lane or running off road		1	0	W	FAU
0417/1627-03	Williston	0.95	1/18/2003	13:25	Clear	Followed too closely, No improper driving	Rear End	0	0	E	FAU
0417/5658-03	Williston	1.01	3/30/2003	17:36	Snow	No improper driving	Head On	0	0	E	FAU
0417/4581	Williston	1.05	2/26/1999	15:10	Clear	Operating defective equipment		0	0	E	FAU
0417/6452	Williston	UNK	8/18/1999	18:00	Clear	Failure to keep in proper lane or running off road		0	0	E	FAU
0417/5981	Williston	UNK	9/8/1999	17:45	Clear	Failed to yield right of way		1	0	E	FAU

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: MT. VIEW ROAD, WILLISTON											
0417/02WT0303	Williston	0	9/19/2002	17:25	Clear	Inattention, No improper driving	Rear End	0	0	E	FAU
0417/9691-03	Williston	0.01	8/12/2003	16:16	Clear	Unknown, No improper driving	Rear End	0	0	W	FAU
0417/3792-02	Williston	0.43	4/25/2002	16:16	Rain	Fatigued, asleep, Failure to keep in proper lane or running off road	Head On	1	0	W	FAU
0417/1723-03	Williston	0.44	2/12/2003	9:44	Cloudy	Driving too fast for conditions	Single Vehicle Crash	0	0	E	FAU
0417/13421	Williston	0.55	5/14/2001	14:37	Clear	Failed to yield right of way		1	0	E	FAU
0417/9721-03	Williston	0.61	8/14/2003	20:12	Clear	Exceeded authorized speed limit	Single Vehicle Crash	1	0	E	FAU
0417/14525-03	Williston	1.13	11/14/2003	16:08	Clear	Unknown	Single Vehicle Crash	0	0	W	FAU
0417/1925-03	Williston	UNK	2/22/2003	21:45	Sleet, Hail (Freezing Rain or	Driving too fast for conditions	Single Vehicle Crash	0	0	W	FAU
0417/13746-03	Williston	UNK	11/7/2003	12:48	Cloudy	No improper driving	Single Vehicle Crash	0	0		FAU

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: NO. WILLISTON ROAD, WILLISTON											
0417/10010-02	Williston	0	9/29/2002	17:36	Cloudy	Inattention, Failed to yield right of way	Same Direction Sideswipe	0	0	W	FAU
0417/10656	Williston	0.18	11/22/2000	6:54	Snow	Driving too fast for conditions	Head On	1	0	S	FAU
0417/971-03	Williston	0.51	1/29/2003	17:26	Snow	Driving too fast for conditions, No improper driving	Rear End	3	0	S	FAU
0417/12424-03	Williston	0.6	10/21/2003	6:35	Rain	Visibility obstructed, Distracted, No improper driving	Rear End	1	0	N	FAU
0417/7092	Williston	1	10/24/1999	16:15	Cloudy	Failed to yield right of way		0	0	E	FAU
0417/9886-02	Williston	1	10/12/2002	10:29	Cloudy	No improper driving, Failed to yield right of way, Inattention		1	0	S	FAU
0417/12287-02	Williston	1	10/23/2002	15:05	Clear	No improper driving, Failed to yield right of way	No Turns, Thru moves only, Broadside ^<	0	0	S	FAU
0417/11276-02	Williston	1	11/26/2002	11:19	Clear	Failed to yield right of way, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	E	FAU
0417/5660-03	Williston	1	4/19/2003	21:50	Clear	Unknown	No Turns, Thru moves only, Broadside ^<	0	0	N	FAU
0417/11651-03	Williston	1.04	9/26/2003	21:01	Cloudy	No improper driving	Head On	0	0	N	FAU
0417/10257	Williston	1.43	5/19/2000	15:45	Clear	Wrong side or wrong way		1	0	S	FAU
0417/7329-02	Williston	1.46	5/19/2002	3:33	Clear	Driving too fast for conditions, Under the influence of medication/druas/alcohol	Single Vehicle Crash	0	0	N	FAU
0418/4436-02	Williston	1.5	5/10/2002	16:34	Clear	No improper driving, Wrong side or wrong way		1	0	N	FAU
0417/4260-03	Williston	1.5	2/12/2003	13:47	Snow	Unknown	Left Turn and Thru, Same Direction Sideswipe/Angle Crash	0	0	N	FAU
0417/7489	Williston	1.8	12/1/1999	12:45	Clear	Inattention	vw-- Rear End	1	0	N	FAU
0417/8311	Williston	1.8	2/7/2000	16:45	Clear	Disregarded traffic signs, signals, road markings, Failed to yield right of way		2	0	E	FAU
0417/10886-02	Williston	1.8	10/25/2002	21:20	Clear	Exceeded authorized speed limit, Failure to keep in proper lane or running off road	Opp Direction Sideswipe	0	0	E	FAU
0417/14163-03	Williston	1.81	11/18/2003	15:10	Cloudy	Unknown	Single Vehicle Crash	0	0	S	FAU
0417/10657	Williston	2.19	1/21/2000	10:36	Unknown	Other improper action		0	0	N	FAU
0417/12055-02	Williston	2.21	2/8/2002	15:37	Clear	Driving too fast for conditions	Single Vehicle Crash	1	0	N	FAU
0417/10259	Williston	UNK	1/20/2000	13:31	Snow	Other improper action		0	0	N	FAU
0417/10956	Williston	UNK	12/14/2000	13:15	Snow	Other improper action		0	0	N	FAU
0417/02WT0362	Williston	UNK	11/7/2002	6:53	Snow	Unknown	Single Vehicle Crash	0	0	S	FAU
0417/14635-02	Williston	UNK	12/27/2002	12:54	Clear	Other improper action	Rear End	0	0		FAU

Route: NO. WILLISTON RD., ESSEX

0406/10591	Essex	0.34	11/7/2000	16:57	Cloudy	Other improper action	Rear End	2	0	N	FAU
------------	-------	------	-----------	-------	--------	-----------------------	----------	---	---	---	-----

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
 From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: VT-289											
0406/10101	Essex	0	8/26/2000	17:58	Clear	Operating defective equipment		3	0	W	Ramp/Spur
0406/10416	Essex	0	10/26/2000	9:45	Clear	Followed too closely	Rear End	0	0	W	Ramp/Spur
0406/11156-	Essex	0	9/18/2003	17:02	Other	Failure to keep in proper lane or running off road, Unknown	Rear End	0	0	N	Ramp/Spur
0406/13524	Essex	0.04	5/1/2001		Clear	Driving too fast for conditions		1	0	W	Ramp/Spur
0406/5482-02	Essex	0.27	6/23/2002	21:25	Cloudy	No improper driving, Followed too closely	Rear End	1	0	E	Ramp/Spur
0406/07-03	Essex	0.5	2/10/2003	14:08	Cloudy	No improper driving, Failure to keep in proper lane or running off road. Unknown	Opp Direction Sideswipe	0	1	E	Ramp/Spur
0406/13008	Essex	7.86	7/10/2001	16:14	Clear	Followed too closely	Rear End	0	0	W	SH
0406/4176	Essex	8	1/19/1999	19:33	Clear	Other improper action		0	0	E	SH
0406/8878	Essex	8	5/24/2000	23:17	Cloudy	Other improper action		1	0	W	SH
0406/13316	Essex	8.1	7/8/2001	9:56	Clear	Fatigued, asleep		2	0	W	SH
0406/4311	Essex	8.4	1/18/1999	5:46	Clear	Other improper action		0	0	W	SH
0406/65-2002	Essex	8.9	11/2/2002	18:06	Clear	Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner, Under the influence of medication/drugs/alcohol. No improper driving	Rear End	0	1	E	SH
0406/11493	Essex	9	1/19/2001	22:30	Snow	Made an improper turn		0	0	W	SH
0406/8264-03	Essex	9	5/31/2003	0:12	Clear	No improper driving	Single Vehicle Crash	0	0	W	SH
0406/14135	Essex	9.66	10/22/2001	12:25	Clear	Other improper action		0	0	W	SH
0406/6847	Essex	11	10/12/1999	15:30	Clear	Inattention		1	0	E	SH
0406/16189-	Essex	11.24	12/26/2003	16:24	Cloudy	Followed too closely, No improper driving	Rear End	0	0		SH
0406/5208	Essex	UNK	4/10/1999	17:19	Clear	Other improper action		0	0	W	SH
0406/9050	Essex	UNK	6/5/2000	19:28	Clear	Other improper action	Rear End	1	0	W	Ramp/Spur
0406/15483-	Essex	UNK	12/6/2003	15:18	Snow	No improper driving	Head On	0	0		SH

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Date Marker MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group	
Route: I-89											
0417/6443-03	Williston	0.01	5/1/2003	22:30	Cloudy	Failure to keep in proper lane or running off road, Under the influence of medication/drugs/alcohol	Single Vehicle Crash	0	0	N	Ramp/Spur
0417/7713-03	Williston	0.01	6/10/2003	18:44	Cloudy	Failure to keep in proper lane or running off road	Single Vehicle Crash	0	0	N	Ramp/Spur
0417/8407-02	Williston	0.16	9/18/2002	17:20	Clear	No improper driving, Followed too closely, Distracted	Rear End	0	0	N	Ramp/Spur
0417/8571-02	Williston	0.16	9/20/2002	2:15	Clear	Inattention, Followed too closely	Rear End	0	0	E	Ramp/Spur
0417/4535-03	Williston	0.17	3/27/2003	16:38	Clear	Inattention, No improper driving	Rear End	1	0	S	Ramp/Spur
0417/10462	Williston	0.19	11/21/2000	16:45	Snow	Followed too closely	Rear End	0	0	S	Ramp/Spur
0417/11190-03	Williston	0.19	9/23/2003	18:00	Rain	Followed too closely, No improper driving	Rear End	0	0	S	Ramp/Spur
0417/14186-03	Williston	0.19	11/22/2003	13:50	Cloudy	Followed too closely, No improper driving	Rear End	0	0	S	Ramp/Spur
0417/10286-03	Williston	0.21	8/8/2003	22:00	Clear	Followed too closely, No improper driving	Rear End	0	0	N	Ramp/Spur
0417/12513	Williston	0.25	4/30/2001	8:10	Clear	Inattention	Rear End	1	0	W	Ramp/Spur
0417/02M10286	Williston	0.25	7/15/2002	17:00	Clear	Inattention, No improper driving	Same Direction Sideswipe	0	0	W	Ramp/Spur
0417/3144-03	Williston	0.28	3/9/2003	11:40	Clear	Inattention, No improper driving	Rear End	0	0	W	Ramp/Spur
0417/5025-03	Williston	79.75	3/29/2003	14:40	Rain	Driving too fast for conditions	Single Vehicle Crash	1	0	S	SH
0417/4839-03	Williston	79.75	4/1/2003	18:11	Cloudy	Followed too closely, Technology Related Distraction	Single Vehicle Crash	0	0	S	SH
0417/8895	Williston	79.8	4/9/2000	11:45	Snow	Driving too fast for conditions, Other improper action	Rear End	0	0	S	SH
0417/1677-03	Williston	80	1/16/2003	8:15	Clear	Driving too fast for conditions	Single Vehicle Crash	0	0	S	SH
0414/14723-03	Williston	80	12/4/2003	7:18	Snow	Driving too fast for conditions, Visibility obstructed	Single Vehicle Crash	0	0	N	SH
0414/14724-03	Williston	80	12/4/2003	7:18	Clear	Driving too fast for conditions, Visibility obstructed	Single Vehicle Crash	0	0	N	SH
0417/11970-02	Williston	80.02	10/19/2002	4:18	Cloudy	Under the influence of medication/drugs/alcohol, Fatigued, asleep	Rear End	0	0	N	SH
0417/102389-02	Williston	80.04	6/12/2002	10:25	Rain	Swerving or avoiding due to wind, slippery surface, vehicle, object. non-motorist in roadway etc	Single Vehicle Crash	0	0	S	SH
0417/10185	Williston	80.05	6/28/2000	4:05	Clear	Driving too fast for conditions, Other improper action		1	0	S	SH
0417/11226-02	Williston	80.25	11/29/2002	5:35	Snow	Driving too fast for conditions	Single Vehicle Crash	0	0	N	SH
0417/8496	Williston	80.35	3/16/2000	22:40	Sleet, Hail (Freezing Rain or	Driving too fast for conditions		0	0	N	SH
0417/11230-02	Williston	80.75	11/29/2002	5:40	Snow	Driving too fast for conditions	Single Vehicle Crash	0	0	N	SH
0417/02A104306	Williston	81	12/22/2002	14:24	Clear	Followed too closely, No improper driving	Rear End	0	0	S	SH
0417/12532-02	Williston	81	12/23/2002	22:15	Snow	Driving too fast for conditions	Single Vehicle Crash	0	0	S	SH
0417/9051-02	Williston	81.02	9/2/2002	19:18	Clear	Failure to keep in proper lane or running off road	Single Vehicle Crash	0	0	S	SH
0417/11320-03	Williston	81.21	9/22/2003	17:00	Clear	Made an improper turn, No improper driving	Same Direction Sideswipe	0	0	N	SH
0417/6962-03	Williston	81.28	6/5/2003	12:43	Cloudy	Swerving or avoiding due to wind, slippery surface, vehicle, object. non-motorist in roadway etc. Unknown	Single Vehicle Crash	1	0	N	SH
1211/4380-02	Williston	81.73	5/13/2002	7:27	Rain	Inattention	Head On	0	0		SH
0417/10139-03	Williston	81.75	8/22/2003	17:19	Clear	Fatigued, asleep, Exceeded authorized speed limit, No improper driving	Rear End	3	0	N	SH
0417/12557-02	Williston	81.8	11/17/2002	7:45	Sleet, Hail (Freezing Rain or	Driving too fast for conditions	Single Vehicle Crash	2	0	S	SH
0417/17597-03	Williston	81.8	1/26/2003	18:40	Snow	Driving too fast for conditions	Single Vehicle Crash	0	0	N	SH
0417/12222	Williston	82	4/28/2001	12:41	Clear	Exceeded authorized speed limit, Other improper action		1	0	N	SH

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Date Marker MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group	
Route: I-89											
0411/17541-03	Williston	82	1/16/2003	6:45	Snow	Unknown	Single Vehicle Crash	0	0	N	SH
0417/9984-03	Williston	82	7/25/2003	7:14	Clear	Followed too closely, No improper driving	Rear End	0	0	S	SH
0417/12414-03	Williston	82	10/19/2003	5:45	Clear	Fatigued, asleep	Single Vehicle Crash	0	0	S	SH
0417/8967-03	Williston	82.22	7/23/2003	10:20	Rain	Driving too fast for conditions, No improper driving	Same Direction Sideswipe	2	0	N	SH
0417/12560-02	Williston	82.24	11/9/2002	21:25	Cloudy	No improper driving	Single Vehicle Crash	0	0	S	SH
0417/8359-02	Williston	82.6	9/2/2002	18:17	Clear	Swerving or avoiding due to wind, slippery surface, vehicle, object, non-motorist in roadway etc, Followed too closely, No improper driving	Head On	4	0	N	SH
0417/103192-02	Williston	83	8/6/2002	15:35	Clear	Driving too fast for conditions, Operating vehicle in erratic, reckless, careless, negligent, or aggressive manner, No improper driving	Rear End	0	0	N	SH
0417/4813-03	Williston	83	4/3/2003	15:56	Snow	Driving too fast for conditions, No improper driving	Same Direction Sideswipe	0	0	N	SH
0417/7157-03	Williston	83.25	5/16/2003	16:00	Clear	Fatigued, asleep, No improper driving	Rear End	0	0	S	SH
0417/12572-02	Williston	83.41	11/18/2002	9:30	Cloudy	Driving too fast for conditions	Single Vehicle Crash	0	0	N	SH
0417/7308	Williston	83.45	11/2/1999	2:30	Cloudy	Other improper action		0	0	N	SH
0417/02A105213	Williston	83.5	12/26/2002	9:40	Cloudy	Other improper action	Single Vehicle Crash	0	0	S	SH
0417/6266-03	Williston	83.5	4/24/2003	21:13	Cloudy	No improper driving	Single Vehicle Crash	0	0	N	SH
0417/10798-03	Williston	83.5	9/12/2003	10:00	Clear	Failure to keep in proper lane or running off road, No improper driving	Same Direction Sideswipe	0	0	N	SH
0417/10885	Williston	83.55	12/5/2000		Snow	Other improper action		0	0	N	SH
0411/9254-03	Williston	83.55	7/13/2003	16:00	Cloudy	Technology Related Distraction, Inattention	Single Vehicle Crash	2	0	S	SH
0417/11969-02	Williston	83.63	10/19/2002	6:00	Rain	Driving too fast for conditions	Rear End	0	0	S	SH
0417/8814-02	Williston	83.96	10/6/2002	16:50	Clear	Other improper action	Single Vehicle Crash	0	0	N	SH
0417/8798-03	Williston	84	7/21/2003	12:18	Cloudy	Made an improper turn, Failure to keep in proper lane or running off road, No improper driving	Left Turn and Thru, Head On ^v--	1	0	N	SH
0417/8543	Williston	84.65	4/20/2000	8:10	Clear	Other improper action	Same Direction Sideswipe	1	0	N	SH
0417/8726-02	Williston	84.92	10/2/2002	15:43	Clear	Swerving or avoiding due to wind, slippery surface, vehicle, object, non-motorist in roadway etc, Failure to keep in proper lane or running off road	Single Vehicle Crash	0	0	N	SH
0417/13140-02	Williston	85	12/24/2002	15:37	Clear	Failure to keep in proper lane or running off road, Inattention	Single Vehicle Crash	0	0	N	SH
0417/6550	Williston	UNK	9/24/1999	17:20	Clear	Other improper action		1	0	S	SH
0417/8896	Williston	UNK	5/7/2000	10:17	Unknown	Other improper action	Rear End	7	0	E	SH
0417/9713	Williston	UNK	8/18/2000	9:26	Clear	Other improper action	Rear End	0	0	N	SH
0417/12107	Williston	UNK	3/25/2001	21:00	Cloudy	Other improper action		0	0	S	SH
0417/12512	Williston	UNK	5/11/2001	14:53	Unknown	Technology Related Distraction	Same Direction Sideswipe	0	0	S	SH
0417/7573-02	Williston	UNK	7/22/2002	0:50	Cloudy	No improper driving	Head On	0	0	N	SH
0411/7538-02	Williston	UNK	7/28/2002	21:42	Cloudy	Driving too fast for conditions	Single Vehicle Crash	2	0	N	SH
0417/72140-02	Williston	UNK	8/13/2002	23:12	Clear	No improper driving, Followed too closely	Rear End	0	0	N	SH
0417/9568-02	Williston	UNK	9/12/2002	15:50	Clear	Inattention, No improper driving	Rear End	1	0	N	Ramp/Spur

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Date Marker MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: I-89										
0417/8758-02	Williston	UNK	10/3/2002	19:00	Clear	No improper driving	0	0	N	SH
0417/1040-03	Williston	UNK	1/3/2003	2:10	Clear	Inattention	0	0	N	SH
0417/1914-03	Williston	UNK	1/26/2003	15:31	Snow	Driving too fast for conditions	1	0	S	SH
0417/4526-03	Williston	UNK	3/30/2003	17:30	Snow	Driving too fast for conditions	1	0	N	SH
0417/5161-03	Williston	UNK	4/5/2003	2:14	Snow	Driving too fast for conditions	0	0	N	SH
0417/7707-03	Williston	UNK	5/16/2003	20:49	Clear	No improper driving	0	0	S	SH
0417/8487-03	Williston	UNK	7/13/2003	3:16	Clear	No improper driving	0	0	N	SH

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation
General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems
From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/		Mile Date		Time	Weather	Contributing Circumstances	Direction Of Collision	Number	Number	Road
* Number	Town	Marker	MM/DD/YY					Of Injuries	Of Fatalities	
Route: MARSHALL AVE., WILLISTON										
0417/11864-	Williston	0.34	10/9/2003	12:54	Clear	Failed to yield right of way, No improper driving	Opp Direction Sideswipe	2	0	E FAU
0417/9693-02	Williston	0.48	9/20/2002	15:48	Cloudy	Inattention, No improper driving		0	0	W FAU
0417/11822-	Williston	0.54	12/8/2002	13:47	Snow	No improper driving	Single Vehicle Crash	0	0	E FAU
0417/2966-03	Williston	0.58	1/24/2003	13:38	Clear	No improper driving, Failed to yield right of way	Left Turn and Thru, Angle Broadside -->v--	0	0	E FAU
0417/10544-	Williston	0.68	10/1/2002	15:30	Cloudy	Inattention	Rear End	0	0	FAU
0417/5314-03	Williston	0.73	4/19/2003	15:06	Cloudy	No improper driving, Failed to yield right of way, Made an improper turn	Rear-to-rear	0	0	E FAU
0417/8058-03	Williston	0.73	7/2/2003	15:17	Clear	Inattention, No improper driving	Rear End	0	0	E FAU
0417/13867-	Williston	0.73	11/15/2003	13:02	Clear	Visibility obstructed, No improper driving	Rear End	0	0	W FAU
0417/15534-03	Williston	0.73	12/17/2003	18:52	Snow	No improper driving, Driving too fast for conditions, Inattention	Head On	0	0	E FAU
0417/15547-03	Williston	0.73	12/18/2003	17:37	Snow	Failed to yield right of way, Visibility obstructed, No improper driving	Left Turn and Thru, Angle Broadside -->v--	0	0	S FAU
0417/12340-	Williston	0.85	10/8/2003	18:26	Clear	Inattention, No improper driving	Rear End	0	0	N FAU
0417/6949-03	Williston	1.11	6/4/2003	7:25	Clear	No improper driving, Visibility obstructed, Driving too fast for conditions	Left Turn and Thru, Angle Broadside -->v--	0	0	N FAU
0417/10834-	Williston	1.11	9/12/2003	9:56	Cloudy	No improper driving, Failed to yield right of way, Inattention	Left Turn and Thru, Angle Broadside -->v--	1	0	E FAU
0417/2932-03	Williston	1.3	1/23/2003	13:49	Cloudy	No improper driving	Rear End	0	0	W FAU
0417/3299-03	Williston	1.3	1/31/2003	17:29	Clear	Unknown	Rear End	0	0	E FAU
0417/5826-03	Williston	1.3	5/7/2003	17:01	Clear	Inattention, Driving too fast for conditions, No improper driving	Rear End	1	0	E FAU
0417/18164-	Williston	1.3	5/7/2003	20:43	Cloudy	Other improper action, No improper driving	Rear End	0	0	FAU
0417/15309-03	Williston	1.3	12/9/2003	11:39	Clear	Disregarded traffic signs, signals, road markings, Inattention, No improper driving	Left Turn and Thru, Broadside v<--	0	0	E FAU
0417/11137-	Williston	1.4	9/15/2003	17:29	Cloudy	Distracted, No improper driving	Rear End	0	0	FAU
0417/9896-02	Williston	1.41	10/23/2002	18:40	Cloudy	Visibility obstructed, Other improper action	Rear End	0	0	E FAU
0417/2589-03	Williston	1.43	3/3/2003	10:25	Clear	No improper driving, Failed to yield right of way	Right Turn and Thru, Same Direction Sideswipe/Angle Crash ^^--	0	0	E FAU
0417/13208-	Williston	1.45	10/24/2003	11:20	Cloudy	Followed too closely, Inattention, No improper driving	Rear End	0	0	W FAU
0411/18152-	Williston	1.57	5/29/2003	17:17	Cloudy	Distracted, Inattention, No improper driving	Rear End	0	0	E FAU
0417/10725-	Williston	1.57	9/5/2003	12:21	Cloudy	No improper driving, Made an improper turn	Head On	0	0	N FAU
0417/11100-	Williston	1.57	9/20/2003	13:11	Clear	Inattention, No improper driving	Rear End	1	0	E FAU
0417/8330	Williston	UNK	2/16/2000	10:28	Other	Other improper action	Head On	1	0	E FAU
0417/9043	Williston	UNK	5/19/2000	16:50	Clear	Inattention	Rear End	1	0	E FAU
0417/10433	Williston	UNK	10/13/2000	12:37	Clear	Failed to yield right of way		2	0	E FAU
0417/10432	Williston	UNK	11/6/2000	9:30	Cloudy	Inattention		0	0	E FAU
0417/13036	Williston	UNK	8/9/2001	10:18	Clear	Made an improper turn		1	0	W FAU
0417/14104-	Williston	UNK	12/31/2002	13:49	Clear	No improper driving, Failed to yield right of way	Left Turn and Thru, Angle Broadside -->v--	0	0	E FAU

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

Vermont Agency of Transportation

General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems

From 01/01/99 To 12/31/03 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Marker	Mile Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Direction	Road Group
Route: WEST ST., ESSEX JUNCTION VILLAGE											
0406/737-03	Essex	0	1/24/2003	8:30	Clear	Failed to yield right of way, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	S	FAU
0406/5978	Essex	0.14	6/5/1999	11:30	Clear	Inattention	Rear End	1	0	E	FAU
0406/6293	Essex	0.47	8/23/1999	6:40	Unknown	Failed to yield right of way		1	0	E	FAU
0406/7877-03	Essex	0.47	6/9/2003	13:14	Not Reported	Under the influence of medication/drugs/alcohol, No improper driving		0	0	W	FAU

Note: THIS DOCUMENT IS EXEMPT FROM DISCOVERY OR ADMISSION UNDER 23 U.S.C 409.

**Crash Analysis for Major Intersections
(from 01/01/99 to 12/31/2003)**

No.	Intersections	Town	Functional Classification	5-Year Crashes	2001 AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
1	VT2A/I-89 SB Off Ramp	Williston	I(u)/PA(u)	16	19,275	0.455	0.205	ABOVE	0.388	1.17	HCL
2	VT2A/I-89 NB Off Ramp	Williston	I(u)/PA(u)	8	21,050	0.208	0.205	ABOVE	0.380	0.55	-
3	VT2A/Marshall Ave./Maple Treee Place	Williston	PA(u)/UC(u)	31	30,150	0.563	0.232	ABOVE	0.390	1.44	HCL
4	VT2A/US2	Williston	PA(u)/PA(u)	41	27,800	0.808	0.258	ABOVE	0.432	1.87	HCL
5	VT2A/Industrial Ave./Mountain View Rd.	Williston	MinA(u)/UC(u)	13	25,325	0.281	0.240	ABOVE	0.415	0.68	-
6	VT2A/South Street	Essex	MinA(u)/UC(u)	1	23,600	0.023	0.240	BELOW	0.421	0.06	-
7	VT2A/VT15/VT117	Essex	MinA(u)/PA(u)	9	29,100	0.169	0.418	BELOW	0.637	0.27	-
8	VT2A/VT289/Susie Wilson Rd.	Essex	MinA(u)/UC(u)	13	21,575	0.330	0.240	ABOVE	0.429	0.77	-
9	VT2A/VT289 WB Off Ramp	Essex	F(u)/MinA(u)	4	19,600	0.112	0.285	BELOW	0.501	0.22	-
10	VT15/VT289 EB Ramp A/VT 289 EB Ramp B	Essex	F(u)/PA(u)	5	18,465	0.148	0.205	BELOW	0.391	0.38	-
11	VT15/VT289 WB Ramp C/VT 289 WB Ramp D	Essex	F(u)/PA(u)	4	17,660	0.124	0.205	BELOW	0.395	0.31	-
12	VT 117/VT289 EB Off Ramp D	Essex	F(u)/PA(u)	2	12,475	0.088	0.205	BELOW	0.428	0.21	-
13	VT 117/VT289 WB OnRamp B	Essex	F(u)/PA(u)	1	12,875	0.043	0.205	BELOW	0.425	0.10	-
14	US2/Industrial Ave.	Williston	PA(u)/UC(u)	13	20,550	0.347	0.232	ABOVE	0.422	0.82	-
15	US2/Brownell Rd.	Williston	PA(u)/UC(u)	6	17,975	0.183	0.232	BELOW	0.434	0.42	-
16	US2/Old Stage Rd.	Williston	MinA(u)/UC (u)	4	11,900	0.184	0.240	BELOW	0.488	0.38	-
17	US2/N. Williston Rd./Oak Hill Rd.	Williston	MinA(u)/UC(u)	14	11,325	0.677	0.240	ABOVE	0.494	1.37	HCL
18	VT117/Sand Hill Rd.	Essex	PA(u)/UC(u)	6	9,850	0.334	0.232	ABOVE	0.497	0.67	-
19	VT117/N. Williston Rd.	Essex	PA(u)/UC(u)	6	8,850	0.371	0.232	ABOVE	0.510	0.73	-
20	VT15/Susie Wilson Rd.	Essex	PA(u)/UC(u)	16	33,750	0.260	0.232	ABOVE	0.382	0.68	-
21	VT15/West St.	Essex	PA(u)/UC(u)	2	21,700	0.051	0.232	BELOW	0.417	0.12	-
22	VT15/Old Stage Rd.	Essex	PA(u)/UC(u)	4	15,525	0.141	0.232	BELOW	0.448	0.32	-
23	VT15/VT128/Towers Rd.	Essex	PA(u)/UC(u)	2	17,200	0.064	0.232	BELOW	0.438	0.15	-
24	VT15/Sand Hill Rd.	Essex	PA(u)/UC(u)	9	14,525	0.340	0.232	ABOVE	0.455	0.75	-

**Accident Rates (from 01/01/99 to 12/31/2003)
VT2A in Williston
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1		0										
	0.1	0.2		0										
1	0.0	0.3		0	0	0.3	7,850	7,850	0.0000	1.4338	BELOW	2.8076	0.00	-
2	0.1	0.4		1	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
3	0.2	0.5		0	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
4	0.3	0.6		0	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
5	0.4	0.7		0	0	0.3	7,850	7,850	0.0000	1.4338	BELOW	2.8076	0.00	-
6	0.5	0.8		0	0	0.3	7,850	7,850	0.0000	1.4338	BELOW	2.8076	0.00	-
7	0.6	0.9		1	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
8	0.7	1.0		2	3	0.3	7,850	7,850	0.6980	1.4338	BELOW	2.8076	0.25	-
9	0.8	1.1		1	4	0.3	7,850	7,850	0.9307	1.4338	BELOW	2.8076	0.33	-
10	0.9	1.2		0	3	0.3	7,850	7,850	0.6980	1.4338	BELOW	2.8076	0.25	-
11	1.0	1.3		0	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
12	1.1	1.4		1	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
13	1.2	1.5		0	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
14	1.3	1.6		0	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
15	1.4	1.7		1	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
16	1.5	1.8		0	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
17	1.6	1.9		1	2	0.3	7,850	7,850	0.4653	1.4338	BELOW	2.8076	0.17	-
18	1.7	2.0		1	2	0.3	7,850	7,850	0.4653	1.4338	BELOW	2.8076	0.17	-
19	1.8	2.1		0	2	0.3	7,850	7,850	0.4653	1.4338	BELOW	2.8076	0.17	-
20	1.9	2.2		1	2	0.3	7,850	7,850	0.4653	1.4338	BELOW	2.8076	0.17	-
21	2.0	2.3		0	1	0.3	7,850	7,850	0.2327	1.4338	BELOW	2.8076	0.08	-
22	2.1	2.4		3	4	0.3	7,850	7,850	0.9307	1.4338	BELOW	2.8076	0.33	-
23	2.2	2.5		1	4	0.3	7,850	7,850	0.9307	1.4338	BELOW	2.8076	0.33	-
24	2.3	2.6		2	6	0.3	7,850	7,850	1.3960	1.4338	BELOW	2.8076	0.50	-
25	2.4	2.7		1	4	0.3	7,850	7,850	0.9307	1.4338	BELOW	2.8076	0.33	-
26	2.5	2.8		1	4	0.3	10,675	8,792	0.8310	1.4338	BELOW	2.7380	0.30	-
27	2.6	2.9	I 89 SB Off Ramp/Hurricane Lane	2	4	0.3	10,675	9,733	0.7506	1.4338	BELOW	2.6782	0.28	-
28	2.7	3.0	I 89 NB Off Ramp	8	11	0.3	13,500	11,617	1.7295	1.4338	ABOVE	2.5802	0.67	-
29	2.8	3.1		7	17	0.3	13,500	12,558	2.4725	1.7787	ABOVE	3.0182	0.82	-
30	2.9	3.2		10	25	0.3	17,250	14,750	3.0957	1.7787	ABOVE	2.9276	1.06	HCL
31	3.0	3.3		6	23	0.3	21,000	17,250	2.4353	1.7787	ABOVE	2.8454	0.86	-
32	3.1	3.4	Marshall Ave./Maple Tree Place	35	51	0.3	22,500	20,250	4.6000	1.7787	ABOVE	2.7670	1.66	HCL
33	3.2	3.5	Bishop Ave	2	43	0.3	22,500	22,000	3.5699	1.7787	ABOVE	2.7286	1.31	HCL
34	3.3	3.6	Conner Way	3	40	0.3	22,500	22,500	3.2471	1.7787	ABOVE	2.7185	1.19	HCL
35	3.4	3.7		1	6	0.3	22,500	22,500	0.4871	1.7787	BELOW	2.7185	0.18	-
36	3.5	3.8	US 2	22	26	0.3	22,500	22,500	2.1106	1.4338	ABOVE	2.2734	0.93	-
37	3.6	3.9	Helena Drive	9	32	0.3	18,075	21,025	2.7799	1.4338	ABOVE	2.3009	1.21	HCL
38	3.7	4.0	Paul St/Zephyr Road	1	32	0.3	18,075	19,550	2.9896	1.4338	ABOVE	2.3314	1.28	HCL
39	3.8	4.1		1	11	0.3	18,075	18,075	1.1116	1.4338	BELOW	2.3653	0.47	-
40	3.9	4.2	Knight Lane	1	3	0.3	18,075	18,075	0.3032	1.4338	BELOW	2.3653	0.13	-
41	4.0	4.3	Obrient Ct.	2	4	0.3	18,075	18,075	0.4042	1.4338	BELOW	2.3653	0.17	-
42	4.1	4.4	Beaudry Ln/Hideaway Ln	2	5	0.3	13,650	16,600	0.5501	1.4338	BELOW	2.4035	0.23	-
43	4.2	4.5	Pincrest Cir	3	7	0.3	13,650	15,125	0.8453	1.4338	BELOW	2.4470	0.35	-
44	4.3	4.6		6	11	0.3	13,650	13,650	1.4719	1.4338	ABOVE	2.4970	0.59	-
45	4.4	4.7	Meadowrun Rd/Country Ln	3	12	0.3	13,650	13,650	1.6057	1.4338	ABOVE	2.4970	0.64	-
46	4.5	4.8	Industrial Ave./Mountain View Rd.	12	21	0.3	13,650	13,650	2.8100	1.4338	ABOVE	2.4970	1.13	HCL
47	4.6	4.9		1	16	0.3	13,650	13,650	2.1409	1.4338	ABOVE	2.4970	0.86	-

**Accident Rates (from 01/01/99 to 12/31/2003)
VT2A in Williston
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
48	4.7	5.0	Sharon Drive	6	19	0.3	13,650	13,650	2.5424	1.4338	ABOVE	2.4970	1.02	HCL
49	4.8	5.1	Hillside Drive	3	10	0.3	13,650	13,650	1.3381	1.4338	BELOW	2.4970	0.54	-
50	4.9	5.2	Bitter Sweet Cir	2	11	0.3	16,175	14,492	1.3864	1.4338	BELOW	2.4675	0.56	-
51	5.0	5.3		1	6	0.3	16,175	15,333	0.7147	1.4338	BELOW	2.4405	0.29	-
52	5.1	5.4	River Cove Road	3	6	0.3	16,175	16,175	0.6775	1.4338	BELOW	2.4155	0.28	-
53	5.2	5.5	Morgan Parkway	4	8	0.3	16,175	16,175	0.9034	1.4338	BELOW	2.4155	0.37	-
54	5.3	5.6	James Brown Drive	12	19	0.3	18,700	17,017	2.0394	1.4338	ABOVE	2.3923	0.85	-
55	5.4	5.7	Eastview Cir	4	20	0.3	18,700	17,858	2.0455	1.4338	ABOVE	2.3706	0.86	-
56	5.5	5.8		0	16	0.3	18,700	18,700	1.5628	1.4338	ABOVE	2.3505	0.66	-
57	5.6	5.9		0	4	0.3	18,700	18,700	0.3907	1.4338	BELOW	2.3505	0.17	-
58	5.7	6.0	Town Line	2	2	0.3	18,700	18,700	0.1953	1.4338	BELOW	2.3505	0.08	-
Unknow				8										
Total		6.0		200	200	6.0	12,985	12,798	1.4272	1.4338	BELOW	1.6912	0.84	-

**Accident Rates (from 01/01/99 to 12/31/2003)
VT2A in Essex
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1	Cascade Street	0	2	0.3	18,800	18800	0.1943	1.4338	BELOW	2.3481	0.08	-
	0.1	0.2	Mill Street	2	4	0.3	18,800	18800	0.3886	1.4338	BELOW	2.3481	0.17	-
1	0.0	0.3	South Street/River Street	1	3	0.3	18,800	18,800	0.2915	1.4338	BELOW	2.3481	0.12	-
2	0.1	0.4	Silver Bow Ter	4	7	0.3	18,800	18,800	0.6801	1.4338	BELOW	2.3481	0.29	-
3	0.2	0.5	Iroquois Ave/Railroad	5	10	0.3	16,700	17,750	1.0290	1.4338	BELOW	2.3733	0.43	-
4	0.3	0.6	Railroad	5	14	0.3	16,700	17,400	1.4696	1.4338	ABOVE	2.3822	0.62	-
5	0.4	0.7	Park Ter/Five Corners	12	22	0.3	16,700	16,700	2.4061	1.4338	ABOVE	2.4008	1.00	HCL
6	0.5	0.8		1	18	0.3	12,175	15,192	2.1641	1.4338	ABOVE	2.4449	0.89	-
7	0.6	0.9	Central Street	2	15	0.3	7,650	12,175	2.2503	1.4338	ABOVE	2.5554	0.88	-
8	0.7	1.0	Prospect Street	1	4	0.3	7,650	9,158	0.7977	1.4338	BELOW	2.7137	0.29	-
9	0.8	1.1		1	4	0.3	7,650	7,650	0.9550	1.4338	BELOW	2.8240	0.34	-
10	0.9	1.2	St. James Place	2	4	0.3	7,650	7,650	0.9550	1.4338	BELOW	2.8240	0.34	-
11	1.0	1.3		0	3	0.3	7,650	7,650	0.7163	1.4338	BELOW	2.8240	0.25	-
12	1.1	1.4		0	2	0.3	7,525	7,608	0.4801	1.4338	BELOW	2.8274	0.17	-
13	1.2	1.5		0	0	0.3	7,525	7,567	0.0000	1.4338	BELOW	2.8309	0.00	-
14	1.3	1.6		0	0	0.3	7,525	7,525	0.0000	1.4338	BELOW	2.8345	0.00	-
15	1.4	1.7		0	0	0.3	7,400	7,483	0.0000	1.4338	BELOW	2.8380	0.00	-
16	1.5	1.8		0	0	0.3	7,400	7,442	0.0000	1.4338	BELOW	2.8416	0.00	-
17	1.6	1.9	Pinecrest Dr.	8	8	0.3	7,400	7,400	1.9746	1.4338	ABOVE	2.8452	0.69	-
18	1.7	2.0		0	8	0.3	7,400	7,400	1.9746	1.4338	ABOVE	2.8452	0.69	-
19	1.8	2.1		0	8	0.3	7,400	7,400	1.9746	1.4338	ABOVE	2.8452	0.69	-
20	1.9	2.2		0	0	0.3	7,150	7,317	0.0000	1.4338	BELOW	2.8525	0.00	-
21	2.0	2.3		0	0	0.3	7,150	7,233	0.0000	1.4338	BELOW	2.8599	0.00	-
22	2.1	2.4		0	0	0.3	6,900	7,067	0.0000	1.4338	BELOW	2.8752	0.00	-
23	2.2	2.5	VT289/Susie Willson Rd.	7	7	0.3	6,900	6,983	1.8308	1.4338	ABOVE	2.8830	0.64	-
24	2.3	2.6		1	8	0.3	11,075	8,292	1.7622	1.4338	ABOVE	2.7736	0.64	-
25	2.4	2.7	VT289 WB Off Ramp	4	12	0.3	15,250	11,075	1.9790	1.4338	ABOVE	2.6059	0.76	-
26	2.5	2.8		6	11	0.3	12,800	13,042	1.5405	1.4338	ABOVE	2.5199	0.61	-
27	2.6	2.9		0	10	0.3	10,350	12,800	1.4269	1.4338	BELOW	2.5294	0.56	-
28	2.7	3.0		2	8	0.3	10,350	11,167	1.3085	1.4338	BELOW	2.6014	0.50	-
29	2.8	3.1		2	4	0.3	10,350	10,350	0.7059	1.4338	BELOW	2.6433	0.27	-
30	2.9	3.2		0	4	0.3	10,350	10,350	0.7059	1.4338	BELOW	2.6433	0.27	-
31	3.0	3.3		0	2	0.3	10,350	10,350	0.3529	1.4338	BELOW	2.6433	0.13	-
32	3.1	3.4		0	0	0.3	10,350	10,350	0.0000	1.4338	BELOW	2.6433	0.00	-
33	3.2	3.5		2	2	0.3	10,350	10,350	0.3529	1.4338	BELOW	2.6433	0.13	-
Unknown				2										
Total		3.5		70	70	3.5	10,223	10,469	1.0468	1.4338	BELOW	1.8041	0.58	-

**Accident Rates (from 01/01/99 to 12/31/2003)
US 2 in Williston
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1		3										
	0.1	0.2		1										
1	0.0	0.3	Industrial Avenue	10	14	0.3	19,900	19,900	1.2850	1.7787	BELOW	2.7753	0.46	-
2	0.1	0.4		1	12	0.3	15,400	15,400	1.4232	1.7787	BELOW	2.9044	0.49	-
3	0.2	0.5	Munson Way	0	11	0.3	10,900	13,150	1.5279	1.7787	BELOW	2.9916	0.51	-
4	0.3	0.6	Chad Ln.	1	2	0.3	10,900	12,400	0.2946	1.7787	BELOW	3.0256	0.10	-
5	0.4	0.7	Brownell Rd.	1	2	0.3	11,325	11,042	0.3308	1.7787	BELOW	3.0955	0.11	-
6	0.5	0.8		7	9	0.3	11,750	11,325	1.4515	1.7787	BELOW	3.0799	0.47	-
7	0.6	0.9	Commerce St.	2	10	0.3	11,750	11,608	1.5734	1.7787	BELOW	3.0649	0.51	-
8	0.7	1.0		1	10	0.3	11,750	11,750	1.5545	1.7787	BELOW	3.0576	0.51	-
9	0.8	1.1	Blair Park Rd.	5	8	0.3	11,350	11,617	1.2578	1.7787	BELOW	3.0645	0.41	-
10	0.9	1.2		0	6	0.3	10,950	11,350	0.9655	1.7787	BELOW	3.0786	0.31	-
11	1.0	1.3		2	7	0.3	10,950	11,083	1.1536	1.7787	BELOW	3.0931	0.37	-
12	1.1	1.4	Helena Dr.	8	10	0.3	10,950	10,950	1.6680	1.7787	BELOW	3.1006	0.54	-
13	1.2	1.5	VT 2A	42	52	0.3	10,950	10,950	8.6737	1.7787	ABOVE	3.1006	2.80	HCL
14	1.3	1.6	Boxwood St.	4	54	0.3	10,950	10,950	9.0073	1.4338	ABOVE	2.6121	3.45	HCL
15	1.4	1.7	Maple Tree Pl./Tafts Corner Shopping Center Dr.	4	50	0.3	10,950	10,950	8.3401	1.4338	ABOVE	2.6121	3.19	HCL
16	1.5	1.8	Talcott Rd. West	2	10	0.3	10,950	10,950	1.6680	1.4338	ABOVE	2.6121	0.64	-
17	1.6	1.9		0	6	0.3	10,950	10,950	1.0008	1.4338	BELOW	2.6121	0.38	-
18	1.7	2.0	Talcott Rd. East	0	2	0.3	10,950	10,950	0.3336	1.4338	BELOW	2.6121	0.13	-
19	1.8	2.1		2	2	0.3	10,950	10,950	0.3336	1.4338	BELOW	2.6121	0.13	-
20	1.9	2.2		0	2	0.3	10,950	10,950	0.3336	1.4338	BELOW	2.6121	0.13	-
21	2.0	2.3		0	2	0.3	10,950	10,950	0.3336	1.4338	BELOW	2.6121	0.13	-
22	2.1	2.4		1	1	0.3	10,950	10,950	0.1668	1.4338	BELOW	2.6121	0.06	-
23	2.2	2.5		0	1	0.3	10,950	10,950	0.1668	1.4338	BELOW	2.6121	0.06	-
24	2.3	2.6	Timothy Way	1	2	0.3	10,950	10,950	0.3336	1.4338	BELOW	2.6121	0.13	-
25	2.4	2.7	Southridge Rd.	2	3	0.3	10,950	10,950	0.5004	1.4338	BELOW	2.6121	0.19	-
26	2.5	2.8		2	5	0.3	7,375	9,758	0.9359	1.4338	BELOW	2.6768	0.35	-
27	2.6	2.9		0	4	0.3	7,375	8,567	0.8528	1.4338	BELOW	2.7537	0.31	-
28	2.7	3.0		1	3	0.3	7,375	7,375	0.7430	1.4338	BELOW	2.8474	0.26	-
29	2.8	3.1		1	2	0.3	7,375	7,375	0.4953	1.4338	BELOW	2.8474	0.17	-
30	2.9	3.2	Old Stage Rd.	3	5	0.3	7,375	7,375	1.2383	1.4338	BELOW	2.8474	0.43	-
31	3.0	3.3	Maple Rd./Whitney Hill Rd.	0	4	0.3	7,375	7,375	0.9906	1.4338	BELOW	2.8474	0.35	-
32	3.1	3.4	Central School Dr.	3	6	0.3	7,375	7,375	1.4860	1.4338	ABOVE	2.8474	0.52	-
33	3.2	3.5	Library Ln.	1	4	0.3	7,375	7,375	0.9906	1.4338	BELOW	2.8474	0.35	-
34	3.3	3.6	Penny Ln.	3	7	0.3	7,375	7,375	1.7336	1.4338	ABOVE	2.8474	0.61	-
35	3.4	3.7	Lambert Ln.	0	4	0.3	7,375	7,375	0.9906	1.4338	BELOW	2.8474	0.35	-
36	3.5	3.8	N. Williston Rd./Oak Hill Rd.	14	17	0.3	7,375	7,375	4.2102	1.4338	ABOVE	2.8474	1.48	HCL
37	3.6	3.9		1	15	0.3	7,375	7,375	3.7149	1.4338	ABOVE	2.8474	1.30	HCL
38	3.7	4.0		0	15	0.3	7,375	7,375	3.7149	1.4338	ABOVE	2.8474	1.30	HCL
39	3.8	4.1		0	1	0.3	7,375	7,375	0.2477	1.4338	BELOW	2.8474	0.09	-
40	3.9	4.2	Johnson Ln.	0	0	0.3	7,375	7,375	0.0000	1.4338	BELOW	2.8474	0.00	-
41	4.0	4.3		1	1	0.3	3,800	6,183	0.2954	1.4338	BELOW	2.9651	0.10	-
42	4.1	4.4		0	1	0.3	3,800	4,992	0.3659	1.4338	BELOW	3.1196	0.12	-
43	4.2	4.5		0	1	0.3	3,800	3,800	0.4807	1.4338	BELOW	3.3353	0.14	-
44	4.3	4.6		0	0	0.3	3,800	3,800	0.0000	1.4338	BELOW	3.3353	0.00	-
45	4.4	4.7	French Hill Mnr.	0	0	0.3	3,800	3,800	0.0000	1.4338	BELOW	3.3353	0.00	-
46	4.5	4.8		0	0	0.3	3,800	3,800	0.0000	1.4338	BELOW	3.3353	0.00	-
47	4.6	4.9	Sunrise Dr.	0	0	0.3	3,800	3,800	0.0000	1.4338	BELOW	3.3353	0.00	-

**Accident Rates (from 01/01/99 to 12/31/2003)
US 2 in Williston
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
48	4.7	5.0		0	0	0.3	3,800	3,800	0.0000	1.4338	BELOW	3.3353	0.00	-
49	4.8	5.1		0	0	0.3	3,800	3,800	0.0000	1.4338	BELOW	3.3353	0.00	-
50	4.9	5.2		1	1	0.3	3,800	3,800	0.4807	1.4338	BELOW	3.3353	0.14	-
51	5.0	5.3		2	3	0.3	3,800	3,800	1.4420	1.4338	ABOVE	3.3353	0.43	-
52	5.1	5.4	Gov. Chittenden Rd.	1	4	0.3	3,800	3,800	1.9226	1.4338	ABOVE	3.3353	0.58	-
53	5.2	5.5		0	3	0.3	3,800	3,800	1.4420	1.4338	ABOVE	3.3353	0.43	-
54	5.3	5.6		1	2	0.3	3,800	3,800	0.9613	1.4338	BELOW	3.3353	0.29	-
55	5.4	5.7		1	2	0.3	3,800	3,800	0.9613	1.4338	BELOW	3.3353	0.29	-
56	5.5	5.8		0	2	0.3	3,800	3,800	0.9613	1.4338	BELOW	3.3353	0.29	-
57	5.6	5.9		1	2	0.3	3,800	3,800	0.9613	1.4338	BELOW	3.3353	0.29	-
Unknow				11										
Total		5.9		148	148	5.9	8,166	8,356	1.6449	1.7787	BELOW	2.1359	0.77	-

**Accident Rates (from 01/01/99 to 12/31/2003)
VT117 in Essex
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1	Five Corners	4										
	0.1	0.2	Elm St.	0			9,050							
1	0.0	0.3	kings Ct.	0	4	0.3	9,050	9,050	0.8073	1.7787		3.2236	0.25	
2	0.1	0.4		1	1	0.3	9,050	9,050	0.2018	1.7787		3.2236	0.06	
3	0.2	0.5	Mansfield Ave.	2	3	0.3	8,350	8,700	0.6298	1.7787		3.2503	0.19	
4	0.3	0.6	Maplewood Ln.	1	4	0.3	8,350	8,583	0.8512	1.7787		3.2596	0.26	
5	0.4	0.7	US 2	0	3	0.3	7,650	8,117	0.6751	1.7787	BELOW	3.2984	0.20	-
6	0.5	0.8		0	1	0.3	7,650	7,883	0.2317	1.7787	BELOW	3.3191	0.07	-
7	0.6	0.9	Rivendell Dr./Robinson Parkway/Maple St. Ext.	0	0	0.3	7,650	7,650	0.0000	1.7787	BELOW	3.3406	0.00	-
8	0.7	1.0		3	3	0.3	8,000	7,767	0.7055	1.7787	BELOW	3.3298	0.21	-
9	0.8	1.1		0	3	0.3	8,350	8,000	0.6849	1.7787	BELOW	3.3087	0.21	-
10	0.9	1.2		0	3	0.3	8,350	8,233	0.6655	1.7787	BELOW	3.2884	0.20	-
11	1.0	1.3		0	0	0.3	8,350	8,350	0.0000	1.7787	BELOW	3.2786	0.00	-
12	1.1	1.4		0	0	0.3	8,650	8,450	0.0000	1.7787	BELOW	3.2704	0.00	-
13	1.2	1.5		0	0	0.3	8,650	8,550	0.0000	1.7787	BELOW	3.2622	0.00	-
14	1.3	1.6		2	2	0.3	8,650	8,650	0.4223	1.7787	BELOW	3.2543	0.13	-
15	1.4	1.7		0	2	0.3	8,950	8,750	0.4175	1.7787	BELOW	3.2464	0.13	-
16	1.5	1.8	Valleview Dr.	2	4	0.3	8,950	8,850	0.8255	1.7787	BELOW	3.2387	0.25	-
17	1.6	1.9		0	2	0.3	8,950	8,950	0.4082	1.7787	BELOW	3.2311	0.13	-
18	1.7	2.0	Pinewood Dr.	0	2	0.3	8,950	8,950	0.4082	1.7787	BELOW	3.2311	0.13	-
19	1.8	2.1	VT 289 EB Off Ramp D	0	0	0.3	9,350	9,083	0.0000	1.7787	BELOW	3.2211	0.00	-
20	1.9	2.2		1	1	0.3	9,750	9,350	0.1953	1.7787	BELOW	3.2018	0.06	-
21	2.0	2.3		0	1	0.3	9,750	9,617	0.1899	1.7787	BELOW	3.1833	0.06	-
22	2.1	2.4	VT 289 WB On Ramp B	0	1	0.3	9,750	9,750	0.1873	1.7787	BELOW	3.1743	0.06	-
23	2.2	2.5		0	0	0.3	7,475	8,992	0.0000	1.7787	BELOW	3.2279	0.00	-
24	2.3	2.6		0	0	0.3	7,475	8,233	0.0000	1.7787	BELOW	3.2884	0.00	-
25	2.4	2.7		0	0	0.3	5,200	6,717	0.0000	1.7787	BELOW	3.4371	0.00	-
26	2.5	2.8		2	2	0.3	5,200	5,958	0.6131	1.7787	BELOW	3.5305	0.17	-
27	2.6	2.9	Greenfield Rd.	0	2	0.3	5,200	5,200	0.7025	1.7787	BELOW	3.6424	0.19	-
28	2.7	3.0		3	5	0.3	6,450	5,617	1.6260	1.7787	BELOW	3.5783	0.45	-
29	2.8	3.1		0	3	0.3	6,450	6,033	0.9082	1.7787	BELOW	3.5206	0.26	-
30	2.9	3.2		2	5	0.3	7,700	6,867	1.3300	1.7787	BELOW	3.4203	0.39	-
31	3.0	3.3	Sand Hill Rd.	6	8	0.3	7,700	7,283	2.0062	1.7787	ABOVE	3.3764	0.59	-
32	3.1	3.4		0	8	0.3	7,700	7,700	1.8976	1.7787	ABOVE	3.3359	0.57	-
33	3.2	3.5		0	6	0.3	7,700	7,700	1.4232	1.7787	BELOW	3.3359	0.43	-
34	3.3	3.6		1	1	0.3	7,700	7,700	0.2372	1.7787	BELOW	3.3359	0.07	-
35	3.4	3.7		0	1	0.3	7,700	7,700	0.2372	1.7787	BELOW	3.3359	0.07	-
36	3.5	3.8		0	1	0.3	7,700	7,700	0.2372	1.7787	BELOW	3.3359	0.07	-
37	3.6	3.9	N. Williston Rd.	6	6	0.3	7,700	7,700	1.4232	1.7787	BELOW	3.3359	0.43	-
38	3.7	4.0		0	6	0.3	7,700	7,700	1.4232	1.7787	BELOW	3.3359	0.43	-
39	3.8	4.1		0	6	0.3	7,700	7,700	1.4232	1.7787	BELOW	3.3359	0.43	-
40	3.9	4.2		1	1	0.3	7,700	7,700	0.2372	1.7787	BELOW	3.3359	0.07	-
41	4.0	4.3		1	2	0.3	7,700	7,700	0.4744	1.7787	BELOW	3.3359	0.14	-
Unknow				1										
Total		4.3		39	39	4.3	7,976	8,006	0.6208	1.7787	BELOW	2.2049	0.28	-

**Accident Rates (from 01/01/99 to 12/31/2003)
VT15 in Essex
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1		1										
	0.1	0.2		1										
1	0.0	0.3		0	2	0.3	26,250	26,250	0.1392	1.7787		2.6516	0.05	
2	0.1	0.4		3	4	0.3	26,250	26,250	0.2783	1.7787		2.6516	0.10	
3	0.2	0.5		0	3	0.3	21,900	24,075	0.2276	1.7787		2.6885	0.08	
4	0.3	0.6	Susie Wilson Rd.	18	21	0.3	21,900	23,350	1.6427	1.7787		2.7019	0.61	
5	0.4	0.7		3	21	0.3	21,900	21,900	1.7514	1.7787	BELOW	2.7307	0.64	-
6	0.5	0.8		0	21	0.3	21,900	21,900	1.7514	1.7787	BELOW	2.7307	0.64	-
7	0.6	0.9		5	8	0.3	21,900	21,900	0.6672	1.7787	BELOW	2.7307	0.24	-
8	0.7	1.0	West St. Ext.	1	6	0.3	21,900	21,900	0.5004	1.7787	BELOW	2.7307	0.18	-
9	0.8	1.1		6	12	0.3	15,400	19,733	1.1107	1.7787	BELOW	2.7793	0.40	-
10	0.9	1.2	Warner Avenue	1	8	0.3	15,400	17,567	0.8318	1.7787	BELOW	2.8362	0.29	-
11	1.0	1.3		6	13	0.3	15,400	15,400	1.5418	1.7787	BELOW	2.9044	0.53	-
12	1.1	1.4	Willeys Ct.	5	12	0.3	16,720	15,840	1.3837	1.7787	BELOW	2.8895	0.48	-
13	1.2	1.5		14	25	0.3	16,720	16,280	2.8048	1.7787	ABOVE	2.8751	0.98	-
14	1.3	1.6		15	34	0.3	16,720	16,720	3.7141	1.7787	ABOVE	2.8613	1.30	HCL
15	1.4	1.7		4	33	0.3	13,250	15,563	3.8728	1.7787	ABOVE	2.8988	1.34	HCL
16	1.5	1.8		5	24	0.3	13,250	14,407	3.0427	1.7787	ABOVE	2.9405	1.03	HCL
17	1.6	1.9	W. Hillcrest Rd./Hillcrest Road	5	14	0.3	13,250	13,250	1.9299	1.7787	ABOVE	2.9873	0.65	-
18	1.7	2.0	Summit St.	5	15	0.3	13,750	13,417	2.0420	1.7787	ABOVE	2.9802	0.69	-
19	1.8	2.1	School St.	1	11	0.3	13,750	13,583	1.4791	1.7787	BELOW	2.9732	0.50	-
20	1.9	2.2	VT 2A and VT 117	10	16	0.3	13,100	13,533	2.1594	1.7787	ABOVE	2.9753	0.73	-
21	2.0	2.3		3	14	0.3	12,500	13,117	1.9495	1.7787	ABOVE	2.9931	0.65	-
22	2.1	2.4	Railroad	5	18	0.3	11,900	12,500	2.6301	1.7787	ABOVE	3.0209	0.87	-
23	2.2	2.5	Grove St.	4	12	0.3	12,000	12,133	1.8064	1.7787	ABOVE	3.0385	0.59	-
24	2.3	2.6	Educational Dr.	4	13	0.3	12,000	11,967	1.9842	1.7787	ABOVE	3.0467	0.65	-
25	2.4	2.7	Densmore Dr.	6	14	0.3	13,450	12,483	2.0484	1.7787	ABOVE	3.0217	0.68	-
26	2.5	2.8	Crestview Rd./Sugartree Ln.	6	16	0.3	13,450	12,967	2.2538	1.7787	ABOVE	2.9997	0.75	-
27	2.6	2.9		1	13	0.3	13,450	13,450	1.7654	1.7787	BELOW	2.9788	0.59	-
28	2.7	3.0		0	7	0.3	13,925	13,608	0.9395	1.7787	BELOW	2.9722	0.32	-
29	2.8	3.1	Taft St./Fairview Dr.	0	1	0.3	13,925	13,767	0.1327	1.7787	BELOW	2.9657	0.04	-
30	2.9	3.2	Athens Dr.	1	1	0.3	13,925	13,925	0.1312	1.7787	BELOW	2.9593	0.04	-
31	3.0	3.3		0	1	0.3	14,400	14,083	0.1297	1.7787	BELOW	2.9530	0.04	-
32	3.1	3.4		0	1	0.3	14,400	14,242	0.1282	1.7787	BELOW	2.9468	0.04	-
33	3.2	3.5		0	0	0.3	14,400	14,400	0.0000	1.7787	BELOW	2.9407	0.00	-
34	3.3	3.6		0	0	0.3	15,400	14,733	0.0000	1.7787	BELOW	2.9282	0.00	-
35	3.4	3.7	VT 289 Eastbound	3	3	0.3	15,400	15,067	0.3637	1.7787	BELOW	2.9161	0.12	-
36	3.5	3.8		3	6	0.3	15,400	15,400	0.7116	1.7787	BELOW	2.9044	0.25	-
37	3.6	3.9	VT 289 Westbound	6	12	0.3	16,400	15,733	1.3931	1.7787	BELOW	2.8930	0.48	-
38	3.7	4.0		11	20	0.3	16,400	16,067	2.2736	1.7787	ABOVE	2.8820	0.79	-
39	3.8	4.1		1	18	0.3	19,430	17,410	1.8884	1.7787	ABOVE	2.8407	0.66	-
40	3.9	4.2	Old Stage Rd.	5	17	0.3	14,100	16,643	1.8656	1.7787	ABOVE	2.8637	0.65	-
41	4.0	4.3		0	6	0.3	14,100	15,877	0.6903	1.7787	BELOW	2.8883	0.24	-
42	4.1	4.4	Essex Way	4	9	0.3	14,100	14,100	1.1658	1.7787	BELOW	2.9524	0.39	-
43	4.2	4.5		5	9	0.3	14,100	14,100	1.1658	1.7787	BELOW	2.9524	0.39	-
44	4.3	4.6	Londonderry Ln./Saybrook Rd.	1	10	0.3	14,100	14,100	1.2954	1.7787	BELOW	2.9524	0.44	-
45	4.4	4.7		2	8	0.3	15,550	14,583	1.0020	1.7787	BELOW	2.9338	0.34	-
46	4.5	4.8		3	6	0.3	15,550	15,067	0.7274	1.7787	BELOW	2.9161	0.25	-
47	4.6	4.9	Sunset Dr.	7	12	0.3	15,550	15,550	1.4095	1.7787	BELOW	2.8992	0.49	-

Accident Rates (from 01/01/99 to 12/31/2003)
VT15 in Essex
Existing Condition

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
48	4.7	5.0		5	15	0.3	17,000	16,033	1.7088	1.7787	BELOW	2.8831	0.59	-
49	4.8	5.1		0	12	0.3	17,000	16,517	1.3270	1.7787	BELOW	2.8676	0.46	-
50	4.9	5.2		2	7	0.3	17,000	17,000	0.7521	1.7787	BELOW	2.8528	0.26	-
51	5.0	5.3		4	6	0.3	17,000	17,000	0.6446	1.7787	BELOW	2.8528	0.23	-
52	5.1	5.4	VT128/Towers Rd.	2	8	0.3	17,000	17,000	0.8595	1.7787	BELOW	2.8528	0.30	-
53	5.2	5.5	Alder Ln.	2	8	0.3	13,000	15,667	0.9327	1.7787	BELOW	2.8953	0.32	-
54	5.3	5.6	Sand Hill Rd.	3	7	0.3	13,950	14,650	0.8727	1.7787	BELOW	2.9313	0.30	-
55	5.4	5.7		8	13	0.3	13,950	13,633	1.7416	1.7787	BELOW	2.9712	0.59	-
56	5.5	5.8		1	12	0.3	13,950	13,950	1.5712	1.7787	BELOW	2.9583	0.53	-
57	5.6	5.9	Richard St	0	9	0.3	13,950	13,950	1.1784	1.7787	BELOW	2.9583	0.40	-
58	5.7	6.0		0	1	0.3	13,950	13,950	0.1309	1.7787	BELOW	2.9583	0.04	-
59	5.8	6.1		0	0	0.3	13,950	13,950	0.0000	1.7787	BELOW	2.9583	0.00	-
60	5.9	6.2		0	0	0.3	13,950	13,950	0.0000	1.7787	BELOW	2.9583	0.00	-
61	6.0	6.3		0	0	0.3	13,950	13,950	0.0000	1.7787	BELOW	2.9583	0.00	-
62	6.1	6.4		1	1	0.3	13,950	13,950	0.1309	1.7787	BELOW	2.9583	0.04	-
63	6.2	6.5		0	1	0.3	12,500	13,467	0.1356	1.7787	BELOW	2.9781	0.05	-
64	6.3	6.6	Allen Martin Dr.	2	3	0.3	12,500	12,983	0.4220	1.7787	BELOW	2.9989	0.14	-
65	6.4	6.7		2	4	0.3	12,500	12,500	0.5845	1.7787	BELOW	3.0209	0.19	-
66	6.5	6.8		1	5	0.3	12,500	12,500	0.7306	1.7787	BELOW	3.0209	0.24	-
67	6.6	6.9		2	5	0.3	12,500	12,500	0.7306	1.7787	BELOW	3.0209	0.24	-
68	6.7	7.0		2	5	0.3	12,500	12,500	0.7306	1.7787	BELOW	3.0209	0.24	-
69	6.8	7.1		0	4	0.3	12,500	12,500	0.5845	1.7787	BELOW	3.0209	0.19	-
70	6.9	7.2		1	3	0.3	12,500	12,500	0.4384	1.7787	BELOW	3.0209	0.15	-
71	7.0	7.3	Saxon Hill Rd.	1	2	0.3	11,050	12,017	0.3040	1.7787	BELOW	3.0442	0.10	-
72	7.1	7.4	Naylor Rd.	1	3	0.3	11,050	11,533	0.4751	1.7787	BELOW	3.0688	0.15	-
73	7.2	7.5		5	7	0.3	11,050	11,050	1.1570	1.7787	BELOW	3.0950	0.37	-
74	7.3	7.6		0	6	0.3	11,050	11,050	0.9918	1.7787	BELOW	3.0950	0.32	-
75	7.4	7.7		0	5	0.3	11,050	11,050	0.8265	1.7787	BELOW	3.0950	0.27	-
76	7.5	7.8		0	0	0.3	11,050	11,050	0.0000	1.7787	BELOW	3.0950	0.00	-
77	7.6	7.9		0	0	0.3	11,050	11,050	0.0000	1.7787	BELOW	3.0950	0.00	-
78	7.7	8.0		2	2	0.3	11,050	11,050	0.3306	1.7787	BELOW	3.0950	0.11	-
79	7.8	8.1		2	4	0.3	11,050	11,050	0.6612	1.7787	BELOW	3.0950	0.21	-
Unknow				5										
Total		8.1		244	244	8.1	14,847	15,030	1.0982	1.7787	BELOW	2.0073	0.55	-

**Accident Rates (from 01/01/99 to 12/31/2003)
Industrial Avenue in Williston
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1	US 2	3										
	0.1	0.2	Avenue A	6										
1	0.0	0.3	Avenue B	1	10	0.3	9,900	9,900	1.8449	1.4265		2.6578	0.69	
2	0.1	0.4		0	7	0.3	9,900	9,900	1.2915	1.4265		2.6578	0.49	
3	0.2	0.5	Avenue C	0	1	0.3	9,900	9,900	0.1845	1.4265		2.6578	0.07	
4	0.3	0.6	Prushko Ln.	4	4	0.3	9,900	9,900	0.7380	1.4265		2.6578	0.28	
5	0.4	0.7	Avenue D/N. Brownell Rd.	2	6	0.3	11,900	10,567	1.0371	1.4265	BELOW	2.6212	0.40	-
6	0.5	0.8	Foxwood Cir.	8	14	0.3	11,900	11,233	2.2763	1.4265	ABOVE	2.5877	0.88	-
7	0.6	0.9	Gail Ter.	2	12	0.3	10,950	11,583	1.8922	1.4265	ABOVE	2.5713	0.74	-
8	0.7	1.0		1	11	0.3	10,000	10,950	1.8348	1.4265	ABOVE	2.6016	0.71	-
9	0.8	1.1	VT 2A/Mountain View Rd.	2	5	0.3	10,000	10,317	0.8852	1.4265	BELOW	2.6345	0.34	-
Unknow				2										
Total		1.1		31	31	1.1	10,483	10,472	1.4746	1.4265	ABOVE	2.0748	0.71	-

Accident Rates (from 01/01/99 to 12/31/2003)
Mountain View Rd in Williston
Existing Condition

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1	VT 2A/Industrial Ave.	2										
	0.1	0.2		0			6,500							
1	0.0	0.3	Trinity Dr.	0	2	0.3	6,500	6,500	0.5620	1.4265	BELOW	2.9195	0.19	-
2	0.1	0.4		0	0	0.3	6,500	6,500	0.0000	1.4265	BELOW	2.9195	0.00	-
3	0.2	0.5		2	2	0.3	6,450	6,475	0.5642	1.4265	BELOW	2.9221	0.19	-
4	0.3	0.6		1	3	0.3	6,450	6,467	0.8473	1.4265	BELOW	2.9229	0.29	-
5	0.4	0.7	Kate Ln.	1	4	0.3	6,450	6,450	1.1327	1.4265	BELOW	2.9247	0.39	-
6	0.5	0.8		0	2	0.3	6,450	6,450	0.5664	1.4265	BELOW	2.9247	0.19	-
7	0.6	0.9		0	1	0.3	6,400	6,433	0.2839	1.4265	BELOW	2.9264	0.10	-
8	0.7	1.0	Brennan woods Dr.	0	0	0.3	6,400	6,417	0.0000	1.4265	BELOW	2.9282	0.00	-
9	0.8	1.1		0	0	0.3	6,400	6,400	0.0000	1.4265	BELOW	2.9300	0.00	-
10	0.9	1.2	Redmond Rd.	1	1	0.3	6,400	6,400	0.2854	1.4265	BELOW	2.9300	0.10	-
Unknow				2										
Total		1.2		9	9	1.2	6,440	6,449	0.6372	1.4265	BELOW	2.2110	0.29	-

**Accident Rates (from 01/01/99 to 12/31/2003)
N. Williston Rd. in Williston
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1	US 2	1										
	0.1	0.2	Lefevre Ln.	1										
1	0.0	0.3		0	2	0.3	4,200	4,200	0.8698	1.4265		3.2411	0.27	
2	0.1	0.4	Vt 117	0	1	0.3	4,200	4,200	0.4349	1.4265		3.2411	0.13	
3	0.2	0.5	Golf Course Rd.	0	0	0.3	4,200	4,200	0.0000	1.4265		3.2411	0.00	
4	0.3	0.6	Fairway Dr.	1	1	0.3	4,200	4,200	0.4349	1.4265		3.2411	0.13	
5	0.4	0.7		1	2	0.3	4,200	4,200	0.8698	1.4265	BELOW	3.2411	0.27	-
6	0.5	0.8	Tamarack Dr.	0	2	0.3	4,200	4,200	0.8698	1.4265	BELOW	3.2411	0.27	-
7	0.6	0.9	Spruce Ln.	0	1	0.3	4,300	4,233	0.4315	1.4265	BELOW	3.2348	0.13	-
8	0.7	1.0	Mountain View Rd.	0	0	0.3	4,400	4,300	0.0000	1.4265	BELOW	3.2224	0.00	-
9	0.8	1.1		6	6	0.3	4,400	4,367	2.5097	1.4265	ABOVE	3.2103	0.78	-
10	0.9	1.2		0	6	0.3	4,400	4,400	2.4907	1.4265	ABOVE	3.2043	0.78	-
11	1.0	1.3		0	6	0.3	4,400	4,400	2.4907	1.4265	ABOVE	3.2043	0.78	-
12	1.1	1.4		0	0	0.3	4,400	4,400	0.0000	1.4265	BELOW	3.2043	0.00	-
13	1.2	1.5	Peterson Ln.	2	2	0.3	4,250	4,350	0.8398	1.4265	BELOW	3.2133	0.26	-
14	1.3	1.6		2	4	0.3	4,250	4,300	1.6991	1.4265	ABOVE	3.2224	0.53	-
15	1.4	1.7		0	4	0.3	4,250	4,250	1.7190	1.4265	ABOVE	3.2317	0.53	-
16	1.5	1.8	Williston Wodds Rd.	0	2	0.3	4,250	4,250	0.8595	1.4265	BELOW	3.2317	0.27	-
17	1.6	1.9		4	4	0.3	4,250	4,250	1.7190	1.4265	ABOVE	3.2317	0.53	-
18	1.7	2.0		0	4	0.3	4,100	4,200	1.7395	1.4265	ABOVE	3.2411	0.54	-
19	1.8	2.1	Fontaine Ln.	0	4	0.3	4,100	4,150	1.7605	1.4265	ABOVE	3.2507	0.54	-
20	1.9	2.2		1	1	0.3	4,100	4,100	0.4455	1.4265	BELOW	3.2605	0.14	-
21	2.0	2.3		1	2	0.3	4,100	4,100	0.8910	1.4265	BELOW	3.2605	0.27	-
22	2.1	2.4	Fay Ln.	0	2	0.3	4,100	4,100	0.8910	1.4265	BELOW	3.2605	0.27	-
Unknow				4										
Total		2.4		24	24	2.4	4,239	4,243	1.2914	1.4265	BELOW	2.1144	0.61	-

**Accident Rates (from 01/01/99 to 12/31/2003)
Susie Williston Rd in Essex
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1		0										
	0.1	0.2		0										
1	0.0	0.3		0	0	0.3	19,300	19,300	0.0000	1.4265		2.3271	0.00	
2	0.1	0.4		0	0	0.3	19,300	19,300	0.0000	1.4265		2.3271	0.00	
3	0.2	0.5		0	0	0.3	19,300	19,300	0.0000	1.4265		2.3271	0.00	
4	0.3	0.6		0	0	0.3	19,300	19,300	0.0000	1.4265		2.3271	0.00	
5	0.4	0.7		0	0	0.3	19,300	19,300	0.0000	1.4265	BELOW	2.3271	0.00	-
6	0.5	0.8		0	0	0.3	19,300	19,300	0.0000	1.4265	BELOW	2.3271	0.00	-
7	0.6	0.9		0	0	0.3	19,300	19,300	0.0000	1.4265	BELOW	2.3271	0.00	-
8	0.7	1.0		0	0	0.3	19,300	19,300	0.0000	1.4265	BELOW	2.3271	0.00	-
9	0.8	1.1		0	0	0.3	19,300	19,300	0.0000	1.4265	BELOW	2.3271	0.00	-
10	0.9	1.2		0	0	0.3	19,300	19,300	0.0000	1.4265	BELOW	2.3271	0.00	-
11	1.0	1.3		3	3	0.3	19,300	19,300	0.2839	1.4265	BELOW	2.3271	0.12	-
12	1.1	1.4		0	3	0.3	19,300	19,300	0.2839	1.4265	BELOW	2.3271	0.12	-
13	1.2	1.5		0	3	0.3	19,300	19,300	0.2839	1.4265	BELOW	2.3271	0.12	-
14	1.3	1.6		0	0	0.3	19,300	19,300	0.0000	1.4265	BELOW	2.3271	0.00	-
Unknow														
Total		1.6		3	3	1.6	19,300	19,300	0.0532	1.4265	BELOW	1.8281	0.03	-

Accident Rates (from 01/01/99 to 12/31/2003)
VT 289 in Essex
Existing Condition

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	7.7		0										
	7.7	7.8		0										
1	0.0	7.9		1	1	0.3	15,400	15,400	0.1186	0.3453	BELOW	0.8081	0.15	-
2	7.7	8.0		0	1	0.3	15,400	15,400	0.1186	0.3453	BELOW	0.8081	0.15	-
3	7.8	8.1		2	3	0.3	15,400	15,400	0.3558	0.3453	ABOVE	0.8081	0.44	-
4	7.9	8.2		1	3	0.3	15,400	15,400	0.3558	0.3453	ABOVE	0.8081	0.44	-
5	8.0	8.3		0	3	0.3	15,400	15,400	0.3558	0.3453	ABOVE	0.8081	0.44	-
6	8.1	8.4		0	1	0.3	15,400	15,400	0.1186	0.3453	BELOW	0.8081	0.15	-
7	8.2	8.5		1	1	0.3	15,400	15,400	0.1186	0.3453	BELOW	0.8081	0.15	-
8	8.3	8.6		0	1	0.3	15,400	15,400	0.1186	0.3453	BELOW	0.8081	0.15	-
9	8.4	8.7		0	1	0.3	15,400	15,400	0.1186	0.3453	BELOW	0.8081	0.15	-
10	8.5	8.8		0	0	0.3	15,400	15,400	0.0000	0.3453	BELOW	0.8081	0.00	-
11	8.6	8.9		0	0	0.3	15,400	15,400	0.0000	0.3453	BELOW	0.8081	0.00	-
12	8.7	9.0		1	1	0.3	15,400	15,400	0.1186	0.3453	BELOW	0.8081	0.15	-
13	8.8	9.1		2	3	0.3	15,400	15,400	0.3558	0.3453	ABOVE	0.8081	0.44	-
14	8.9	9.2		0	3	0.3	15,400	15,400	0.3558	0.3453	ABOVE	0.8081	0.44	-
15	9.0	9.3		0	2	0.3	15,400	15,400	0.2372	0.3453	BELOW	0.8081	0.29	-
16	9.1	9.4	VT 289 EB Off Ramp & WB On Ramp	0	0	0.3	6,600	12,467	0.0000	0.3453	BELOW	0.8523	0.00	-
17	9.2	9.5		0	0	0.3	6,600	9,533	0.0000	0.3453	BELOW	0.9131	0.00	-
18	9.3	9.6		0	0	0.3	6,600	6,600	0.0000	0.3453	BELOW	1.0045	0.00	-
19	9.4	9.7		1	1	0.3	6,600	6,600	0.2767	0.3453	BELOW	1.0045	0.28	-
20	9.5	9.8	VT 289 EB On Ramp & WB Off Ramp	0	1	0.3	6,600	6,600	0.2767	0.3453	BELOW	1.0045	0.28	-
21	9.6	9.9		0	1	0.3	6,600	6,600	0.2767	0.3453	BELOW	1.0045	0.28	-
22	9.7	10.0	VT 289 EB Off Ramp & WB On Ramp	0	0	0.3	6,600	6,600	0.0000	0.3453	BELOW	1.0045	0.00	-
23	9.8	10.1		0	0	0.3	6,600	6,600	0.0000	0.3453	BELOW	1.0045	0.00	-
24	9.9	10.2		0	0	0.3	6,600	6,600	0.0000	0.3453	BELOW	1.0045	0.00	-
25	10.0	10.3	VT 289 EB On Ramp & WB Off Ramp	0	0	0.3	6,000	6,400	0.0000	0.3453	BELOW	1.0125	0.00	-
26	10.1	10.4		0	0	0.3	6,000	6,200	0.0000	0.3453	BELOW	1.0209	0.00	-
27	10.2	10.5		0	0	0.3	6,000	6,000	0.0000	0.3453	BELOW	1.0296	0.00	-
28	10.3	10.6		0	0	0.3	5,400	5,800	0.0000	0.3453	BELOW	1.0386	0.00	-
29	10.4	10.7		0	0	0.3	5,400	5,600	0.0000	0.3453	BELOW	1.0480	0.00	-
30	10.5	10.8		0	0	0.3	5,400	5,400	0.0000	0.3453	BELOW	1.0579	0.00	-
31	10.6	10.9		0	0	0.3	5,400	5,400	0.0000	0.3453	BELOW	1.0579	0.00	-
32	10.7	11.0		0	0	0.3	5,400	5,400	0.0000	0.3453	BELOW	1.0579	0.00	-
33	10.8	11.1		1	1	0.3	5,400	5,400	0.3382	0.3453	BELOW	1.0579	0.32	-
34	10.9	11.2		0	1	0.3	5,400	5,400	0.3382	0.3453	BELOW	1.0579	0.32	-
35	11.0	11.3		1	2	0.3	5,400	5,400	0.6765	0.3453	ABOVE	1.0579	0.64	-
Unknow				9										
Total		11.3		20	20	11.3	10,046	10,331	0.0939	0.3453	BELOW	0.4468	0.21	-

Accident Rates (from 01/01/99 to 12/31/2003)
I-89 in Williston
Existing Condition

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	79.0		0										
	79.0	79.1		0										
	78.9	79.2		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
	79.0	79.3		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
	79.1	79.4		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
	79.2	79.5		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
	79.3	79.6		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
	79.4	79.7		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
1	79.5	79.8		2	2	0.3	27,100	27,100	0.1348	0.1071	ABOVE	0.2926	0.46	-
2	79.6	79.9		1	3	0.3	27,100	27,100	0.2022	0.1071	ABOVE	0.2926	0.69	-
3	79.7	80.0		0	3	0.3	27,100	27,100	0.2022	0.1071	ABOVE	0.2926	0.69	-
4	79.8	80.1		6	7	0.3	27,100	27,100	0.4718	0.1071	ABOVE	0.2926	1.61	HCL
5	79.9	80.2		0	6	0.3	27,100	27,100	0.4044	0.1071	ABOVE	0.2926	1.38	HCL
6	80.0	80.3		1	7	0.3	27,100	27,100	0.4718	0.1071	ABOVE	0.2926	1.61	HCL
7	80.1	80.4		1	2	0.3	27,100	27,100	0.1348	0.1071	ABOVE	0.2926	0.46	-
8	80.2	80.5		0	2	0.3	27,100	27,100	0.1348	0.1071	ABOVE	0.2926	0.46	-
9	80.3	80.6		0	1	0.3	27,100	27,100	0.0674	0.1071	BELOW	0.2926	0.23	-
10	80.4	80.7		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
11	80.5	80.8		1	1	0.3	27,100	27,100	0.0674	0.1071	BELOW	0.2926	0.23	-
12	80.6	80.9		0	1	0.3	27,100	27,100	0.0674	0.1071	BELOW	0.2926	0.23	-
13	80.7	81.0		0	1	0.3	27,100	27,100	0.0674	0.1071	BELOW	0.2926	0.23	-
14	80.8	81.1		3	3	0.3	27,100	27,100	0.2022	0.1071	ABOVE	0.2926	0.69	-
15	80.9	81.2		0	3	0.3	27,100	27,100	0.2022	0.1071	ABOVE	0.2926	0.69	-
16	81.0	81.3		2	5	0.3	27,100	27,100	0.3370	0.1071	ABOVE	0.2926	1.15	HCL
17	81.1	81.4		0	2	0.3	27,100	27,100	0.1348	0.1071	ABOVE	0.2926	0.46	-
18	81.2	81.5		0	2	0.3	27,100	27,100	0.1348	0.1071	ABOVE	0.2926	0.46	-
19	81.3	81.6		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
20	81.4	81.7		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
21	81.5	81.8		2	2	0.3	27,100	27,100	0.1348	0.1071	ABOVE	0.2926	0.46	-
22	81.6	81.9		2	4	0.3	27,100	27,100	0.2696	0.1071	ABOVE	0.2926	0.92	-
23	81.7	82.0		0	4	0.3	27,100	27,100	0.2696	0.1071	ABOVE	0.2926	0.92	-
24	81.8	82.1		4	6	0.3	27,100	27,100	0.4044	0.1071	ABOVE	0.2926	1.38	HCL
25	81.9	82.2		0	4	0.3	27,100	27,100	0.2696	0.1071	ABOVE	0.2926	0.92	-
26	82.0	82.3		2	6	0.3	27,100	27,100	0.4044	0.1071	ABOVE	0.2926	1.38	HCL
27	82.1	82.4		0	2	0.3	27,100	27,100	0.1348	0.1071	ABOVE	0.2926	0.46	-
28	82.2	82.5		0	2	0.3	27,100	27,100	0.1348	0.1071	ABOVE	0.2926	0.46	-
29	82.3	82.6		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
30	82.4	82.7		1	1	0.3	27,100	27,100	0.0674	0.1071	BELOW	0.2926	0.23	-
31	82.5	82.8		0	1	0.3	27,100	27,100	0.0674	0.1071	BELOW	0.2926	0.23	-
32	82.6	82.9		0	1	0.3	27,100	27,100	0.0674	0.1071	BELOW	0.2926	0.23	-
33	82.7	83.0		0	0	0.3	27,100	27,100	0.0000	0.1071	BELOW	0.2926	0.00	-
34	82.8	83.1		2	2	0.3	27,100	27,100	0.1348	0.1071	ABOVE	0.2926	0.46	-
35	82.9	83.2		0	2	0.3	27,100	27,100	0.1348	0.1071	ABOVE	0.2926	0.46	-
36	83.0	83.3		1	3	0.3	27,100	27,100	0.2022	0.1071	ABOVE	0.2926	0.69	-
37	83.1	83.4		0	1	0.3	27,100	27,100	0.0674	0.1071	BELOW	0.2926	0.23	-
38	83.2	83.5		2	3	0.3	27,100	27,100	0.2022	0.1071	ABOVE	0.2926	0.69	-
39	83.3	83.6		5	7	0.3	27,100	27,100	0.4718	0.1071	ABOVE	0.2926	1.61	HCL
40	83.4	83.7		1	8	0.3	27,100	27,100	0.5392	0.1071	ABOVE	0.2926	1.84	HCL
41	83.5	83.8	I 89 NB Off Ramp/I 89 EB On Ramp	0	6	0.3	31,600	28,600	0.3832	0.1071	ABOVE	0.2885	1.33	HCL

Accident Rates (from 01/01/99 to 12/31/2003)
I-89 in Williston
Existing Condition

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
42	83.6	83.9		0	1	0.3	31,600	30,100	0.0607	0.1071	BELOW	0.2847	0.21	-
43	83.7	84.0		1	1	0.3	31,600	31,600	0.0578	0.1071	BELOW	0.2812	0.21	-
44	83.8	84.1		1	2	0.3	31,600	31,600	0.1156	0.1071	ABOVE	0.2812	0.41	-
45	83.9	84.2	I 89 SB Off Ramp/I 89 WB On Ramp	0	2	0.3	31,600	31,600	0.1156	0.1071	ABOVE	0.2812	0.41	-
46	84.0	84.3		0	1	0.3	36,100	33,100	0.0552	0.1071	BELOW	0.2778	0.20	-
47	84.1	84.4		0	0	0.3	36,100	34,600	0.0000	0.1071	BELOW	0.2747	0.00	-
48	84.2	84.5		0	0	0.3	36,100	36,100	0.0000	0.1071	BELOW	0.2717	0.00	-
49	84.3	84.6		0	0	0.3	36,100	36,100	0.0000	0.1071	BELOW	0.2717	0.00	-
50	84.4	84.7		1	1	0.3	36,100	36,100	0.0506	0.1071	BELOW	0.2717	0.19	-
51	84.5	84.8		0	1	0.3	36,100	36,100	0.0506	0.1071	BELOW	0.2717	0.19	-
52	84.6	84.9		0	1	0.3	36,100	36,100	0.0506	0.1071	BELOW	0.2717	0.19	-
53	84.7	85.0		1	1	0.3	36,100	36,100	0.0506	0.1071	BELOW	0.2717	0.19	-
54	84.8	85.1		1	2	0.3	36,100	36,100	0.1012	0.1071	BELOW	0.2717	0.37	-
Unknow				#REF!										
Total		6.1		#REF!	#REF!	6.1	28,825	28,675	#REF!	0.1071	#REF!	0.1528	#REF!	#REF!

**Accident Rates (from 01/01/99 to 12/31/2003)
Marshall Avenue in Williston
Existing Condition**

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1		0										
	0.1	0.2		0										
1	0.2	0.3		0	0	0.3	13,600	13,600	0.0000	1.7787		2.9725	0.00	
2	0.3	0.4		1	1	0.3	13,600	13,600	0.1343	1.7787		2.9725	0.05	
3	0.4	0.5		1	2	0.3	13,600	13,600	0.2686	1.7787		2.9725	0.09	
4	0.5	0.6		2	4	0.3	13,600	13,600	0.5372	1.7787		2.9725	0.18	
5	0.6	0.7		1	4	0.3	13,600	13,600	0.5372	1.7787	BELOW	2.9725	0.18	-
6	0.7	0.8		5	8	0.3	13,600	13,600	1.0744	1.7787	BELOW	2.9725	0.36	-
7	0.8	0.9		1	7	0.3	13,600	13,600	0.9401	1.7787	BELOW	2.9725	0.32	-
8	0.9	1.0		0	6	0.3	13,600	13,600	0.8058	1.7787	BELOW	2.9725	0.27	-
9	1.0	1.1		0	1	0.3	13,600	13,600	0.1343	1.7787	BELOW	2.9725	0.05	-
10	1.1	1.2		2	2	0.3	13,600	13,600	0.2686	1.7787	BELOW	2.9725	0.09	-
11	1.2	1.3	VT 2A/ Maple Tree Place	0	2	0.3	13,600	13,600	0.2686	1.7787	BELOW	2.9725	0.09	-
12	1.3	1.4		5	7	0.3	13,600	13,600	0.9401	1.7787	BELOW	2.9725	0.32	-
13	1.4	1.5		4	9	0.3	13,600	13,600	1.2087	1.7787	BELOW	2.9725	0.41	-
14	1.5	1.6		3	12	0.3	13,600	13,600	1.6116	1.7787	BELOW	2.9725	0.54	-
Unknow				6										
Total		1.6		31	31	1.6	13,600	13,600	0.7806	1.7787	BELOW	2.3121	0.34	-

Accident Rates (from 01/01/99 to 12/31/2003)
West St in Essex
Existing Condition

Segment	Mile Post Start	Mile Post End	Intersection	Accidents by 0.1 mile	Accidents Sliding by 0.3 mile	Section Length	0.1 mile AADT	AADT	Actual Crash Rate (MVM)	1999 - 2003 Statewide Rate (MVM)	Relation to Statewide Rate	Critical Crash Rate	Actual/Critical Ratio	High Crash Location ?
	0.0	0.1		1										
	0.1	0.2		1			3,000							
1	0.2	0.3		0	2	0.3	3,000	3,000	1.2177	1.7787	BELOW	4.1591	0.29	-
2	0.3	0.4		0	1	0.3	3,000	3,000	0.6088	1.7787	BELOW	4.1591	0.15	-
3	0.4	0.5		2	2	0.3	3,000	2,900	1.2596	1.7787	BELOW	4.1945	0.30	-
4	0.5	0.6		0	2	0.3	3,000	2,900	1.2596	1.7787	BELOW	4.1945	0.30	-
5	0.6	0.7		0	2	0.3	3,000	2,900	1.2596	1.7787	BELOW	4.1945	0.30	-
6	0.7	0.8		0	0	0.3	2,800	2,933	0.0000	1.7787	BELOW	4.1825	0.00	-
7	0.8	0.9		0	0	0.3	3,950	3,950	0.0000	1.7787	BELOW	3.8873	0.00	-
8	0.9	1.0		0	0	0.3	5,100	5,100	0.0000	1.7787	BELOW	3.6588	0.00	-
9	1.0	1.1		0	0	0.3	5,400	5,400	0.0000	1.7787	BELOW	3.6107	0.00	-
Unknow														
Total		1.1		4	4	1.1	3,583	3,565	0.5589	1.7787	BELOW	2.9951	0.19	-

Future Annual Crash Projection for Major Corridors

No.	Corridors	Town	Condition		Group 1			Group 2				Group 3		
			Existing	2030 No Build	Alt 2	Alt 3	Alt 22	Alt 16A	Alt 16B	Alt 16C	Alt 17	Alt 18	Alt 19	Alt 23
Number of Crashes														
1	VT 2A	Williston	40	47	38	36	33	38	37	38	39	37	35	32
	VT 2A	Essex	14	17	16	15	14	16	16	16	16	16	15	14
2	US2	Williston	30	36	35	35	36	35	34	34	34	34	34	34
3	VT 117	Essex	8	9	9	9	9	8	8	8	8	8	8	9
4	VT 15	Essex	49	52	54	53	52	52	52	52	52	54	53	52
5	Industrial Avenue	Williston	6	7	8	8	7	7	7	7	7	8	7	7
6	Mountain View Road	Williston	2	2	2	2	2	2	2	2	2	2	2	2
7	N. Williston Road	Williston	5	5	5	5	5	5	4	4	5	5	5	5
	N. Williston Road	Essex	0	0	0	0	0	0	0	0	0	0	0	0
8	Susie Wilson Road	Essex	1	1	1	1	1	1	0	0	0	1	1	1
9	VT 289	Essex	4	6	6	6	6	6	7	7	7	6	6	6
10	I-89	Williston	14	17	17	17	17	18	20	20	20	18	18	18
11	Marshall Avenue	Williston	6	8	8	8	8	8	8	8	8	8	8	8
12	South Street/West Street	Essex	1	1	1	1	1	1	1	1	1	1	1	1
Total			180	208	200	196	191	197	196	197	199	198	193	189

VT 2A	54	64	54	51	47	54	53	54	55	53	50	46
Other Roadways	126	144	146	145	144	143	143	143	144	145	143	143

Future Annual Crash Projection for Major Corridors Net Change (Alternative - No Build)

No.	Corridors	Town	Condition		Group 1			Group 2				Group 3		
			Existing	2030 No Build	Alt 2	Alt 3	Alt 22	Alt 16A	Alt 16B	Alt 16C	Alt 17	Alt 18	Alt 19	Alt 23
Number of Crashes														
1	VT 2A	Williston	40	47	-9	-11	-14	-9	-10	-9	-8	-10	-12	-15
	VT 2A	Essex	14	17	-1	-2	-3	-1	-1	-1	-1	-1	-2	-3
2	US2	Williston	30	36	-1	-1	0	-1	-2	-2	-2	-2	-2	-2
3	VT 117	Essex	8	9	0	0	0	-1	-1	-1	-1	-1	-1	0
4	VT 15	Essex	49	52	2	1	0	0	0	0	0	2	1	0
5	Industrial Avenue	Williston	6	7	1	1	0	0	0	0	0	1	0	0
6	Mountain View Road	Williston	2	2	0	0	0	0	0	0	0	0	0	0
7	N. Williston Road	Williston	5	5	0	0	0	0	-1	-1	0	0	0	0
	N. Williston Road	Essex	0	0	0	0	0	0	0	0	0	0	0	0
8	Susie Wilson Road	Essex	1	1	0	0	0	0	-1	-1	-1	0	0	0
9	VT 289	Essex	4	6	0	0	0	0	1	1	1	0	0	0
10	I-89	Williston	14	17	0	0	0	1	3	3	3	1	1	1
11	Marshall Avenue	Williston	6	8	0	0	0	0	0	0	0	0	0	0
12	South Street/West Street	Essex	1	1	0	0	0	0	0	0	0	0	0	0
13														
Total			180	208	-8	-12	-17	-11	-12	-11	-9	-10	-15	-19

VT 2A	54	64	-10	-13	-17	-10	-11	-10	-9	-11	-14	-18
Other Roadways	126	144	2	1	0	-1	-1	-1	0	1	-1	-1