

## CHAPTER 5 – REFERENCES

### References

- Agway, Inc. February 2001. *Site Investigation Report, Agway, Inc., Route 2A, Williston, Vermont*. Harding ESE, Inc.
- Beers, F.W., A.D. Ellis and G. G. Soule. 1869. *Atlas of Chittenden County, Vermont*. New York.
- CN Real Estate Management. March 1999. *Phase II Environmental Site Assessment Report, PIN 4770874, Mile Post 108.0 on the Roxbury Subdivision, Park Street, Essex Junction, Vermont*. Golder Associates Inc.
- Chittenden Solid Waste District. October 2005. *CSWD Phase I, II & III Groundwater Sampling Results which Exceed Vermont Groundwater Enforcement Standards*.
- Collins, S.B., Inc. July 1996. *Report on the Investigation of Subsurface Petroleum Contamination at Taft Corners Short Stop, Route 2, Williston, Vermont, Site # 961972*. Griffin International.
- EDR DataMap™. January 13, 2006. *Corridor Study, Route 2A, Essex Junction, VT*.
- EDR DataMap™. January 16, 2006. *Corridor Study, Circ A/ Essex Junction, VT*.
- Handy, Joseph. August 1997. *Report on the Site Investigation of Suspected Subsurface Petroleum Contamination at Former Essex Junction Agway, Five Corners, Essex Junction, Vermont*. Griffin International, Inc.
- Road Res-Q. October 2, 1996. *Initial Site Investigation Report, Road Res-Q, 1 Main Street, Essex Junction, Vermont*. Groundwater of Vermont.
- Robinson, Jim. November 4, 1998. *A Phase II Hydrogeologic Investigation of Robinson's, Inc., 33-35 Park Street, Essex Junction, Vermont, Site # 982473*. Kent S. Koptiuch, Inc.
- Sanborn Fire Insurance Maps. 1899, 1904, 1910, 1922, 1928, 1944, and 1962. Essex Junction, Vermont.
- Sandri, A.R., Inc. August 18, 1999. *Report on the Site Investigation of Suspected Subsurface Petroleum Contamination at Bushey's Sunoco, Essex Junction, Vermont, Site # 982430*. Griffin International.
- Town of Williston, Vermont. October 7, 1993. *Williston Landfill Petroleum Contamination Site, Final Report, Site # 921297*. Lamoureux & Stone Consulting Engineers, Inc.
- Town of Williston, Vermont. September 30, 1993. *Williston Town Garage, James Brown Drive, Williston, Vermont, Subsurface Site Investigation*. Wagner, Heindel, and Noyes, Inc.
- United States Department of Agriculture, Natural Resources Conservation Service (SDA NRCS). 1937. *Chittenden County Black and White Aerial Photography*.
- USDA NRCS. 1941. *Chittenden County Black and White Aerial Photography*.

- USDA NRCS. 1942. *Chittenden County Black and White Aerial Photography.*
- USDA NRCS. 1962. *Chittenden County Black and White Aerial Photography.*
- USDA NRCS. 1974. *Chittenden County Black and White Aerial Photography.*
- USDA NRCS. 1980. *Chittenden County Black and White Aerial Photography.*
- USDA NRCS. 1992. *Chittenden County Black and White Aerial Photography.*
- USDA NRCS. 1977. *Chittenden County Color Infra-red Aerial Photography.*
- USDA NRCS. 1986. *Chittenden County Color Infra-red Aerial Photography.*
- USDA NRCS. 1992. *Chittenden County Color Infra-red Aerial Photography.*
- USDA NRCS. 2004. *Chittenden County Color Aerial Photography.*
- United States Department of Transportation, Federal Highway Administration. August, 1988. *Interim Guidance – Hazardous Waste Sites Affecting Highway Project Development.*
- United States Environmental Protection Agency (EPA). October 14, 2005. *National Priority List, Proposed National Priority List, Delisted National Priority List.*
- EPA. September 19, 2005. *Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS).*
- EPA. August 22, 2005. *CERCLIS No Further Remedial Action Planned.*
- EPA. October 13, 2005. *Corrective Action Report.*
- EPA. October 14, 2005. *Resource Conservation and Recovery Act Information (RCRA).*
- United States Geological Survey (USGS). 1906. *15 Minute Topographic Quadrangle, Burlington, Vermont.*
- USGS. 1906 Revised 1943. *15 Minute Topographic Quadrangle, Burlington, Vermont.*
- USGS. 1948. *15 Minute Topographic Quadrangle, Burlington, Vermont.*
- USGS. 1948 Revised 1972. *7.5 Minute Topographic Quadrangle, Essex Junction, Vermont.*
- USGS. 1987. *7.5 Minute Topographic Quadrangle, Essex Junction, Vermont.*
- Vermont Agency of Natural Resources Department of Environmental Conservation (VANR DEC). April 12, 2005. *Vermont Solid Waste Management Facilities Listed by County.*
- Vermont Agency of Natural Resources Department of Environmental Conservation (VANR DEC). October 1, 2004. *Hazardous Waste Management Regulations.*
- VANR DEC. August 17, 1993. *Petroleum Contamination at Dave's Automotive in Williston, Site # 93-1428.*

- VANR DEC. December 2005. *Vermont Permitted Underground Storage Tank List.*
- VANR DEC. February 20, 1992. *Completion of Investigation, Green Mountain Power, Williston, Site # 900565.*
- VANR DEC. January 2006. *Vermont Active Hazardous Sites List.*
- VANR DEC. January 24, 2000. *Petroleum Contamination at Winston Prouty Federal Building, Site # 992728.*
- VANR DEC. January 30, 2006. *All Vermont Generators, RCRA Rep Handler List.*
- VANR DEC. July 27, 2005. *Site Investigation Expressway Notification Form, Church of the Nazarene.*
- VANR DEC. June 7, 1994. *Groundwater Sampling Results / Site Management Activity Complete at the Essex Public Works in Essex Junction, Site # 900573.*
- VANR DEC. May 1, 1996. *Petroleum Contamination at Taft Corners Short Stop in Williston, Site # 961972.*
- VANR DEC. May 5, 1999. *Site Management Activities Completed at P.J.s Auto Village, Site # 982447.*
- VANR DEC. May 9, 2002. *Judge Development.*
- VANR DEC. May 31, 1996. *Petroleum Contamination at Road Res-Q, Essex Junction, VT, Site # 961993.*
- VANR DEC. March 31, 2000. *Petroleum Contamination at Winston Prouty Federal Building, Site # 992728.*
- VANR DEC. October 6, 2005. *Vermont Spills Sites Database.*
- VANR DEC. October 7, 2005. *Vermont Drycleaner Facilities List.*
- VANR DEC. October 12, 1993. *Closure of the Williston Landfill, Site # 921297.*
- VANR DEC. October 30, 1998. *Petroleum Contamination at Bushey's Sunoco, Essex Junction, Vermont, Site # 982430.*
- VANR DEC. October 31, 1989. *Contamination at Vermont Maple Products, Essex Junction, Vermont, Site # 890334.*
- VANR DEC. September 12, 2000. *Petroleum Contamination at Agway, Inc., Williston, Vermont, Site # 20002805.*
- VANR DEC. September 18, 1995. *Petroleum Contamination at Howard Bank, # 95-1821.*
- VANR DEC. September 29, 1992. *Petroleum Contamination at the Williston Landfill on Redmond Road, Site # 921297.*
- Vermont Agency of Transportation. August 2001. *Environmental Operations Manual.*

Walling, H.F. 1857. *Map of Chittenden County, Vermont*. Baker, Tilden & Company, Boston.

Walling, H.F. 1857. *Map of Chittenden County, Vermont*. Baker, Tilden & Co., Boston.

**Interviews**

Barbagallo, Anthony, Facilities Manager, Chittenden Solid Waste District. March 15, 2006.

Desmond, Ashley, DEC Waste Management Division. April 3, 2006.

DiDomenico, David, DEC Solid Waste Division. April 5, 2006.

Holliday, Jennifer, Environmental and Safety Compliance Manager, Chittenden Solid Waste District. May 12, 2006.

Provencher, Linda, DEC Waste Management Division. April 5, 2006.

Smith, Michael, DEC Waste Management Division. March 16, 2006.